

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBE7595D210128

Final Bill

Customer		
Name:	Lonpac Insurance Berhad	Date: 18-02-21
Address	Motor Claims Department	Vehicle No: GBE7595D
	300 Beach Road #17-04 / 07	Model/Make: Toyota Hiace
	The Concourse Singapore 199555	Van Turbo 5 DR Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bumper	\$ 599.50	\$ -
2	Bumper Clips 1 set	\$ 65.00	\$ -
3	Rear Rh Bumper Bracket	\$ 202.00	\$ -
4	Tail Lamp	\$ 365.10	\$ 362.10
5	Tail Lamp Panel	\$ 258.00	\$ -
	Total		\$ 362.10
	Part Less 25%		\$ 90.53
	Total Part After Less 25%		\$ 271.57
6	Rear "Corporate" Advertisement & Artwork	\$ 450.00	\$ 400.00
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 600.00	\$ 500.00
	To putty & spray painting & including touch up paint on accident affected area	\$ 600.00	\$ 400.00
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 60.00	\$ -

Total Parts & Labour of estimate for damaged vehicle

\$ 3,199.60

Total amount in Lump Sum Basis for repaired vehicle

\$ 1,571.57

SDLS: One Thousand Five Hundred Seventy-One And Cents
Fifty-Seven Only



M/s Liu's Brother Auto Engrg Wks