

SYNERGY MOTOR PTE LTD [HQ]

53 UBI AVENUE 1, #01-45 .PAYA UBI INDUSTRIAL ESTATE S'PORE 408934

VEHICLE No: SJJ 1996Z

1PC	REAR BUMPER	<i>(USA)</i>	<i>n</i>	\$585.10	X
1SET	REAR BUMPER CLIPS		<i>n</i>	\$50.00	X
1SET	REAR BUMPER REVERSE SENSOR		<i>shobh</i>	\$280.00	<i>200 s.w</i>
				\$915.10	

TO CHECK WIRING	\$50.00	<i>2x</i>
TO DISMANTLE & REPLACED REVERSE SENSOR	\$60.00	<i>2x</i>
TO DISMANTLE & REFIX CHSHION UPHOLSTERY	\$80.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$350.00	<i>100</i>
TO PUTTY & SPRAY PAINTING	\$400.00	<i>200</i>
TOTAL	\$1,855.10	

not authorized
12/2/21
MP \$500
1 day
note: MS/20 Tony

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: