



2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : SLH2578C

Accident Date : 10/2/2021

Location : KJE TOWARDS PIE TUAS

JM6DJ2HAA01101007
TP LonPac. Xiao Tong.

Model:

MAZDA 2
(26/2/2016)

3P:

GZ8052C (LONPAC)

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper <i>Distorted.</i>	893.40	✓	-
2	10pcs	Rear bumper clips <i>new</i>	-	30.00	✓
3	2pcs	Rear bumper screw clips <i>new</i>	-	20.00	✓
4	2pcs	Rear bumper o/s & n/s retainer <i>new</i>	116.20	✓	-
5	1 pc	Rear bumper centre retainer <i>new</i>	86.00	25	-
6	1 pc	Rear bumper body kit <i>new</i>	-	400.00	✓
7	1 set	Rear reverse sensor <i>new</i>	-	280.00	2w
8	1 pc	Rear reverse camera <i>new</i>	-	680.00	380
9	1pc	Rear end panel <i>Distorted</i>	599.30	✓	-
10	1 pc	Rear end panel inner trim <i>new</i>	137.20	✓	-
11	6 pcs	Rear end panel inner trim clips <i>new</i>	-	18.00	✓
12	2 pcs	Rear o/s & n/s tail-lamp <i>new</i>	883.20	790	-
13	2 pcs	Rear o/s & n/s tail-lamp panel <i>Repair</i>	342.40	X	-
14	1 pc	Rear tail gate cover <i>Distorted</i>	1,148.20	✓	-
15	1 pc	Rear tail gate cover weatherstrip <i>at</i>	210.20	✓	-
16	2 pcs	Rear o/s & n/s tail gate reflector <i>new</i>	559.20	✓	-
17	1 pc	Rear tail gate inner trim <i>new</i>	398.30	145	-
18	6 pcs	Rear tail gate inner trim clips <i>new</i>	-	18.00	10
19	2 pcs	Rear tail gate lock trim <i>new</i>	82.60	X	-
20	2 pcs	Rear tail gate lock trim clips <i>new</i>	-	6.00	X
21	1 pc	Rear tail gate privacy cover (speaker board) <i>torn</i>	396.00	✓	-
22	1pc	Rear tail gate 'MAZDA LOGO' emblem <i>new</i>	65.50	✓	-
23	1pc	Rear tail gate 'MAZDA 2' emblem <i>new</i>	56.40	✓	-
24	1pc	Rear tail gate 'SKY ACTIV TECHNOLOGY' emblem <i>new</i>	58.60	✓	-
25	1pc	Rear tail gate lock (Upper) <i>new</i>	328.60	✓	-
26	1 pc	Rear tail gate wiper arm <i>at</i>	210.50	95	-
27	1 pc	Rear tail gate wiper motor <i>new</i>	456.20	333	-
28	1 pc	Rear windscreen <i>shattered</i>	1,122.80	✓	-
29	1 pc	Rear windscreen moulding <i>new</i>	-	90.00	✓
30	1 pc	Rear solar film <i>new</i>	-	160.00	✓

31	1 pc	Rear windscreen sealant <i>rec</i>	-	60.00	-
32	1 pc	Rear spare wheel tank panel <i>Buckled.</i>	1,054.44	-	-
33	1 pc	Rear spare wheel tank panel insulator <i>rec</i>	-	210.00	120.00
34	1 pc	Rear spare wheel tank panel board <i>Deformed</i>	340.60	308	-
35	1 pc	Rear tool sponge <i>Deformed.</i>	562.80	285	-
36	1 pc	Rear o/s & n/s fender inner trim <i>Deformed.</i>	865.60	642	-
9369.04			Sub-Total:	10,974.24	1972.00
2495.23			20%	0%	10%
SN: 1488			After Less %:	8,779.39	1972.00

Labour					
1		To dismantle damaged parts, straighten & welding.	1,600.00	1200	
2		To spray painting.	1,200.00	800	
3		To remove & refit rear reverse camera.	50.00	✓	
4		To remove & refit rear reverse sensor	50.00	✓	
5		To re-set electrical system. <i>2210</i>	100.00	139 X	
6		To check wiring.	60.00	35	
7		To re-seal anti-rust.	80.00	✓	
Sub-Total:			3,140.00		
Total:			13,891.39		
After Less 20%:			11,113.11		

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)

Adrian L.
H/S. 10/02/21
09 days.



total: 11193.23
L/S: 8-9K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: