



Exceptional Journeys

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SLJ 4313 B**

	<b><u>Labour</u></b>	<b><u>Cost (\$)</u></b>
1	Conduct diagnostic check using Hi-Scan Pro test and clear trouble code	120.00 ✓
2	Conduct colabration on rear radar	120.00 ✓
3	Remove & reinstall rear seat assy, rear floor board, LH rear fender trims, & all other attachments to facillitate repair	120.00 ✓
4	Supply & install LH rear quarter glass solar film - RikeCool	80.00 ✓
	<b>Total Labour</b>	<b>440.00</b>
	<b>Taxable amount</b>	<b>440.00</b>
	<b>7% GST</b>	<b>30.80</b>
	<b>Grand total</b>	<b><u>\$ 470.80</u></b>

Thank You.

Yours faithfully

A handwritten signature in blue ink, appearing to read "LOI AI TING".

LOI AI TING  
SENIOR OFFICER - ADMIN  
**KIA SERVICE CENTRE**  
DID : 6568 4556 / 6568 4501  
FAX : 6567 5258 / 6565 1240