

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0132/2021/TF
DATE : 11-Feb-21
WIP : 15132

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/2/21
YOUR INSURED VEH NO : SLX 2259 P

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR. VIMLESH KUMAR LAKHI KHEMANI
ADDRESS : BLK TAMPINES ST 72
#11-40
SINGAPORE 520737
TELEPHONE : HP +65 96300636
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : MT/00313634/04
VEHICLE NO : **SGA 5555 U**
MODEL CODE : A6 1.8 TFSI S TRONIC
MODEL YEAR : 30/9/2016
ENGINE NO : CYG 016030
CHASSIS NO : WAUZZZ4G5HN028350
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Feb-21
PLACE OF ACCIDENT : ALONG UBI AVE 2

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGA 5555 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGES.	S/N \$	360.00	✓ /
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00 500	✓ /
3	TO RESPRAY REAR BUMPER.	\$	1,000.00 550	✓ /
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓ /
TOTAL LABOUR CHARGES		:	\$ 2,752.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGA 5555 U

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER <i>defound</i>	1	\$ 3,268.00	✓	2614.40
2	REAR BUMPER FIXING PARTS <i>Ne a</i>	1	\$ 273.00	+	
3	REAR BUMPER SPOILER <i>lit</i>	1	\$ 479.00	✓	387.20
4	REAR BUMPER SECURING STRIP <i>2100 Nee</i>	1	\$ 223.00	X	
5	REAR BUMPER CLOSING ELEMENT - LH / RH <i>Ne a</i>	2	\$ 162.00	+	
6	REAR BUMPER CARRIER <i>3 Nee</i>	1	\$ 1,012.00	+	
7	REAR BUMPER CARRIER SEAL	2	\$ 28.00	+	
8	REAR BUMPER TOP GUIDE SECTION - LH / RH	2	\$ 66.00	+	
9	REAR BUMPER TOP GUIDE SECTION PIN - LH / RH	2	\$ 25.00	+	
10	REAR BUMPER GUIDE PROFILE - LH / RH	2	\$ 134.00	+	
11	REAR BUMPER GUIDE SECTION - CENTER	1	\$ 106.00	+	
12	REAR BUMPER HOLDING STRIP - LH / RH	2	\$ 126.00	+	
13	REAR BUMPER SENSOR <i>3 Nee</i>	1	TBC	+	
14	REAR BUMPER SENSOR SEAL RING <i>3 Nee</i>	4	\$ 6.00	+	
15	SUNDRIES <i>2100 Nee</i>		\$ 200.00	X	

TOTAL SPARE PARTS	:	\$	6,108.00
TOTAL LABOUR CHARGES	:	\$	2,752.00
GRAND TOTAL	:	\$	8,860.00

ALL CHARGES ARE INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ling*
SURVEYED DATE : *18/02/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT