

profi automotive

10 Kaki Bukit Road 2 #01-03 First East Centre S417868 M:94335558 E: profi.automotive@asia.com

17 February 2021

Date Of Accident:

Name Of Registered Owner:

Vehicle Registered Number:

Vehicle Model:

TP ALG.

Xiao Tong.

09 Feb 2021

Wong Kim Fong

SMG9879G

Toyota Sienta

NSP1707040637

Description (Listed Item)	Qty	Unit Price (S\$)	Amount (S\$)
Rear bumper <i>Distorted</i>	1	647.70	647.70 ✓
Rear bumper retainer LH <i>2nd</i> SVC	1	52.30	52.30 +
Rear bumper retainer RH <i>Neu</i>	1	52.30	52.30 ✓
Rear bumper outer bracket LH <i>?</i>	1	155.00	155.00 +
Rear bumper outer bracket RH <i>new</i>	1	155.00	155.00 +
Rear bumper inner bracket LH <i>new</i>	1	179.00	179.00 +
Rear bumper inner bracket RH	1	179.00	179.00 +
Rear bumper centre garnish <i>cut</i>	1	230.00	230.00 ✓
Rear bumper side garnish LH <i>cut</i>	1	159.10	159.10 ✓
Rear bumper side garnish RH <i>new</i>	1	159.10	159.10 ✓
Rear bumper reflector LH <i>could</i>	1	87.80	87.70 ✓
Rear bumper reflector RH <i>Not new</i>	1	87.80	87.80 +
Rear tailgate <i>Dented</i>	1	1631.10	1631.10 1288.
Rear tailgate hinge LH <i>new</i>	1	132.00	132.00 +
Rear tailgate hinge RH	1	132.00	132.00 +
Rear tailgate lock <i>Neu</i>	1	401.00	401.00 +
Rear tailgate lock catch <i>new</i>	1	52.00	52.00 +
Rear tailgate weatherstrip <i>cut</i>	1	465.30	465.30 329
Rear tailgate inner trim board <i>Neu</i>	1	198.00	198.00 +
Rear tailgate emblem logo <i>Neu</i>	1	65.60	65.60 ✓
Rear tailgate lamp LH <i>could</i>	1	321.40	321.40 ✓
Rear tailgate absorber LH <i>new</i>	1	282.50	282.50 +
Rear tailgate absorber RH	1	282.50	282.50 +
Rear tailgate switch opener	1	265.00	265.00 +
Rear tailgate opening panel LH top <i>new</i>	1	277.00	277.00 +
Rear tailgate opening panel LH bottom	1	297.00	297.00 +
Rear windscreen moulding top <i>new</i>	1	64.00	64.00 ✓
Rear windscreen moulding bottom	1	64.00	64.00 ✓
Rear windscreen moulding LH	1	57.00	57.00 ✓
Rear windscreen moulding RH	1	57.00	57.00 ✓
Rear fender inner garnish LH bottom <i>new</i>	1	783.00	783.00 +
Rear fender inner garnish LH top <i>Neu</i>	1	265.00	265.00 +
Rear fender inner garnish LH bottom pocket <i>Neu</i>	1	208.00	208.00 +
Rear end panel inner <i>Repair</i>	1	471.00	471.00 +
Rear end panel outer <i>Dented</i>	1	531.00	531.00 ✓
Rear end panel top garnish <i>crushed</i>	1	184.50	184.50 ✓
Rear spare tyre top board <i>Neu</i>	1	558.70	558.70 +
Rear spare tyre panel board inner cover <i>Neu</i>	1	349.00	349.00 +
Fuel tank cover <i>Repair</i>	1	198.00	198.00 +
Rear axel <i>Neu</i>	1	3174.10	3174.10 X

profi automotive

10 Kaki Bukit Road 2 #01-03 First East Centre S417868 M:94335558 E: profi.automotive@asia.com

Rear shock absorber LH	1	272.20	272.20
Rear hub bearing LH	1	937.80	937.80
Rear sliding door panel	1	1518.20	1518.20
Rear sliding run channel LH	1	465.00	465.00
Rear door lock LH	1	321.00	321.00
Rear auto door motor module assembly LH	1	698.00	698.00
Rear fender LH	1	1697.30	1697.30
Rear fender air vent LH	1	45.00	45.00
Rear fender inner trim LH	1	721.00	721.00
Rear fender inner shield LH	1	265.00	265.00
Rear tail lamp LH	1	457.20	457.20
Rear fender quarter glass moulding LH	1	201.00	201.00

Subtotal 21509.30
Less (25%) 5377.30
Total 16132.00

Description (Special Nett Item)	Qty	Unit Price (S\$)	Amount (S\$)
Rear bumper clip	1 set	40.00	40.00
Rear tailgate inner trim clip	1 set	40.00	40.00
Rear fender inner trim clip	1 set	40.00	40.00
Rear reverse sensor	1 set	400.00	400.00
Rim	1	700.00	700.00
Brake fluid	1 btl	60.00	60.00
Joint sealant	1	120.00	120.00
Windscreen sealant	1	120.00	120.00

Total 1520.00

740

profi automotive

10 Kaki Bukit Road 2 #01-03 First East Centre S417868 M:94335558 E: profi.automotive@asia.com

Description (Labour)	Qty	Unit Price (\$)	Amount (\$)
Check wiring and lightning system		120.00	120.00 30
Remove and renew reverse sensors		120.00	120.00 50
Remove, refit rear lining, trim and garnish		250.00	250.00 80
Remove and refit fuel tank		150.00	150.00 80
Remove and refit tailgate glass		150.00	150.00 120
Remove and refit rear quarter glass LH		130.00	130.00 60
Computerised and check rear wheel alignment		150.00	150.00 80
Remove and renew rear undercarriage parts		300.00	300.00 80
Transfer parts, attachment from old tailgate to new		200.00	200.00 80
Transfer parts, attachment from old sliding door LH to new	3840	200.00	200.00 x 1500
Panel beating on affected areas and renew damage parts		2600.00	2600.00 1500
Spray painting on affected areas		1800.00	1800.00 80
Apply anti rust on affected areas		150.00	150.00 80
Total			6320.00

Description (Cost of Repair)	Qty	Unit Price (\$)	Amount (\$)
Listed Items		16132.00	16132.00
Special Nett Items		1520.00	1520.00
Labour		6320.00	6320.00
Subtotal			23972.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Supplementary: 807-75

total: 10449.62

H/s: 8.3K

10 Days

8.3K

profi automotive

10 Kaki Bukit Road 2 #01-03 First East Centre S417868 M:94335558 E: profi.automotive@asia.com

17 February 2021

Date Of Accident:
Name Of Registered Owner:
Vehicle Registered Number:
Vehicle Model:

09 Feb 2021
Wong Kim Fong
SMG9879G
Toyota Sienta

Supplementary Item

Description (Listed Item)	Qty	Unit Price (S\$)	Amount (S\$)
Rear slide rail cover LH <i>authd.</i>	1	420.00	420.00
Rear fender outer trim LH <i>61632A</i>	1	756.00	756.00 <i>657</i>
<i>1077</i>			
<i>807.75</i>			
Subtotal			1176.00
Less (25%)			294.00
Total			882.00

Description (Special Nett Item)	Qty	Unit Price (S\$)	Amount (S\$)
Rear number plate holder <i>3x4 mm</i>	1	20.00	20.00 <i>+</i>
Reverse camera	1	300.00	300.00 <i>+</i>
Total			320.00

Supplementary: 807.75