



興利摩多汽車燒焊廠

HING LEE MOTOR CAR REPAIR & WELDER WORKS

BLK 7 UNIT 397-D WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677996

TEL: 762 1010, 763 9909 FAX: 760 2724 Email: hinglee@pacific.net.sg

Fish Podium

GBJ 8807K

Date 08/12/21 NO.

1.	Rear tail gate / pr	\$2015.30	N 1750
2.	Rear tail gate Lock / Tum	300.15	N 250
3.	Rear tail gate w/strip X svc	140.86	NX
4.	Rear "NISSAN" emblem /NA	69.70	N /
5.	Rear "NV 200" emblem /Nec	87.00	N /
6.	Rear no plate Lamp Garish /SCR	386.40	N 260
7.	1 Set Rear tail gate Trim Board clip Xsvc	40.00	SNX
8.	Rear LH tail Lamp bezel / CRA	297.51	N /
9.	Rear end panel X svc	250.56	NX
10.	Rear end panel Garish X svc	187.45	NX
11.	Rear bumper bumper. / CR4.	699.78	N 615
12.	Rear tail gate "VANETTE" emblem /Nec	79.70	N / 3408.91
13.	Rear bumper Sensor / Short.	220.00	SN -200
14.	1 Set Rear bumper clip / Nec.	35.00	SN 30
15.	Rear "70km" sticker / Nec	15.00	SN /
16.	Rear "5 pax" sticker / Nec	15.00	SN /
17.	Rear no plate /SCR.	45.00	SN /
18.	Rear wiper motor ? Xsvc	405.00	NX
19.	Rear w/Screen Repair kit /Nec.	120.00	N 40 sn
20.	2 R&L Rear tail gate Shock Stand \$1800 Xsvc	360.00	NX
			345





興利摩多汽車燒焊廠

HING LEE MOTOR CAR REPAIR & WELDER WORKS

BLK 7 UNIT 397-D WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677996
TEL: 762 1010, 763 9909 FAX: 760 2724 Email: hinglee@pacific.net.sg

Fish Podium

GBJ. 8807K

Date 08/2/21 NO.

Labour Charge			
1.	To Remove & Refit Rear glass	\$ 120.00	/
2.	Rear bumper Sensor Remove & Refit	\$ 80.00	30.
3.	wiring fee	\$ 40.00	30.
4.	Anti Rust	\$ 100.00	40.
5.	Respray painting Damage Area	\$ 600.00	400
6.	To Repair fcc Damage Area	\$ 600.00	550
7.	To Remove & Refit Boot Interior	\$ 80.00	40.
			1,210.

Repair day - 48 days

P/P

before paint photo

Sun Pin (Lick) - 86612627

17/02/2021

Sunpin@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

hinglee motor @ yahoo-com.sg



bp

興利摩多汽車燒焊廠

HING LEE MOTOR CAR REPAIR & WELDER WORKS

BLK 7 UNIT 397-D WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677996

TEL : 762 1010, 763 9909 FAX : 760 2724 Email: hinglee@pacific.net.sg

Fish Podium

G3J 8807K

Date

02/3/21

NO.

Supplementary

1. Rear bumper sponge / cm

\$ 133.80

N /

~~3,548.91~~

3,408.91

133.80

133.80

~~3682.71~~

3,542.71

P/P

~~-10%~~~~-10%~~

\$4,743.44

P

~~3,314.44~~

3,188.44

4 days

SN

345

345

1,210

1,210

~~4,869.44~~

4,743.44

