

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

9-Feb-21

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8065 E

1 pc	Front o/s fender inner shield	X repair	\$	120.00
1 pc	Wheel cover	X	\$	116.00
			\$	236.00
		Less 10%	\$	23.60
			\$	212.40

### S/NETT

1 set	Front o/s fender inner shield clips	X NN	\$	28.00
	Sundry		\$	50.00 X NN
	To check wheel alignment		\$	120.00 60.
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same		\$	450.00 200
	To putty and spray painting on Front bumper, front o/s fender		\$	400.00 ✓
	To applu rustproofing on repaired panels		\$	80.00 X NN
			\$	1,340.40

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

20 days.

part by part.

After repair photos.

Gmo Qian - 82880282

22/2/2021.