

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

9-Feb-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8065 E

1 pc	Front o/s fender inner shield	X repair	\$	120.00
1 pc	Wheel cover	X	\$	116.00
			\$	236.00
		Less 10%	\$	23.60
			\$	212.40

S/NETT

1 set	Front o/s fender inner shield clips	X NN	\$	28.00
	Sundry		\$	50.00 X NN
	To check wheel alignment		\$	120.00 60.
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same		\$	450.00 200
	To putty and spray painting on Front bumper, front o/s fender		\$	400.00 ✓
	To applu rustproofing on repaired panels		\$	80.00 X NN
			\$	1,340.40

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

660

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

20 days.

part by part.

After repair photos.

Gmo Qian - 82880282

22/2/2021.