

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD232G

AAD2102-042

NOT AUTHORIZED
LI Sup \$11000

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

SHD232G

VF1ABL15AUC282171

RENAULT

LATITUDE

31/01/2021

AIG

16/10/2015

PART	LIST
1 BUMPER COVER REAR	\$ <i>Bu</i> 561.70 ✓
1 BUMPER LOWER REAR	\$ <i>Sn</i> 411.90 X
1 BUMPER BRACKET CTR REAR	\$ <i>Sn</i> 98.10 X
1 BUMPER BRACKET SIDE RH REAR	\$ <i>Sn</i> 82.10 X
1 BUMPER BRACKET SIDE LH REAR	\$ <i>Sn</i> 80.80 X
1 BUMPER RETAINER RH REAR	\$ <i>Sn</i> 59.80 ✓
1 BUMPER RETAINER LH REAR	\$ <i>Sn</i> 54.20 X
1 BUMPER BEAM REAR	\$ <i>n</i> 547.80 X
	\$ 1,896.40
	10% \$ 189.64
	<u>\$ 1,706.76</u>

Special Nett	
1SET PARKING AID	\$ <i>Sn</i> 700.00 X
1SET REAR BUMPER CLIP	\$ <i>Ma</i> 66.00 ✓
1SET BUMPER BRACKET CTR CLIP	\$ <i>na</i> 33.00 X
1SET BUMPER BRACKET SIDE CLIP RH RR	\$ <i>Sn</i> 10.00 ✓
1SET BUMPER RETAINER RH CLIP RR	\$ <i>Sn</i> 20.00 X
1SET BUMPER LOWER REAR RIVET	\$ <i>na</i> 22.00 X
1SET BUMPER LOWER REAR CLIP	\$ <i>re</i> 66.00 X
	TOTAL \$ 917.00
	TOTAL PARTS \$ 2,623.76

LABOUR

Trans-cab Auto Services Pte Ltd

AAD2102-042

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD232G

Putty And Spray Painting Of The Affected Portion.	\$	1,500.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,500.00	3001
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Check Electrical Lighting Concerned.	\$	170.00	101

TOTAL \$ 4,070.00

Over All Total \$ 8,400.52

(LUMP SUM)**Repair Days****7 DAYS****2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: