

CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Muhamad Royhaizat Bin Musa
C/o: GP Motoring Pte Ltd
284 Macpherson Road,
Singapore 348608

Date : 18 February 2020
Our ref : GPM/02/2002/TP

Accident Date : 06 February 2020
Inspection Date : 12 February 2020
Repairer Name : GP Motoring Pte Ltd
284 Macpherson Road,
Singapore 348608

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : FBN 7647 R
Make / Model : Honda FS150
Chassis No : PMKKC27A0KB204852
Engine No : KC27E2214147

Year / Capacity : 2018 / 149 cc
Colour : Orange
Mileage : 24180

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front	: IRC	90/80 -17	5 mm	Sport
Rear	: IRC	90/80 -17	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 89 copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis
and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle
and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a Lump Sum of \$ 3,100.00 on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.

L APPRAISER PTE LTD

Vehicle Registration No: FBN 7647 R

Our Ref No: GPM/02/2002/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Front o/s footrest bracket	Damage	\$ 65.00	\$ 65.00	✓
1	Front o/s footrest rubber	Necessary	\$ 35.00	\$ 35.00	✓
1	Brake pedal	Damage	\$ 42.00	\$ 42.00	X
1	Rear o/s footrest	Intact	\$ 40.00		
1	Exhaust assy	Damage	\$ 585.00	\$ 585.00	X
1	Exhaust protector	Damage	\$ 80.00	\$ 80.00	✓
1	Rear o/s tailboard	Damage	\$ 155.00	\$ 155.00	X
1	Chain cover	Damage	\$ 48.00	\$ 48.00	X
1	Rear o/s signal	Damage	\$ 65.00	\$ 65.00	X
1	Rear taillamp	Damage	\$ 155.00	\$ 155.00	X
1	Rear brake disc	Damage	\$ 175.00	\$ 175.00	X
1	Rear fender	Damage	\$ 120.00	\$ 120.00	✓
1	Rear rim	Damage	\$ 350.00	\$ 350.00	180(SW)
1	Rear rim shaft	Necessary	\$ 60.00	\$ 60.00	X
1	Rear rim hub with bearing	Damage	\$ 238.00	\$ 238.00	X
1	Swing-arm	Damage	\$ 590.00	\$ 590.00	X
			\$ 2,803.00	\$ 2,763.00	278
Less 10%			\$ 280.30	\$ 276.30	
Total Cost - List Items			\$ 2,522.70	\$ 2,486.70	250.2

SPECIAL NETT ITEMS

1	Rear number plate	Damage	\$ 18.00	\$ 18.00	10
1	Rear box	Damage	\$ 280.00	\$ 280.00	150
1	Rear box bracket	Damage	\$ 100.00	\$ 100.00	X
1	Swing-arm rubber	Necessary	\$ 75.00	\$ 75.00	X
1	Sticker (1 set)	Necessary	\$ 95.00	\$ 95.00	X
Total Cost - Special Nett items			\$ 568.00	\$ 568.00	160

Total cost of parts

\$ 3,090.70 \$ 3,054.70

LCL APPRAISER PTE LTD

Vehicle Registration No: FBN 7647 R

Our Ref No: GPM/02/2002/TP

S/No	Description	Repairer's Estimate	Revised Amount
Total cost of parts c/f		\$ 3,090.70	\$ 3,054.70

LABOUR

1	To provide towing service.	\$ 50.00	\$ 50.00 X
2	To check electrical system, wire harness and focus headlamp.	\$ 80.00	\$ 50.00 X
3	To provide labour charges, workmanship to dismantle above damaged parts ; re-align body structure and damaged consistent to the accident.	\$ 380.00	\$ 320.00 120
4	To check , repair and straighten body frame to the original position.	\$ 350.00	\$ 350.00 X

GRAND TOTAL

\$ 3,950.70	\$ 3,824.70
-------------	-------------

7/10.2

20% : 550

2 Days.