



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS3/LPC20002428/Gqd3e2-1	
			Date: 09/04/2021	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKF 1706D	Veh. Inspected	FBN 7647R
	Policy No.		Coverage (\$)	0.00
	Claim No.	19/20/20/VP05/023024	Excess (\$)	0.00
	Assign From	ONG LI LI	Assign Date	10/02/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA FS150F	c.c	149
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	PMKKC27A0KB204852	Colour	ORANGE
	Odometer	24180 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	90/80-17	IRC	5 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	120/70-17	IRC	5 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/02/2020	Inspection Date	12/02/2020
	Survey held at	GP MOTORING PTE LTD 282 MACPHERSON ROAD SINGAPORE 348607		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	