REF. US TMI21	1000 A3
ACC	
ASSI	GNMENT
From: Date:	Veh No: SHA 2586M Yr Regn: Ang 2017
Estimata Cost.	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /-
GD /-TEP WS / TP RES / OD RES / EVA / INV / MV	Truck/Trailer or
To Inspet Vehicle No:	Make: Toyota Prius c.c 1798
ent Workshop m/s	Colour Blue A/C: Insured Std NI NA
of	Sp.Reading 507737 T/Radio: Insured / Std / NI / NA
Insured	Eng/No: 22RS061286
Policy No.	C/NO: JTDKB3FU603563518
Claims No. <u>M2100745</u>	Gen. Cond. Good / Fair / Poor / Burnt
Sum Irrayred: Excess:	Steering: thorater / Jammed / Leaked / Burnt or
(Cfi ⇔tt's Record)	Brake: (Inorder / Jammed / Leaked / Burnf or
Make diven:	Modi: Nil S/Rim / STD A/Rim or
	Tyre Size: F: 195/65 3-15
(Policy Condition)	R:
Remark The veh had commenced its N/S 0/S	BS DUN EXNOVA GY FS LIZA MIC OHTSU PIR SUMI
repair at the fime of inspection.	TOYOTYOKO DT Westleke
Bal. or Market Value:	Front Rear
IDAC Accident Rport:Consistent? : Yes or No	R/Bal. S mm R/Bal. S mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. C mm
Est. Repairs: 10 days Res.: Yes or No	D.O.A. 09 02 22 D.O.I. 17 02 221
Lurn Sum: 60 20 % 3 Val.: Yes or No	Survey held at Syrvet Sin Ming
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
Tokio SMW 3074 J	
R. III S. Ch.	· h
manye ar parts to	with her ports - LIS at 10% 1.
24/08/2n Janu :2/3 20 2001-	it 10 days of rep (Red \$26591.58, 57%)
27/08/21@4.29pm revised to Telma Gomez vi	
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 10
1) 27/08 Typist : Final Report	Resurvey No. of Trip: 1 Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fe	ee: : Site Insp (\$)s+Rssi
	: Interview (\$) Photos
Reperior MER-TP	: Tech. Invs (\$) Others
Lunap Sturn / LB.h (\$ 20200)	:Weelend (\$
	TOTAL

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

INSURANCE:

DATE:

10-Feb-21

LKK Auto Consultants hence notify the Repairer of the following:

the Repairer of the following:

the resurvey before/after spray painting

MODEL:

TOYOTA PRIUS

To display damaged part(s) during resurvey Parts prices are subject to confirmation

VEHICLE NO.:

SHA2586M

Third party survey is on a "Without Prejudice" basis

DESCRIPTION			O CONTROLLION	P(s) is allowed
	QTY	LIST PRICE	AMOUNT	flust be resurveyed and
REAR BUMPER DIPLEM IN	1	\$458.60	\$458.60	Insurance Company
REAR BUMPER SIDE RETAINER SYL	1	\$112.70	\$192.70	rei 🗡
REAR BUMPER CLIPS	1	\$22.00	\$22.00	*
REAR BUMPER SIDE CLIP HA	1	\$25.00	\$25.00	×
REAR TYRE RIM (RH) NH	1	\$1,555.00	\$1,555.00	*
REAR WHEEL HUB CAP (RH) C	1	\$177.70	\$177.70	~
REAR WHEEL BEARING & HUB assy	1	\$610.20	\$610.20	×
REAR LOWER ARM HA ON THAN	1	\$497.50	\$497.50	4~
REAR UPPER ARM Hel distance	1	\$356.80	\$356.80	4
REAR KNUCKLE ARM PHI Austra	1	\$810.60	\$810.60	X L
FRONT BUMPER COVER broken Itom	1	\$499.90	\$499.90	1
FRONT BUMPER LOWER REINFORCEMENT BRACKET HA	2	\$330.00	\$660.00	×
FRONT SIDE MEMBER REINFORCEMENT PANEL (LH/RH)		\$ 320.70	\$641.40	7
FRONT SIDE MEMBER SIDE COVER HA	2	\$ 172.50	\$345.00]⊁
LAMP ASSY, FOG, RH Scredded money borken	1	\$920.00	\$920.00	1
LAMP ASSY, FOG, LH	1	\$920.00	\$920.00	1 ×
FRONT BUMPER SIDE RETAINER SAL	2	\$77.00	\$154.00	19
FRONT LOWER PANEL HA	1	\$320.65	\$320.65	×
FRONT LOWER SIDE RAIL (LH/RH)	2	\$230.80	\$461.60	14
UNIT ASSY, HEADLAMP, RH (LED) money borker	1	\$3,455.00	\$3,455.00	
UNIT ASSY, HEADLAMP, LH (LED) month broken	1	\$3,455.00	\$3,455.00	W2637-60
HEADLAMP ECU HH	1	\$682.60	\$682.60	× 35,00
HEAD LAMP PANEL (RH)	1	\$240.10	\$240.10	×
HEAD LAMP PANEL (LH)	1	\$240.10	\$240.10	*
OP PANEL CENTRE H	1	\$364.98	\$364.98	400
OP PANEL SIDE H	1	\$145.90	\$145.90	*
ENDER SUB-ASSY, FRONT RH Devis	1	\$945.30	\$945.30	-
ENDER SUB-ASSY, FRONT LH	1	\$945.30	\$945.30	×
RONT FENDER SHIELD tom HIS of dymu	2	\$38.00	\$76.00	·
RONT FENDER SHIELD CLIP	2	\$14.90	\$29.80	
RONT FENDER HYBRID EMBLEM, LH	1	\$86.50	\$86.50	×
RONT FENDER HYBRID EMBLEM, RH Hec	1	\$86.50	\$86.50	·-
RACKET, FRONT SIDE PANEL, RH	1	\$86.30	\$86.30	×
RACKET, FRONT SIDE PANEL, LH	1	\$86.30	\$86.30	7
RONT WHEEL RIM Chistorna 1 124	2	\$1,570.55	\$3,141.10	·
RONT WHEEL RIM CAP HH	2	\$189.60	\$379.20	×
RONT WHEEL HUB CAP O 3 broken ms distriby	2	\$177.70	\$355.40	
RONT WHEEL HUB BEARING > ? Dem	2	\$560.10		21
RONT SUSPENSION LOWER ARM (RH) ? an through	1	\$637.50		2/
RONT SUSPENSION LOWER ARM (LH) Z distur	1	\$637.50		2
RONT SHOCK ABSORBER (LH) Z	1	\$401.80		21
RONT SHOCK ABSORBER (RH) ≥ >>	1	\$401.80		2~
BSORBER TOP MOUNTING HH	2	\$196.20		×
RONT DRIVE SHAFT (LH)	1	\$1,764.00		*
RONT DRIVE SHAFT (RH) HH	1	\$1,764.00	04 704	× 1310.10
ACK & PINION ASSY HH	1	\$1,634.90		×

BAR, STABILIZER H-	T 1	\$360.00	\$360.00	
LINK ASSY, FRONT STABILIZER, "	2	\$199.00		- /
KNUCKLE, STEERING, RH Z MANN	1	\$580.80	\$580.80	1212
KNUCKLE, STEERING, LH 2 destand	1	\$580.80	\$580.80	
JOINT ASSY, LOWER BALL, FRONT (LH/RH) 中村 11	2	\$199.98		
END SUB-ASSY, TIE ROD, RH & distorne	1	\$159.30	\$399.96	
END SUB-ASSY, TIE ROD, LH	1		\$159.30	-
SENSOR, SPEED, FRONT RH	1	\$159.30 \$446.50	\$159.30	Η΄
SENSOR, SPEED, FRONT LH	1		\$446.50	⊣ ′
ENGINE UNDER COVER 2 HOVE	1	\$446.50 \$457.20	\$446.50	⊣
ENGINE UNDER COVER FRONT 7	1		\$457.20	4
ENGINE CROSS MEMBER HA MISTAN	1	\$288.30	\$288.30	-, -
ENGINE MOUNTING (LH/RH)		\$2,531.70	\$2,531.70	-
ENGINE MTG (FRONT)	2	\$386.60	\$773.20	-1 `
ENGINE MTG (REAR)	1	\$174.63	\$174.63	-1 '.
ENGINE FRONT MOUNTING BRACKET, LH	1	\$172.90	\$172.90	
COVER, ENGINE UNDERCOVER CENTRE	1	\$172.91	\$172.91	17
COVER, ENGINE UNDER, CTR LH	1	\$448.30	\$448.30	- 1 ''
COVER, ENGINE UNDER, CTR RH	1	\$76.90	\$76.90	1 (
COVER, ENGINE UNDER, REAR RH	1	\$76.90	\$76.90	1 /
COVER ENGINE		\$84.90	\$84.90	文
SUB TOTAL	1	\$84.90	\$84.90	X
LESS 20% 25%			\$41,978.03	21160.56
DISCOUNTED TOTAL			\$8,395.61	1 = 0
TO TAL			\$33,582.42	21160.56
REAR BUMPER RUBBER MAT HA SN	4	252.22		1
DEAD DOOD COLLEGE	1	\$50.00	\$50.00	1 200
EDON'T DOOR COLLEGE	1	\$80.00	\$80.00	
DEAD TYPE (DIE)	1	\$75.00	\$75.00	~ 263.W
OIT	1	\$216.00	\$216.00	X /
FRONT TYRE (LH/RH) OS TAN TIS CON 50% SN SUB TOTAL	2	\$216.00	\$432.00	108.00
			\$853.00	
Labour Charge				
Panel Beating				
Spray Painting Charge	1	\$2,000.00	\$2,000.00	
Wiring Charge	1	\$2,000.00		
Tuff Kote	1	\$100.00	\$100.00	30 -
Towing Charge	1	\$150.00	\$1 50.0 0	401-
Remove/Refix Reverse Sensor	1	\$80.00	\$80.00	HM
Remove/Refix Undercarriage (RR)	1	\$120.00	\$120.00	***
Re-set Rear ABS System	1	\$400.00	\$400.00	120/-
Four Wheel Alignment	1	\$400.00		
Remove/Refix Undercarriage (Frt)	1	\$120.00	\$1 20.00	601-
Re-set Frt ABS System	2	\$400.00	\$800.00	7201-
Remove/Refix Radiator	2	\$200.00	\$400.00	HM 7850.00
Remove/Refix Aircon & Refill Gas	1	\$90.00		44
Remove/Refix Fuse Box	1	\$130.00		HH
Diagnostic & Resetting To Erase Fault Code	1	\$120.00	\$120.00	
TOTAL LABOUR	1	\$550.00	\$550.00	150 -
17 02 22 C 1300 kms			\$7,460.00	*
ESTIMATE TOTAL HA AUTOM				18902.47.
50, 1,100,			\$41,895.42	18983.42
			9	MP 3775.12
This is an initial estimate based on a visual inspection of the ab will be prepared after the vehicle is surveyed by a motor Su	ove vehic	cle. The final repa	ir quantum	22758.54
company.			Ilc and sal	
company. LKK And Chek Pat Tries: US 20,2001-				

BIFROST AUTO PTE LTD

Supplementary ESTIMATE

DA ⁻	TF.

18-Feb-21

MODEL:

TOYOTA PRIUS

VEHICLE NO.:

SHA 2586 M (S)

INSURANCE: Tokio

DESCRIPTION	QTY	LIST PRICE	AMOUNT
FRONT DOOR (RH) Dewn	1	\$2,256.40	
REAR DOOR (RH)	1	\$2,201.10	, , , , , , , , , , , , , , , , , , , ,
REAR FENDER, RH	1	\$836.70	,
Rocker Panel Outer Garnish のります しゅう	1	\$576.00	\$576.00
SUB TOTAL			
LESS 30% 25%			\$5,870.20
DISCOUNTED TOTAL			\$1,174.04
DIGGORIED TOTAL			\$4,696.16
REAR DOOR ADVERTISEMENT LOGO	N 1	\$100.00	\$100.00
FRONT DOOR ADVERTISEMENT LOGO HE SI		\$100.00	\$100.00
SUB TOTAL	+		\$200.00
			\$200.00
ESTIMATE TOTAL			
ESTIMATE TOTAL			\$4,896.16

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2kk Augo

5033.50

25% 3775.12

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

mpany 1R A2586M 5 Feb 2021 YOTA IUS HYBRID 1.8 CVT 10 RS061286 DKB3FU603563518 0 kW (120 bhp) 0,007.00 Aug 2017 Aug 2017
A2586M Feb 2021 YOTA IUS HYBRID 1.8 CVT Rec 17 RS061286 DKB3FU603563518 0 kW (120 bhp) P,007.00 Aug 2017
Feb 2021 YOTA IUS HYBRID 1.8 CVT IVE 17 RS061286 DKB3FU603563518 0 kW (120 bhp) P,007.00 Aug 2017
Feb 2021 YOTA IUS HYBRID 1.8 CVT IVE 17 RS061286 DKB3FU603563518 0 kW (120 bhp) P,007.00 Aug 2017
Feb 2021 YOTA IUS HYBRID 1.8 CVT IIE 17 RS061286 DKB3FU603563518 0 kW (120 bhp) P,007.00 Aug 2017
YOTA IUS HYBRID 1.8 CVT tile 17 RS061286 DKB3FU603563518 0 kW (120 bhp) P,007.00 Aug 2017
IUS HYBRID 1.8 CVT lie 17 RS061286 DKB3FU603563518 0 kW (120 bhp) P,007.00 Aug 2017
ne 17 RS061286 DKB3FU603563518 0 kW (120 bhp) P,007.00 Aug 2017
ne 17 RS061286 DKB3FU603563518 0 kW (120 bhp) P,007.00 Aug 2017
RS061286 DKB3FU603563518 0 kW (120 bhp) P,007.00 Aug 2017
RS061286 DKB3FU603563518 0 kW (120 bhp) P,007.00 Aug 2017
DKB3FU603563518 0 kW (120 bhp) P,007.00 Aug 2017
0 kW (120 bhp) ?,007.00 Aug 2017
P,007.00 Aug 2017
Aug 2017
NG ZOT/
000.00
550.50
Aug 2025
750.00
33.33
Aug 2025
Car up to 1600cc & 97kW (130bhp)
1,200
,320.00
.576.00
326.00
, ,

The information contained herein is correct as at 10 Feb 2021



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 10/02/2021 11:04 (SGT) Date of Accident 09/02/2021 17:00 (SGT) Exact Location of Accident Chang Charn Rd, Singapore Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHA2586M

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD Company Reg No 1XXXXX821R **Email Address** fleetsafety@cdgtaxi.com.sg Mobile Phone No (Phone) +65-82231632 Alternative Phone No (Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer Tovota Model Prius Variant Exact purpose for which vehicle was being used at time of Private hire Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Taxi

INSURANCE COMPANY

Name of Insurance Company Type of Coverage ThirdPartyFireTheft Fleet Policy Yes Policy Number VFX/P2419138 Cover Note Number

DRIVER

Name of Driver KEH GEOK HIN NRIC No SXXXX966J Date Of Birth 15/12/1952 Occupation Outdoor

Date Of Driving Pass 17/04/1973 Driving experience 47 YEARS AND 10 MONTHS Gender Male Mobile Number (Phone) +65-82231632 Alt. Phone Number Email Address fleetsafety@cdgtaxi.com.sg Address BLK 39 JALAN RUMAH TINGGI #11-266 Address complement Postcode 151039 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Major/Minor Rd Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? No Was any other material or property damaged? Yes Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT ON 09/01/2021 AT ABOUT 1700HRS, I WAS DRIVING MY VEHICLE (SHA2586M) ON A ONE WAY ROAD (CHANG CHARN RD) AND VEHICLE B (SMW8074J) MADE AN ILLEGAL EXIT FROM UNIT 8 OF CHANG CHARN ROAD AND COLLIDED ONTO MY FRONT RIGHT BUMPER RESULTING MY VEHICLE PUSHED FORWARD AND TOWARDS THE LEFT SIDE CURB WHICH RESULTED A TYRE PUNCTURE (FRONT LEFT) AND DAMAGED. I WAS INJURED ON MY RIGHT SHOULDER AND RIGHT LEG ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No Was there any audio recorded? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SMW8074J Vehicle Manufacturer Mercedes Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Private car Name of Driver

KWAN XIANG CONG

(Phone) +65-92731200

SXXXX943B

NRIC No

Contact Number

Address	_
Address complement	_
Postcode	-
Insurance Company Name	_
Nature Of Damage	_
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

INJURED PERSONS DETAILS

INJURED 1

Name of injured person Address Address Complement	KEH GEOK HIN BLK 39 JALAN RUMAH TINGGI #11-266
Post Code Approximate Age Years Old Injuries Sustained Injured person in which vehicle? Were seat belts worn? Was this injured conveyed to hospital by ambulance?	151039 69 RIGHT SHOULDER AND RIGHT LEG SHA2586M Yes No

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD CO. REG. NO. 199303821R

> Policyholder's Signature Date & Time:


Driver's Signature

(If driver is not the policyholder) Date & Time: 10.02.2021

@ 10:30 hrs

Reporting Centre Personnel's Signature

NRIC/FIN No.: Regina



On 09.02.2021 at about 17:00 hours I was travelling along Chang Charn Road x Entrance with no passenger onboard .

While I was travelling straight, suddenly veh B (SMW 8074J) dash out from the

entrance without giving way to me and collided into my taxi A - Whole Right Portion

after the impact it caused my taxi to mount the kerb on the left .

My taxi sustain damages on both Right and Left Portion .

I have company video and photo to support my claims .

After the accident I felt unwell at my back , hand and leg area . Doctor given me 5

days mc.

Veh B (SMW 8074J) - Mr Kwan Xiang Cong H/P: 9273 1200

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD

CO. REG. NO. 199303821R

Policyholder's Signature Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 10.02.2021 @ 10:30 hrs

Reporting Centre Personnel's Signature

NRIC/FIN No.: Regina