

MFORTDELGRO PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC8932Y

05/01/21

MAKE :

MODEL HYU- I40

CHIANG/ NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
1	REAR BUMPER COVER			\$1,106.00	del
2	REAR BUMPER BRACKET SIDE LH/RH		\$35.60	\$71.20	X ny
10	REAR BUMPER CLIPS		\$2.20	\$22.00	ner
1	REAR BUMPER REFLECTOR / RH			\$32.00	ny
1	REAR BUMPER REINFORCEMENT			\$428.40	Z un
1	REAR BUMPER UNDER COVER			\$228.00	X un.
1	BOOTLID MOULDING			\$85.00	ent
1	BOOTLID EMBLEM CRDI			\$52.40	ner
1	BOOTLID EMBLEM I40			\$52.40	ner
			1349.80	\$2,077.40	
			679.84	\$415.48	
				\$1,661.90	
		20.00%			
		DISCOUNTED TOTAL			
1	BOOTID COMFORT & TEL NUMBER STICKER	10.00%		\$60.00	ner
1	REAR BUMPER MAT			\$50.00	ner
1	REVERSE SENSOR	10.00%		\$135.70	nn
			226.13	\$226.13	
	Labour Charge		420	\$600.00	
	Panel Beating		500	\$600.00	
	Spray Painting Charge		30	\$60.00	
	Remove/refix reverse sensor		950	\$60.00	
	Check lighting			\$90.00	
	Tuff Kote			\$90.00	
			2255.97	\$1,410.00	
			1/5 \$1800		
			* 3 days		
				\$3,298.03	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

Tanphik 97495749
 WP 10/1/21 @ 11am
 HS Resing after repair
 2-3 days
 Tanphik @ Wharfedale.