

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	Document No.	: SQT21000530	Page	1
Registration No	: SLQ9855J	Date	: 10. Feb 2021		
Chassis No	: JHMRU1810GX202868	Customer No.	: WZI007		
Model	: HRV DX-SIN CVT YM 2016	Svc Advisor	: IVAN TEO BOON KIAT		
Owner's Name	: TAN BEE HUA	Engine No	: L15B4532868		
Ins Policy No.	:	Date Time	: 10. Feb 2021 4:25:43 PM		
Date of Accident	: 9/2/2021	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TAN BEE HUA OWNER INSURER: Aviva ACC DATE: 09/02/2021 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INTERNATIONAL TP VEH: SLP8742M						
68100-T7A-J20ZZ	TAIL GATE COMP	1	877.90	25	658.42	46.09	704.51
74440-T7A-003	WEATHERSTRIPTAILGATE	1	101.30	25	75.97	5.32	81.29
74800-T7Y-K01	LOCK ASSY, TAILGATE ASSY	1	167.40	25	125.55	8.79	134.34
75722-T7W-A01	EMBLEMRR.	1	14.60	25	10.95	0.77	11.72
75725-T8N-T00	EMBLEM, RR. I-VTEC	1	15.90	25	11.92	0.83	12.75
73214-T7J-H01	RUBBER CR. WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.70	25	6.52	0.46	6.98
73254-T7J-H01	RUBBER CL. WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	5.00	25	3.75	0.26	4.01
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
66100-T7A-300ZZ	PANEL COMPRR.	1	382.70	25	287.02	20.09	307.11
71501-T7B-000	FACE RR. BUMPER	1	798.10	25	598.57	41.90	640.47
04717-T7A-000ZZ	FACER. RR. BUMPER CORNER	1	96.50	25	72.37	5.07	77.44
04718-T7A-000ZZ	FACEL. RR. BUMPER CORNER	1	96.50	25	72.37	5.07	77.44
33505-T7A-J01	REFLECTOR ASSY. RR.	1	170.80	25	128.10	8.97	137.07
33555-T7A-J01	REFLECTOR ASSYL. RR.	1	170.80	25	128.10	8.97	137.07

Printed on 10/2/2021 4:39:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	Document No.	: SQT21000530	Page	2
Registration No	: SLQ9855J	Date	: 10. Feb 2021		
Chassis No	: JHMRU1810GX202868	Customer No.	: WZI007		
Model	: HRV DX-SIN CVT YM 2016	Svc Advisor	: IVAN TEO BOON KIAT		
Owner's Name	: TAN BEE HUA	Engine No	: L15B4532868		
Ins Policy No.	:	Date Time	: 10. Feb 2021 4:25:43 PM		
Date of Accident	: 9/2/2021	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71593-T7A-J00	SPACER,R.RR.BUMPER SIDE	1	17.30	25	12.97	0.91	13.88
71598-T7A-J00	SPACER,L.RR.BPR S	1	17.30	25	12.97	0.91	13.88
91505-TM8-003	CLIP,BUMPER	8	2.30	25	13.80	0.97	14.77
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
Sum Item					2717.84	190.27	2,908.11

BG02R	REPLACE RR. WINDSCREEN.(N)	1	650.00		650.00	45.50	695.50
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	280.00		280.00	19.60	299.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	280.00		280.00	19.60	299.60
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	560.00		560.00	39.20	599.20
BC01R	PERFORM SETTING ON MULTI VIEW CAMERAS & SMART	1	560.00		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	480.00		480.00	33.60	513.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00		650.00	45.50	695.50
BOJSE	BODY JOINT SEALANT.	1	120.00		120.00	8.40	128.40
BOBC	BODY UNDERSIDE COATING (N)	1	280.00		280.00	19.60	299.60
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN	1	3900.00		3900.00	273.00	4173.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	1	3640.00		3640.00	254.80	3894.80
Sum Labor					11500.00	805.00	12,305.00

Survey By	_____				
Date & Time	_____	Total Amount	14,217.84	995.27	15,213.11
Excess	_____	Total (Inclusive of GST)			15,213.11
Status	_____				
Signature	_____				

Printed on 10/2/2021 4:39:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.