

ASS. REC. BY:

REF:

CC4/GRB21002060/Riba3

778A

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / INV

To Inspect Vehicle No: SLQ 9855Jat Workshop m/s KAH MOTORof NO. 255, ALUMPA RDInsured: 111

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 69K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLQ9855JYr Regn: 2017, July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda HRV 1.5 DX CVT c.c. 1496Colour: Red A/C: Insured / Std / NI / NASp. Reading: 061403 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: HMRM18106X202868

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17R: 1.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 09/02/2021 D.O.I. 18/02/2021Survey held at KAH MOTORDes. of Damages: Frt / Rear / OIS / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Int - 30K

Date/Time, File Pass to?



: Prel. Report



: Final Report

1)

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / I.S.R. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SLQ9855J

Chassis No : JHMRU1810GX202868

Model : HRV DX-SIN CVT YM 2016

Owner's Name : TAN BEE HUA

Ins Policy No. :

Date of Accident : 9/2/2021

Document No. : SQT21000530

Date : 10. Feb 2021

Customer No. : WZI007

Svc Advisor : IVAN TEO BOON KIAT

Engine No : L15B4532868

Date | Time : 10. Feb 2021 4:25:43 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TAN BEE HUA OWNER INSURER: Aviva ACC DATE: 09/02/2021 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INTERNATIONAL TP VEH: SLP8742M						
68100-T7A-J20ZZ	TAIL GATE COMP <i>bt</i>	1	877.90 <i>855.70</i>	25	658.42 <i>641.77</i>	46.09	704.51
74440-T7A-003	WEATHERSTRIPTAILGATE <i>per</i>	1	101.30	25	75.97	5.32	81.29
74800-T7Y-K01	LOCK ASSY, TAILGATE ASSY <i>X suc</i>	1	167.40	25	125.55	8.79	134.34
75722-T7W-A01	EMBLEMRR. <i>per</i>	1	14.60	25	10.95	0.77	11.72
75725-T8N-T00	EMBLEM, RR. I-VTEC <i>per</i>	1	15.90	25	11.92	0.83	12.75
73214-T7J-H01	RUBBER CR. WINDSHIELD DAMPER <i>per</i>	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5 <i>per</i>	1	8.70	25	6.52	0.46	6.98
73254-T7J-H01	RUBBER CL. WINDSHIELD DAMPER <i>per</i>	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT <i>per</i>	1	5.00	25	3.75	0.26	4.01
91501-S70-003	FASTENER BW/SHIELD <i>per</i>	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B <i>per</i>	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD <i>per</i>	2	3.80	25	5.70	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>per</i>	2	60.00		120.00	8.40	128.40
66100-T7A-300ZZ	PANEL COMPR. <i>X suc</i>	1	382.70	25	287.02	20.09	307.11
71501-T7B-000	FACE RR. BUMPER <i>de</i>	1	798.10 <i>463.70</i>	25	598.57 <i>347.17</i>	41.90	640.47
04717-T7A-000ZZ	FACER. RR. BUMPER CORNER <i>X suc</i>	1	96.50	25	72.37	5.07	77.44
04718-T7A-000ZZ	FACEL. RR. BUMPER CORNER <i>X suc</i>	1	96.50	25	72.37	5.07	77.44
33505-T7A-J01	REFLECTOR ASSY. RR. <i>X suc</i>	1	170.80	25	128.10	8.97	137.07
33555-T7A-J01	REFLECTOR ASSY. LL. RR. <i>X suc</i>	1	170.80	25	128.10	8.97	137.07

Printed on 10/2/2021 4:39:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SLQ9855J

Chassis No : JHMRU1810GX202868

Model : HRV DX-SIN CVT YM 2016

Owner's Name : TAN BEE HUA

Ins Policy No. :

Date of Accident : 9/2/2021

Document No. : SQT21000530 **Page** 2

Date : 10. Feb 2021

Customer No. : WZI007

Svc Advisor : IVAN TEO BOON KIAT

Engine No : L15B4532868

Date | Time : 10. Feb 2021 4:25:43 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71593-T7A-J00	SPACER,R.RR.BUMPER SIDE <i>X 111</i>	1	17.30	25	12.97	0.91	13.88
71598-T7A-J00	SPACER,L.RR.BPR S <i>X 111</i>	1	17.30	25	12.97	0.91	13.88
91505-TM8-003	CLIP,BUMPER <i>new</i>	8	2.30	25	13.80	0.97	14.77
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>? X 300</i>	1	320.00		320.00	22.40	342.40
Sum Item					2717.84	190.27	2,908.11
BG02R	REPLACE RR. WINDSCREEN.(N)	1	650.00		650.00	45.50	695.50
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	280.00		280.00	19.60	299.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	280.00		280.00	19.60	299.60
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	560.00		560.00	39.20	599.20
BC01R	PERFORM SETTING ON MULTI VIEW CAMERAS & SMART	1	560.00		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	480.00		480.00	33.60	513.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00		650.00	45.50	695.50
BOJSE	BODY JOINT SEALANT.	1	120.00		120.00	8.40	128.40
BOBC	BODY UNDERSIDE COATING (N)	1	280.00		280.00	19.60	299.60
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN <i>eb 50</i>	1	3900.00		3900.00	273.00	4173.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P) <i>@ 520</i>	1	3640.00		3640.00	254.80	3894.80
Sum Labor					11500.00	805.00	12,305.00

Survey By

Date & Time

Excess

Status

Signature

Total Amount 14,217.84 995.27 15,213.11**Total (Inclusive of GST)** **15,213.11**

Printed on 10/2/2021 4:39:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.

Supplementary

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer: CU0017455 / INDIA
Chassis No: JHMRU1810GX202868
License No: SLQ9855J
Mileage: 61403
Engine No: L15B4532868

Document No: SVO21009630
Printed By: IVANTEO
Order Date: 18. February 2021
Order Time: 2:31:06 PM
Service Advisor: IVAN TEO BOON KIAT

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TAN BEE HUA OWNER INSURER: Aviva ACC DATE: 09/02/2021 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INTERNATIONAL TP VEH: SLP8742M SUPPLEMENTARY PART						
90676-SA7-003	GROMMET.SCREW.5 <i>an</i>	2.	2.40	25.	3.60	0.25	3.85
84640-T7A-J01ZA	LINING ASSYRR.PANEL <i>de</i>	1.	45.00	25.	33.75	2.36	36.11

GST Amount is calculated from individual line(s)

