

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV12557/ISMANI BIN KASIMI Reg No/Reg Date SMR574L / 17/12/201 Date In/Mileage / 33076 Chassis No GF7W0600199 Engine No 4J11AA2736 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	11/02/2021/ 11:30	BLE	261 / Edwin Caina	62875			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1800.00
RENEW FRT BUMPER								450
REPAIR / ALIGN RHF FENDER								350
E PNT98000								700.00
RESPRAY FRT BUMPER & RHF FENDER								30.00
M SUNDRY								30.00
RENEW RHF SPORT RIM & TRANSFER TYRE								120.00
A 54900099								120.00
CHECK WIRING ELECTRICAL SYSTEM								120.00
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								80.00
USING HI-SCAN PRO TEST								20.00
A WHEELALIGNMENTBP								
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY								
Sundries								
M FACE,FR BUMPER					1.00	851.00	23.00	655.27
M EXTENSION,FR BUMPER					1.00	509.00	23.00	391.93
M CLIP					10.00	3.00	23.00	23.10
M GARNISH,FR BUMPER,RH					1.00	48.00	23.00	36.96
M BRACKET,FR BUMPER SIDE,RH					1.00	18.00	23.00	13.86
M COVER,FR BUMPER					1.00	18.00	23.00	13.86
M GARNISH,FR BUMPER SIDE					1.00	48.00	23.00	36.96
M GARNISH,FR BUMPER SIDE					1.00	220.00	23.00	169.40
M GARNISH,FR BUMPER SIDE					1.00	112.00	23.00	86.24
M REINFORCEMENT,FR BUMPER					1.00	490.00	23.00	377.30
M BAR,FR BUMPER GUARD					1.00	130.00	23.00	100.10
M HEADLAMP ASSY,RH					1.00	1948	1938.00	1492.26
M LAMP ASSY,FOG,FR RH					1.00	348.00	23.00	267.96
M SHIELD,FR WHEELHOUSE,RH					1.00	164.00	23.00	126.28
M MOULDING,FR BUMPER,RH					1.00	116.00	23.00	89.32

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV12557/ISMANI BIN KASIMI Reg No/Reg Date SMR574L / 17/12/201 Date In/Mileage / 33076 Chassis No GF7W0600199 Engine No 4J11AA2736 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	11/02/2021/ 11:30	BLE	261 / Edwin Caina	62875			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	MOULDING,FR WHEEL ARCH,RH	X	NM		1.00	160.00	23.00	123.20
M	TANK,WINDSHIELD WASHER	X	NM		1.00	86.00	23.00	66.22
M	WHEEL,DISC RHF	X	NM		1.00	974.00	23.00	749.98

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate

SURVEYOR NAME : Steve CLKK
 SURVEYOR SIGNATURE : 15/2/21, 1.00pm
 DATE : 00-NM AL
 REMARKS : Excess - ?
P/P
By Bel Smy
3 days

Confirm & accepted by

Nett	7,982.77
7% GST on	7982.77
Total Payable	8,541.56

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.