



AIG - OD CLAIM
SURVEY: 15/02/21
LKK - STEVE

VEHICLE NO : SMR 574 L
MODEL : MIT/OUTLANDER 2.0
WIP : 62875

Material	: \$	<u>3,736.81</u>
Labour	: \$	<u>970.00</u>
Sub-Total	: \$	<u>4,706.81</u>
Less 2% Disc	: \$	<u>—</u>
Less Excess	: \$	<u>3,300.00</u>
Total	: \$	<u>1,406.81</u>
GST 7%	: \$	<u>98.48</u>
Grand Total	: \$	<u>1,505.29</u>
Finalise By/Date : <u>Army on 01/03/21</u>		

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 03 WORKING DAYS



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 16/02/2021	Cust No/Name	KCV12557/ISMANI BIN KASIMI
	Reg No/Reg Date	SMR574L / 17/12/2019
	Date In/Mileage	16/02/2021/ 33076
	Chassis/Package	GF7W0600199 /#
	Engine No	4J11AA2736
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	01/03/2021/ 12:44	BLE	884 / Lauro Songcuan	62875

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRONT BUMPER				450.00 ✓
E PNT98000 SPRAY PAINT FRONT BUMPER				350.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
X EXC EXCESS				-3300.00
X FACE,FR BUMPER ✓	1.00	851.00	23.00	655.27 ✓
X EXTENSION,FR BUMPER ✓	1.00	509.00	23.00	391.93 ✓
X CLIP ✓	10.00	3.00	23.00	23.10 ✓
X GARNISH,FR BUMPER,RH ✓	1.00	48.00	23.00	36.96 ✓
X BRACKET,FR BUMPER SIDE,RH ✓	1.00	18.00	23.00	13.86 ✓
X COVER,FR BUMPER ✓	1.00	361.00	23.00	277.97 ✓
X GARNISH,FR BUMPER SIDE ✓	1.00	48.00	23.00	36.96 ✓
X GARNISH,FR BUMPER SIDE ✓	1.00	220.00	23.00	169.40 ✓
X GARNISH,FR BUMPER SIDE ✓	1.00	112.00	23.00	86.24 ✓
X HEADLAMP ASSY,RH ✓	1.00	1948.00	23.00	1499.96 ✓
X LAMP ASSY,FOG,FR RH ✓	1.00	348.00	23.00	267.96 ✓
X SHIELD,FR WHEELHOUSE,RH ✓	1.00	164.00	23.00	126.28 ✓
X MOULDING,FR BUMPER,RH ✓	1.00	116.00	23.00	89.32 ✓
X CLIP,RR BUMPER	10.00	3.00	23.00	23.10 X
X CLIP,ENG ROOM COVER	10.00	2.00	23.00	15.40 X
X RIVET,FR BUMPER	6.00	5.00	23.00	23.10 X
Z TEXT AIG - OD CLAIM SURVEY: STEVE (LKK) 15.02.2021 DOA: 09.02.2021 (03 DAYS) Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Pro Forma

359.00

1,938.00

* - change price

Supp

Parts	3,736.81	Nett	1,406.81
Labour	950.00	7% GST on	98.48
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	1,505.29
Sundry/Others	-3,280.00		
Total(w/o GST)	1,406.81		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMR 574 L

<u>Materials</u>		<u>Cost \$</u>
1	Clip, RR Bumper (10 pcs)	30.00 / nec
2	Clip, Eng Room Cover (10 pcs)	20.00 / nec
3	Rivet, FR Bumper (6 pcs)	30.00 / nec
		<u>80.00</u>
23% Discount		<u>18.40</u>
		61.60
7% GST		4.31
Total		<u>65.91</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SMR574LWIP: 62875

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	CLIP. RR BUM (x10)	? / SUPP			MR 288150
2	CLIP. ENG. RB (x10)	? / SUPP			MR 488006
3	RIVET (x6)	? / SUPP			
4	RHF SPURT RM	? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: OUTLANDERSURVEYOR: STEVE

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	DBA-GF7W 2019MY

SMR574 L

Before use MUF3a ver unit to check all the good

2021.02.19

				</	

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
Power Gate	ETG_92080000		Non-equipped System or Communication Error		
KOS/MMO/Keyless	KOS_8A880020		No DTCs		
OSS	OSS_9588000B		No DTCs		
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error		
ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error		
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error		
EPB	EPB_4C080000	C2253	EPB SW malfunction	Stored	
Gateway	GW_C1000000		Non-equipped System or Communication Error		
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error		
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error		
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error		

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	DBA-GF7W 2019MY

SPR5541
 After using MUT-3x not wit to Ecu all Tsa bond
 Job Done

2021.02.19

All DTCs

2021.02.19

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
MPi/GDI/DIESEL	GAS_0E640000		No DTCs		
Auto Stop & Go (AS&G)	ASG_25080000		No DTCs		
AT/CVT/A-MT/TTC-SST	CVT_14080300		No DTCs		
AUTO CRUISE	GAS_0E640000		Non-target System		
4WS/Electric Power Steering	EPS_45880040		No DTCs		
ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCs		
SRS-AIR BAG	ORC_81047302		No DTCs		
Air Conditioner	AC_80080011		No DTCs		
ETACS	ETACS_83040801		No DTCs		
Meter	MTR_84084001		No DTCs		
Steering Angle Sensor	GS_SAS_47000100		Non-target System		
AND	AND_8C080002		Non-equipped System or Communication Error		
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error		
LIN	ETACS_83040801		Non-target System		
Power Gate	ETG_92080000		Non-equipped System or Communication Error		

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
KOS/IMMO/Keyless	KOS_8A880020		No DTCS		
OSS	OSS_9588000B		No DTCS		
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error		
ACC/FCM	ACCSCFM_4B080000		Non-equipped System or Communication Error		
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error		
EPB	EPB_4C080000		No DTCS		
Gateway	GW_C1000000		Non-equipped System or Communication Error		
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error		
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error		
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error		