

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

22-Feb-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6914 M

1 pc	Boot lid <i>X repair</i>	\$	1,119.00	
1 pc	Boot lid lock <i>- RM</i>	\$	99.00	✓
1 pc	Bootlid lock cable <i>X NN</i>	\$	35.00	
1 pc	Bootlid striker <i>X</i>	\$	21.00	
1 pc	Bootlid emblem <i>- NN</i>	\$	27.00	✓
1 pc	Bootlid CRDi <i>- NN</i>	\$	29.00	✓
1 pc	Boot lid rubber weatherstrip <i>- NN</i>	\$	96.00	✓
1 pc	Boot lid lower garnish <i>- CRA</i>	\$	290.00	✓
2 pcs	Bootlid hinges @ \$66.00 <i>X</i>	\$	132.00	
2 pcs	Rear license plate lamp @ \$30.00 <i>X</i>	\$	60.00	
2 pcs	Bootlid hinge torsion bar @ \$33.00 <i>X</i>	\$	66.00	
1 pc	Handle trunk lid hook <i>X</i>	\$	5.00	
1 pc	Bootlid inner trim <i>X</i>	\$	190.00	
1 pc	Bootlid o/s reflector <i>- car</i>	\$	350.00	✓
1 pc	End panel <i>X repair</i>	\$	250.00	
1 pc	End panel inner garnish <i>X NN</i>	\$	74.00	
1 pc	Rear bumper <i>- RL</i>	\$	696.00	✓
1 pc	Rear bumper lower cover <i>- cut</i>	\$	206.00	✓
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>X NN</i>	\$	58.00	
1 pc	Rear bumper inner sponge <i>✓ CRA</i>	\$	114.00	✓
1 pc	Rear bumper reinforcement <i>✓ CRA</i>	\$	607.00	✓
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>X NN</i>	\$	108.00	
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>X NN</i>	\$	36.00	
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>X NN</i>	\$	36.00	
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 <i>X NN</i>	\$	92.00	
		\$	4,796.00	2935
Less 10%		\$	479.60	
		\$	4,316.40	2641.5

22-Feb-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6914 M

S/NETT

1 set	Rear bumper clips	✓	\$	48.00	✓
1 set	End panel inner garnish clips	✓	\$	30.00	✓
1 set	Bootlid inner trim clips	X NN	\$	52.00	
1 set	Bootlid lower garnish clips	✓	\$	60.00	✓
1 set	Bootlid stickers	✓	\$	100.00	✓
1 set	Reverse sensor	X NN	\$	280.00	
1 pc	Rear bumper top protector	✓	\$	80.00	✓
1 pc	Rear no. plate with casing	X NN	\$	50.00	
	Sundry		\$	50.00	X NN
	To dismantle / replace reverse sensor to new bumper and reset to the same		\$	120.00	40
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00	60
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel. Including knock-out, straighten, repair, reshape and adjust of the rear panel		\$	1,400.00	400
	To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel,		\$	800.00	700
	To apply rustproofing on the repaired and replaced panels.		\$	120.00	X NN
			\$	7,686.40	

4159.5

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

-20%: 3300

4 Days.
Unpsum repair
After repair photos.
Gino Riani - 82880282
22/2/2021.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: