

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

25-Feb-21

SUPPLEMENTARY ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6914 M

1 pc	o/s tail lamp @\$421.00	✓ BR	\$	421.00
		Less 10%	\$	42.10
			\$	<u>378.90</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

***THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.***