

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CC6/AIG21002074/ABA3Q2  
**Date:** 09/09/2021

**REFERENCE**

|                              |                                      |                             |            |                        |
|------------------------------|--------------------------------------|-----------------------------|------------|------------------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 1900019066 |                        |
| <b>Claimant Vehicle No :</b> | SLZ6271R                             | <b>Insured Vehicle No :</b> | SLM39D     |                        |
| Date of Loss:                | 10/02/2021                           | Nature of Claim:            | TP         | Claim No: 5148946120SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SLZ6271R</b>                   |             |                   |
| Make & Model:               | NISSAN SYLPHY, 1.6 (A)            | Engine No:  | HR16926287C       |
| Reg. Date:                  | 12/05/2018 (Man. Year: 2018)      | Chassis No: | MNTBBAB17Z0031980 |
| Colour:                     | Grey                              | Odometer:   | 68990 km          |
| Engine Capacity:            | 1598 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 195/60 R16       | Rear Tyre Size:  | 195/60 R16       |
| Front Left Side:  | Bridgestone 6 mm | Rear Left Side:  | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 8,770.56          | 4,987.09          | 3,783.47          | 43.14         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 2,760.00          | 2,160.00          | 600.00            | 21.74         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>11,530.56</b>  | <b>7,147.09</b>   | <b>4,383.47</b>   | <b>38.02</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>5,700.00</b>   |                   |               |

|                                                  |                  |                 |                 |              |
|--------------------------------------------------|------------------|-----------------|-----------------|--------------|
| (S\$)                                            | 11,530.56        | 5,700.00        | 5,830.56        | 50.57        |
| <b>+ GST 7.00/7.00% (S\$)</b>                    | 807.14           | 399.00          | 408.14          | 50.57        |
| <b>Nett Amount (S\$)</b>                         | <b>12,337.70</b> | <b>6,099.00</b> | <b>6,238.70</b> | <b>50.57</b> |
| <b>+ Car Rental (12.0 x S\$100.00/day) (S\$)</b> |                  | 1,200.00        |                 |              |
| <b>Nett Liability (S\$)</b>                      |                  | <b>7,299.00</b> |                 |              |

INSPECTION

Date of Assignment: 11/02/2021

Date Inspected: 11/02/2021

Estimated Period of Repair: 7.0 days

Inspected At: J-mart Motor Pte Ltd (HQ)  
Blk 5 Defu Lane 10, #01-578  
Singapore 539186

**Adjuster:** ADRIAN LING**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                       | Condition     | Repairer's  | Amount     |
|-----|-----|----------|-----------------------------------|---------------|-------------|------------|
| 1   | 1   |          | *FRT BUMPER                       | Torn          | 761.00 FN   | *761.00 FN |
| 2   | 1   |          | *FRT BUMPER RH RETAINER           | Cracked       | 24.10 FN    | *24.10 FN  |
| 3   | 1   |          | *RH HEADLAMP                      | Cracked       | 738.00 FN   | *738.00 FN |
| 4   | 1   |          | *FRT RH FENDER                    | Dented        | 555.00 FN   | *555.00 FN |
| 5   | 1   |          | *FRT RH FENDER SIGNAL LAMP        | Not Necessary | 66.00 FN    | *- FN      |
| 6   | 1   |          | *FRT RH FENDER INNER SHIELD       | Deformed      | 117.00 FN   | *117.00 FN |
| 7   | 10  |          | *FRT RH FENDER INNER SHIELD CLIPS | Necessary     | 51.00 FN    | *30.00 FN  |
| 8   | 1   |          | *FRT RH RIM                       | Cut           | 1,004.40 FS | *500.00 FS |
| 9   | 1   |          | *FRT RH DOOR                      | Dented        | 918.00 FN   | *918.00 FN |
| 10  | 2   |          | *FRT RH DOOR STICKER              | Necessary     | 72.00 FN    | *72.00 FN  |
| 11  | 1   |          | *FRT RH DOOR LOCK                 | Damaged       | 225.00 FN   | *225.00 FN |
| 12  | 1   |          | *FRT RH DOOR W/STRIP              | Not Necessary | 112.00 FN   | *- FN      |
| 13  | 1   |          | *REAR RH DOOR                     | Dented        | 918.00 FN   | *918.00 FN |
| 14  | 2   |          | *REAR RH DOOR STICKER             | Necessary     | 72.00 FN    | *72.00 FN  |
| 15  | 1   |          | *REAR RH FENDER                   | Repair        | 1,456.30 FN | *- FN      |
| 16  | 1   |          | *REAR BUMPER                      | Repair        | 761.00 FN   | *- FN      |
| 17  | 1   |          | *REAR RH RIM                      | Cut           | 1,004.40 FS | *500.00 FS |
| 18  | 1   |          | *FRT RH TYRE                      | Not Necessary | 300.00 FS   | *- FS      |
| 19  | 1   |          | *REAR RH TYRE                     | Not Necessary | 300.00 FS   | *- FS      |

F=Franchise part. S=SpcNett. N=NettItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>9,455.20</b> | <b>5,430.10</b> |
| <b>- Nett Item Discount on N Items 10.00/10.00% (\$\$)</b> | 684.64          | 443.01          |
| <b>Total Parts (\$\$)</b>                                  | <b>8,770.56</b> | <b>4,987.09</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars            | Lab.Type | Repairer's      | Amount          |
|---------------------------------|------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>      |                        |          |                 |                 |
| 1                               | PANEL BEATING          | New      | 1,000.00        | 700.00          |
| 2                               | SPRAY PAINTING         | New      | 1,600.00        | 1,300.00        |
| 3                               | TRANSFER 2 DOORS PARTS | New      | 80.00           | 80.00           |
| 4                               | ALIGNMENT              | New      | 80.00           | 80.00           |
| <b>Gross Labour Cost (\$\$)</b> |                        |          | <b>2,760.00</b> | <b>2,160.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >