

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

10-Feb-21

Our ref : TP/4947/21

Tang wai Seng Derrick

TPA 16.

Jasper

RE : estimate cost for vehicle no : SLZ 6271R

1 pc	frt bumper	tooth	\$	761.00	nett	2
1 pc	frt bumper rh retainer	united		24.10		2
1 pc	rh headlamp	united		738.00		2
1 pc	frt rh fender	dent		555.00		✓
1 pc	frt rh fender signal lamp	new		66.00		+
1 pc	frt rh fender inner shield	dent		117.00		✓
10 pcs	frt rh fender inner shield clips	in		51.00		30
1 pc	frt rh rim	at		1,116.00		500(SN)
1 pc	frt rh door	dent		918.00		✓
2 pcs	frt rh door sticker	new		72.00		✓
1 pc	frt rh door lock	dent	4430.10	225.00		2
1 pc	frt rh door w/strip	new		112.00		+
1 pc	rear rh door	dent		918.00		✓
2 pcs	rear rh door sticker	new	3987.09	72.00		✓
1 pc	rear rh fender	Repair		1,456.30		+
1 pc	rear bumper		S.N: 1000	761.00		+
1 pc	rear rh rim	at		1,116.00		500(SN)
				9,078.40		
			less 10%	907.84		
				8,170.56		
1 pc	frt rh tyre	3 new		300.00	snett	+
1 pc	rear rh tyre			300.00		+
	Panel beating.			1000.00		700
	Spray painting.		2160	1600.00		1300
	Transfer 2 doors parts.			80.00		✓
	Alignment.			80.00		✓
				11530.56		
			Plus 7% GST	807.13		
				12337.69		

SD : twelve thousand three hundred thirty seven & cents sixty-nine only.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 7147.09 Admin Lj
H/S: 5.7K H/S 11/02/21
07 Dyr