



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21002082/R1Kqd3q2	
			Date: 19/03/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLA 9090H	Veh. Inspected	SHC 611B
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2100484/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	15/02/2021
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI IONIQ 1.6 DCT	c.c	1580
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	KMHC851CVKU141370	Colour	YELLOW
	Odometer	160039 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	TAKSING	6 mm
	L/H Front Tyre	195/65 R15	TAKSING	6 mm
	R/H Rear Tyre	195/65 R15	TAKSING	6 mm
	L/H Rear Tyre	195/65 R15	TAKSING	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/02/2021	Inspection Date	15/02/2021
	Survey held at	31 CORPORATION ROAD		
	Repairer	DING AUTO PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	