

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0129/2021/KS
DATE : 11-Feb-21
WIP : 15195

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 11/2/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian,

10 days - ok - Jy - 02 Jun 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : DEBY SAROJIUY D/O P K KRISHNAN
ADDRESS : 27A JALAN TUA KONG
SINGAPORE 457230
TELEPHONE : HP +65 96745905
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070030542
VEHICLE NO : **SKN 2975 U**
MODEL CODE : A3 SEDAN 1.4 TFSI
MODEL YEAR : 29/05/2014
ENGINE NO : CXS 083572
CHASSIS NO : WAUZZZ8V1E1032598
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Feb-21
PLACE OF ACCIDENT : 1 WALLICH ST, SINGAPORE 078881
IN FRONT FO GUOCO TOWER

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SKN 2975 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	280.00	
2	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	1,200.00	
3	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODUEL	S/N \$	350.00	\$ 250.00
4	TO REMOVE AND TRANSFER RHS FRONT DOOR AND REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	S/N \$	700.00	\$ 560.00
5	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY.	S/N \$	1,800.00	\$ 1,800.00
6	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER.	S/N \$	800.00	
TOTAL LABOUR CHARGES		:	\$ 22,934.00	\$ 2,610.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SKN 2975 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
				\$ 2,610.00
7	TO PUT VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR	S/N \$	2,400.00	
8	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS FRONT FENDER TOP SUPPORT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	7,700.00	\$ 2,000.00
9	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT DOOR, RHS FRONT FENDER TOP SUPPORT, RHS UPPER A-PILLAR, RHS REAR DOOR, DOOR HANDLES AND RHS REAR FENDER.	\$	6,800.00	\$ 3,700.00
10	TO RENEW RHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT TEST.	S/N \$	520.00	\$ 280.00
11	TO CARRY OUT OUT PRE/POST DIAGNOSTIC CHECK	S/N \$	384.00	\$ 192.00
SUB-TOTAL LABOUR CHARGES		:	\$ 17,804.00	\$ 8,782.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6386 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKN 2975 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,233.00	\$ 1,786.40
2	FRONT BUMPER FIXING PARTS	1	\$ 187.00	
3	FRONT BUMPER COVER TRIM RH	1	\$ 163.00	
4	FRONT BUMPER CLOSING ELEMENT LOWER CENTRE	1	\$ 163.00	
5	FRONT BUMPER PULL STRAP LOWER	1	\$ 206.00	
6	FRONT BUMPER GUIDE SECTION	1	\$ 39.00	\$ 30.48
7	FRONT BUMPER AIR GUIDE GRILLE RH	1	\$ 109.00	\$ 87.20
8	RADIATOR GRILLE	1	\$ 691.00	
9	FRONT BUMPER TOP COVER	1	\$ 98.00	
10	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 795.00	
11	REINFORCEMENT BEAM FOAM FILLER PIECE	1	\$ 137.00	
12	REINFORCEMENT BEAM COVER	1	\$ 56.00	
13	"CAUTION" STICKER	1	\$ 14.00	
14	AIR COND STICKER	1	\$ 8.00	
15	FRONT FENDER RH	1	\$ 851.00	\$ 680.40
16	FRONT FENDER ATTACHMENTS PARTS RH	1	\$ 39.00	
17	FRONT FENDER BRACKET RH	1	\$ 39.00	\$ 30.72
18	FRONT FENDER BRACKET RH	1	\$ 28.00	\$ 21.84
19	FRONT FENDER BRACE RH	1	\$ 96.00	\$ 76.48
20	FRONT FENDER CLOSING ELEMENT RH	1	\$ 33.00	\$ 26.16
SUB TOTAL SPARE PARTS		:	\$ 5,985.00	\$ 2,739.68

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKN 2975 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 2,739.68
21	FRONT FENDER INSULATION RH	1	\$ 43.00	
22	FRONT WHEEL HOUSING LINER RH	1	\$ 169.00	\$ 134.80
23	WHEEL HOUSING LINER ATTACHMENT PARTS RH	1	\$ 89.00	
24	FRONT FENDER CLOSING ELEMENT RH	1	\$ 74.00	
25	A-PILLAR CONNECTING PLATE HR	1	\$ 329.00	
26	HEADLIGHT RH	1	\$ 2,641.00	\$ 2,112.80
27	HEADLIGHT CONTROL UNIT RH	1	\$ 1,116.00	
28	HEADLIGHT POWER MODULE RH	1	\$ 556.00	
29	HEADLIGHT GAS DISCHARGE RH	1	\$ 416.00	
30	HEADLIGHT HOSE RH	1	\$ 52.00	
31	HEADLIGHT WASHER LIFT CYLINDER RH	1	\$ 193.00	
32	HEADLIGHT WASHER LIFT CYLINDER HOSE RH	1	\$ 182.00	
33	LOCK CARRIER	1	\$ 727.00	
34	RADIATOR COOLANT	1	\$ 95.00	
35	RADIATOR AIR GUIDE RH	1	\$ 25.00	
36	RADIATOR RH OUTER SEAL	1	\$ 8.00	
37	FRONT DOOR RH	1	\$ 3,039.00	\$ 2,431.20
38	FRONT DOOR OUTER SEAL RH	1	\$ 161.00	\$ 128.40
39	BONDING AGENT	1	\$ 49.00	
40	CLEANING SOLUTION	1	\$ 68.00	
SUB TOTAL SPARE PARTS		:	\$ 16,017.00	\$ 7,546.88

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKN 2975 U

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	7,546.88
41	FRONT DOOR ATTACHMENT PARTS RH	1	\$ 241.00		
42	FRONT DOOR CATCH RH	1	\$ 105.00		
43	FRONT WING MIRROR MOUNTING RH	1	\$ 1,024.00		
44	FRONT WING MIRROR CAP RH	1	\$ 169.00		
45	FRONT WINDOW SLOT SEAL RH	1	\$ 309.00		
46	FRONT WINDOW GUIDE RH	1	\$ 257.00		
47	FRONT DOOR HANDLE RH	1	\$ 374.00		
48	FRONT DOOR HANDLE CAP RH	1	\$ 117.00		
49	FRONT DATA PLATE FOR TYRE PRESSURE	1	\$ 30.00		
50	REAR DOOR RH	1	\$ 3,039.00	\$	2,431.20
51	REAR DOOR OUTER SEAL RH	1	\$ 161.00	\$	128.40
52	BONDING AGENT	1	\$ 49.00		
53	CLEANING SOLUTION	1	\$ 68.00		
54	APPLICATOR	1	\$ 8.00		
55	REAR DOOR ATTACHMENT PARTS RH	1	\$ 129.00		
56	REAR DOOR CATCH RH	1	\$ 94.00		
57	FRONT ALUMINIUM RIM RH	1	\$ 1,166.00	\$	932.80
58	FRONT LOWER ARM RH	1	\$ 373.00	\$	298.00
59	FRONT WHEEL BEARING HOUSING RH	1	\$ 579.00	\$	462.80
60	FRONT WHEELHUB WITH BEARING RH	1	\$ 478.00	\$	382.40
TOTAL SPARE PARTS		:	\$ 14,755.00	\$	12,182.48

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKN 2975 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 12,182.48
61	FRONT WHEEL GUIDE JOINT RH	1	\$ 124.00	\$ 98.80
62	FRONT COUPLING ROD	1	\$ 98.00	
63	FRONT GAS SHOCK ABSORBER RH	1	\$ 259.00	\$ 206.80
64	ARYCLIX SEALANT	S/N	\$ 180.00	
65	CAVITY WAX	S/N	\$ 140.00	
66	STONE CHIP	S/N	\$ 180.00	
67	METAL FILLER POWDER	S/N	\$ 280.00	
68	FRONT NO PLATE	S/N	\$ 60.00	
69	SUNDRIES		\$ 400.00	\$ 172.00
TOTAL SPARE PARTS			: \$ 38,478.00	\$ 12,660.08
TOTAL LABOUR CHARGES			: \$ 22,934.00	\$ 8,782.00
GRAND TOTAL			: \$ 61,412.00	\$ 21,442.08

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-31/03/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LABOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT