

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG21002094/R1BS3Q2

**Date:** 14/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070105863

**Claimant**  
**Vehicle No :** SMD3800M **Insured Vehicle No :** SMT7682B

Date of Loss: 09/02/2021 Nature of Claim: TP Claim No: 2269897760SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                       |             |                   |
|-----------------------------|---------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SMD3800M</b>                       |             |                   |
| Make & Model:               | VOLKSWAGEN SHARAN, 2.0 TSI 7N24MY (A) | Engine No:  | DED024908         |
| Reg. Date:                  | 16/08/2018 (Man. Year: 2018)          | Chassis No: | WVWZZZ7NZJV026788 |
| Colour:                     | Brown                                 | Odometer:   | 58164 km          |
| Engine Capacity:            | 1984 cc                               |             |                   |
| Market Value/New Car Price: | N/A                                   |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b>     |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 225/50 R17   | Rear Tyre Size:  | 225/50 R17   |
| Front Left Side:  | Pirelli 6 mm | Rear Left Side:  | Pirelli 6 mm |
| Front Right Side: | Pirelli 6 mm | Rear Right Side: | Pirelli 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                             | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts   | 3,489.58          | 3,489.58          | 0.00              | 0.00          |
| Miscellaneous Items                               | 0.00              | 0.00              | 0.00              |               |
| Labour  | 6,520.00          | 2,820.00          | 3,700.00          | 56.75         |
| Paintwork Labour                                  | 0.00              | 0.00              | 0.00              |               |
| Towing  | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (\$\$)</b>                         | <b>10,009.58</b>  | <b>6,309.58</b>   | <b>3,700.00</b>   | <b>36.96</b>  |
| <b>+ GST 7.00/7.00% (\$\$)</b>                    | 700.67            | 441.67            | 259.00            | 36.96         |
| <b>Nett Amount (\$\$)</b>                         | <b>10,710.25</b>  | <b>6,751.25</b>   | <b>3,959.00</b>   | <b>36.96</b>  |
| <b>+ Loss of Use (3.0 x S\$120.00/day) (\$\$)</b> |                   | 360.00            |                   |               |
| <b>+ Doc/Search Fee (\$\$)</b>                    |                   | 2.00              |                   |               |
| <b>Nett Liability (\$\$)</b>                      |                   | <b>7,113.25</b>   |                   |               |

### INSPECTION

Date of Assignment: 16/02/2021

Date Inspected: 16/02/2021 Inspected At: Volkswagen Centre Singapore (HQ)  
247 Alexandra Road  
Singapore 159934

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD RASUL

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars  | Condition                | Repairer's      | Amount          |
|-----|-----|----------|--|--------------------------|-----------------|-----------------|
| 1   | 1   |          | *SLIDING DOOR                                      | Buckled                  | 2,504.54 FS     | *2,504.54 FS    |
| 2   | 2   |          | *CLIP  | Necessary                | 1.94 FS         | *1.94 FS        |
| 3   | 1   |          | *SOUND ABSORBER LAMINATED DOOR INSULATOR           | Necessary                | 43.65 FS        | *43.65 FS       |
| 4   | 1   |          | *SEAL FOR SLIDING DOOR WIT                         | Necessary                | 582.79 FS       | *582.79 FS      |
| 5   | 1   |          | *COVER FOR DOOR PRIMED RHS SLIDING DOOR LOWER MLDG | Necessary                | 343.62 FS       | *343.62 FS      |
| 6   | 8   |          | *GROMMET   | Necessary                | 13.04 FS        | *13.04 FS       |
|     |     |          |  | <b>Total Parts (S\$)</b> | <b>3,489.58</b> | <b>3,489.58</b> |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                         | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>      |                                     |          |                 |                 |
| 1                               | CHECK SHOCK CIRCUIT /HARNESS REPAIR | New      | 280.00          | 280.00          |
| 2                               | DIAGNOSTIC AND PROGRAMMING          | New      | 480.00          | 480.00          |
| 3                               | LABOUR                              | New      | 2,520.00        | 840.00          |
| 4                               | SPRAY PAINT                         | New      | 2,400.00        | 800.00          |
| 5                               | TRANSFER DOOR MECHANISM             | New      | 840.00          | 420.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                     |          | <b>6,520.00</b> | <b>2,820.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >