



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref : SNM21D200874

Date: 09th Jan 2023

Our Ref : CC3/CTI21002113/Tpa3q2

M/s CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD #16-00

SPRINGLEAF TOWER

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SHA 1798A
INSURED VEHICLE SLG 6983UACCIDENT ON 27/01/2021**

Instruction was received to inspect the vehicle Reg. No. SHA 1798A. The inspection was conducted on 10/02/2021 at the premises of M/s Comfortdelgro Engineering Pte Ltd, 59 Loyang Drive, Singapore 508969.

The following vehicle information was recorded:

Registration Number	: SHA 1798A
Make/Model	: TOYOTA PRIUS HYBRID 1.8 CVT
Year of Registration	: 2017
Body Colour	: BLUE
Chassis Number	: JTDKB3FU103563524
Engine Capacity	: 1798 cc
Speedometer Reading	: 0 km

The vehicle sustained damages at the front portion & undercarriage. The chassis frame affected due to collision. (Details see photographs enclosed).



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Book Value	S\$ 51,618.78
Less: LTA Reimbursement Value (RV)	(S\$ 24,180.00)
Less: Wreck Value	S\$ 1,200.00
Nett Liability	<u>S\$ 23,238.78</u>

Vehicle Inspected By:

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor

K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MII(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

