ASS	SIGNMENT
rom: Date:	Veh No: SHA1798 A. Yr Regn: 2017, Aug
stimated Cost;	Type: M.Car / M.Cycle / Bus / Van / Lorry / Tax) / Prime Mover /
DITPI WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
	Make: Toyota Priks. c.c 1798
o Inspect Vehicle No:	Colour Rue A/C: Insured / Std / NI / NA
Workshop m/s	() () () () () () () () () () () () () (
	- Op. rodding
sured:	Eng/No: 5TDKB3F4/03:563524
olicy No.	
laims No.	Gen. Cond: Good / Fair / Poor / Burnt
um Insured: Excess:	Steering: Inorder/I Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
fake of Veh:	Modi: Nil / SiRim / STD A/Rim or
- HAA	Tyre Size: F: (95/65/(1)
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	20,001,2,1101,1,01,101
repair at the time of Inspection.	TOYO/YOKO or Nextake
Bal. or Market Value:	Front Rear
DAC Accident Rport: Consistent? : Yes or No	R/Bal, 6 mm , R/Bal. 6 mm
GIA / PR Seen: Consistent? ; Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs:days Res.: Yes or No	D.O.A. D.O.I. 10/2/21
Lum Sum: % 3 Val.: Yes or No	Survey held at Comfut Loyang
CA / REV / REP. / 24 HRS W/	Des. of Damages (Fit) Rear / O/S / N/S / U/O / Rooftop or
	The U/C / Chassis frame / Body Structure affected due to collision
Date.	The U/C / Chassis frame / Body Structure affected due to common
Date / Time Action / Instruction Not Economical to 1	Repair , Total loss.
Not 2 constant cert is	7
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
; Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add	Fee: : Site Insp (\$)s+Rssi
	: Interview (\$) Photos
ReportFormet:	: Tech. Invs (\$) Others
programming transfer from the contract of the contract of	144 1 16
Lump Sum / LB.E. (*)	:Weelfend (\$)

COMFORT DELGRO ENGINEERING PTE LTD

Updated 11 Feb 2020

REPAIR ESTIMATE

DATE:

10-Feb-21

MODEL:

Toyota Prius (Front)

VEHICLE NO.: SHA1798A

INSURANCE: CHINA TAIPING

MVA: JUMANI

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Bonnet			\$950.50
	Insulator, Hood			\$398.10
	Insulator Clips			\$3.60
	Bonnet Rubber			\$35.50
	Bonnet Cable			\$53.20
	Bonnet Hinge (LH/RH)		\$57.70	\$115.40
	Bonnete Lock			\$132.60
	Catch, Hood Auxiliary Hook			\$8.60
	RADIATOR GRILLE EMBLEM			\$438.00
	Radiator Grille Emblem			\$88.00
	Lamp Set, Stop Center			\$231.30
	Front Cabin Lamp			\$506.40
	Bulb, FOG Lamp			\$34.00
	Len, Map Lamp, No. 1			\$243.10
	Nen, Map Lamp, No. 2			\$106.50
	Lens, License Plate Lamp			\$35.70
	Lens & Body Fr Turn (LH/RH)		\$511.80	\$1,023.60
	Front Bumper Cover		30000	\$499.90
	Front Bumper Reinforcement			\$696.40
	Front Bumper Reinforcement Absorber			\$115.70
	Front Bumper Lower Reinforcement Bracket		\$165.00	\$330.00
	Front Bumper Sponge			\$78.80
	Front Bumper Centre Grille			\$301.90
	Front Bumper Lower Grille			\$166.90
	Lamp Assy, FOG (LH/RH)		\$920.00	\$1,840.00
	Front No. Plate			\$25.00
	Front No. Plate Trim Cover			\$30.00
	Front No. Plate Garnish			\$99.00
	Front Bumper Logo			\$87.10
	Front Bumper Clips			\$22.00
	Front Bumper Side Retainer		\$77.00	\$154.00
	Front Lower Crossmember			\$357.70
	Front Radiator Lower Support Panel			\$357.70
	Front Under Cover			\$180.80
	Engine Under Cover (RR)			\$457.40
	Front Bumper Top Garnish			\$225.40
	Cover, Front Bumper Hole (LH/RH)		\$28.38	\$56.76
	Reinforcement, Front Bumper Lower			\$236.10
	Bracket, Front Bumper Extension Mounting			\$110.40
	Support Fr Bumper, RH			\$81.70
	Support Fr Bumper, LH			\$81.70
	Front Bumper Centre Frame			\$236.90

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Bracket, Front Bumper Side, RH			\$82.30	de
	Bracket, Front Bumper Side, LH			\$82.30	de
	Bracket, Front Bumper Mounting			\$29.60	de
	Bracket, Front Bumper Mounting, No. 2			\$97.80	20/
	Absorber, Front Bumper, Lower			\$127.70	de -
	Unit Assy, Headlamp, RH (LED)			\$3,455.00	an
	Unit Assy, Headlamp, LH (LED)			\$3,455.00	w-
	Head Lamp Panel (RH)			\$240.10	ht-
	Head Lamp Panel (LH)			\$240.10	69-
	ke and keep to			\$364.98	de-
	Top Panel Centre			\$145.90	in's
	Top Panel Side			\$145.90	wis -
	Top Panel Side			\$75.20	6T-
	Brace Panel			400000000000000000000000000000000000000	lice
	Bracket, Headlamp Mounting, RH			\$25.50	dis
	Bracket, Headlamp Mounting, LH			\$25.50	Only -
	Headlamp Bulb	}		\$34.30	L+/
	Radiator Assy			\$1,841.80	in
	Radiator Fan Motor Assy			\$661.30)-1-
	*Radiator Top Hose, LH			\$43.03	. /
	*Radiator Top Hose, RH			\$42.60	7.
	Radiator Spare Tank			\$125.80	de
	Radiator Bottom Mounting			\$27.50	ht-
	Stay, Radiator Support, RH			\$65.70	dis-
	Stay, Radiator Support, LH			\$65.70	dist
	Radiator Fan Blade (RH)			\$233.10	7
	Radiator Fan Blade (LH)			\$233.10	7
	Radiator Fan Motor (RH)			\$543.70	2
	Radiator Fan Motor (LH)			\$543.70	-
	Support Sub-Assy, Radiator, LH				
	Deflector, Radiator Side, RH			\$83.50	dis-
	Deflector, Radiator Side, LH			\$83.50	dis-
	Cover, Radiator Support Opening			\$225.40	dis
	Reserve Tank Assy, Radiator w/o Cap			\$395.30	dis -
	Pipe, Radiator			\$126.50	?
	Button Assy, Horn			\$2,377.30	?
	Horn Wire			\$6,079.70	
	Horn (1 PC)			\$112.71	
	Airflow Sensor			\$517.80	7
	Cleaner Assy, Air			\$970.30	cres
	Air Cleaner Top Cover			\$446.50	aco
	Air Cleaner Bottom Cover			\$947.80	ar -
	Air Cleaner Hose			\$62.12	dis-
	AIR DUCT CENTRE			\$129.40	2
	- Control of the Cont			\$199.20	á
	Inlet Assy, Air Cleaner			\$94.03	
	Air Duct Centre			\$867.70	5
	Aircon Control Assy				7
	Panel Assy, Instrument Cluster Finish			\$1,536.20	0
	Valve, Cooler Expansion			\$275.80	2
	Thermistor, Cooler, No. 1			\$68.00	7
	Tube & Accessory Assy, Airconditioner	-		\$631.90	2
	Evaporator Sub-Assy, Cooler, No. 1			\$1,229.30	
	Compressor Assy, W/Motor	ı	J	\$2,924.20	Pa 2 o

147-85-14 Tanasa Deline (Franch)

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Condenser Assy, W/Receiver			\$1,336.60	st-
	Aircon Discharge Hose	1		\$386.90	
	Aircon Liquid Hose & Pipe			\$580.45	1
	Aircon Hose Suction			\$548.50	
	Aircon Blower Assy		1 1	\$1,036.00	lis
	Fender Sub-Assy, Front RH			\$945.30	4-
	Fender Sub-Assy, Front LH			\$945.30	7)-
	Front Housing Assy, LH			\$958.30 6	ul
	Front Housing Assy, RH			\$958.30	9
	Front Fender Shield			\$198.50	in
	Front Fender Shield			\$198.50	m.
	SCAPARIO CONTRACTOR AND			\$38.00	e.
	Front Fender Shield Clip				491
	Front Fender Hybrid Emblem, LH			\$86.50	10
	Front Fender Hybrid Emblem, RH		\$100.00	405.000.000.000.000.000.000	lott
	Front Fender Advertisement Logo (LH/RH)		\$100.00	\$200.00 N	611
	Bracket, Front Side Panel, RH			\$44.50	17.7.
	Bracket, Front Side Panel, LH			\$44.50 \$47.20	7
	Extension, Front Fender, RH	1		124274-0000-000	bt-
	Extension, Front Fender, LH			VII.20	
	Protector, Front Fender Upper, LH			\$46.10	-
	Protector, Front Fender Side Panel, RH			\$113.90	115
	Seal, Front Fender To Cowl Side, RH		1 1	\$15.20	7
	Gusset, Front Fender Apron, Lower RH			\$34.90	7
	Gusset, Front Fender Apron, Lower LH		1 1	\$34.90	,
	Extension, Front Fender Apron, Front RH			\$23.20	7
	Member, Front Apron To Cowl Side, Upper RH			\$138.40	10
	Member, Front Apron To Cowl Side, Upper LH			\$138.40	2
	Front Apron To Cowl Side, Lower Frt RH			\$82.30	1 8
	Front Apron To Cowl Side, Lower Frt LH		1	\$82.30	19-
	Tray, Battery			\$42.80	2
	Clamp, Battery	1		\$58.00	4
	Front Door Safety Belt (LH/RH)			\$846.10	W
	Rear Door Safety Belt (LH/RH)		1 1	\$838.00	uj
	Rear Door Safety Belt, Outer Centre		1 1	\$526.00	í
	Front Cushion Seat			\$1,180.00	7-
	Front Cushion Seat Adjuster (LH)			\$1,450.40	4
	Front Cushion Seat Adjuster (RH)			\$1,530.80	19
	Front Cushion Seat Cushion Pad (RH)		1 1	\$526.80	n
	Front Cushion Seat Cushion Pad (LH)			\$850.40	m-
	Front Cushion Seat Cushion Cover (LH/RH)		\$1,580.00	\$3,160.00	h
	Front Cushion Seat Back Pad (LH/RH)		\$520.30	\$1,040.60	1
	Front Cushion Seat Back Cover (LH/RH)		\$2,940.20	\$5,880.40	`
	Front Cushion Seat Back Frame (LH/RH)		\$780.80	\$1,561.60	
	Mirror Assy, Outer Rear View, RH			\$1,390.10	44
	Cover, Outer Mirror, RH			\$141.90	ris
	Outer Mirror, RH			\$212.80	111
	Front Windscreen Glass			\$1,627.30	309
	Front Windscreen Glass Moulding				rei
	Front Windscreen Glass Pillar				Ry
	Front Windscreen Sealant			\$46.00 N	ett
	Wiper Motor Frt			\$784.10	7
	Arm, Front Wiper, RH			\$180.10	La

\$180.10 | NOS ! SN 246 15 725.50 Pg 3 of 9

ART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
Bli	lade, Front Wiper, RH			\$147.90
Ar	rm, Front Wiper, LH			\$180.10 at
Bla	lade, Front Wiper, LH			\$147.90 01
	/iper Top Garnish			\$668.32 4
10000	/iper Spare Tank			\$183.75
	/iper Spare Tank Motor			\$242.70
	/iper Spare Tank Float (Neck)			\$135.00
1	use Box Top Cover			\$82.30
	use Box Bottom Cover			\$71.00
1	use Box Assy			\$131.80
	and the second of the second o			\$637.50
	ront Suspension Lower Arm (RH)			1 .
	ront Suspension Lower Arm (LH)			\$637.50 64
100	ront Shock Absorber (LH)			\$401.80
	ront Shock Absorber (RH)		0400.00	\$401.80 by T \$392.40 LH b+
Page 1	bsprber Top Mounting (LH/RH)		\$196.20	
	ront Drive Shaft (LH)			\$1,764.00
Fro	ront Drive Shaft (RH)			\$1,764.00
Ra	ack & Pinion Assy			\$1,634.90
Ва	ar, Stabilizer			\$360.00
Lin	nk Assy, Front Stabilizer, LH			\$199.00
Kn	nuckle, Steering, RH			\$580.80
Kn	nuckle, Steering, LH			\$580.80 107
Joi	oint Assy, Lower Ball, Front RH			\$199.98
Dis	sc, Front			\$1,570.00
Hu	ub Sub-Assy, Front Axle, RH/LH			\$549.70
En	nd Sub-Assy, Tie Rod, RH			\$159.30
En	nd Sub-Assy, Tie Rod, LH			\$159.30
En	ngine Under Cover			\$457.20
En	ngine Cross Member			\$2,531.70
Party and	t ABS Wire			\$455.10
1000000	t ABS Sensor			\$222.10
	ont Chassis Member (LH)			\$2,035.10
	ont Chassis Member (RH)			\$2,035.10 RY
	ngine Mounting (LH/RH)			\$386.60
100000	ngine Mtg (Front)			\$174.63
	ngine Mtr (Rear)			\$172.90
1 -0	ngine Top Cover			\$260.00
	ngine Room Wire			\$2,133.90
	agine Room Wire Frt For Fuse Box			\$207.20
	earbox Assy			\$13,850.50
1				\$261.00
	earbox Mounting			\$6,138.00
	gine Main Wire			
	ake Booster			\$2,771.70
100000000000000000000000000000000000000	ake Master Pump			\$6,378.70
0.0120-0	ont Brake Hose			\$90.70
	ont Brake ABS Sensor Only		1	\$450.70
	ont Brake Calipers			\$882.90
le .	n Belt			\$155.00
Lorente Land	In Airland III			\$1,479.00 aut
Section 1	de Airbag, LH	I		
Side	de Airbag, RH			\$1,479.00 aut \$1,615.00 aut

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	1
	Air Bag Assy, Front Seat, LH			\$857.90	art -
	Air Bag Assy, Instrument Panel Passenger w/o Door, LH			\$3,277.50	dis-
	Roof Top Cover Aigbag			\$1,463.80	art -
	Dashboard Air Bag Assy Passenger			\$3,240.20	art-
	Air Bag Sensors			\$986.00	art-
	Instrumental Panel			\$1,536.20	7
	Roof Lining			\$2,082.10	MI
	Dashboard Assy			\$5,480.90	
	Arm Rest Assy			\$1,389.90	7
	Head Rest, Frt			\$739.60	2
				\$2,402.20	act-
	Computer Assy, Air Bag Ecu				4 -
	Sensor, Air Bag, Front RH			\$313.50	on-
	Retainer, Ultrasonic Sensor, No. 1			\$49.60	dist
	Sensor, Water Temperature (For E.F.I.)			\$118.10	7
	Wire, Skid Control Sensor			\$78.80	7
	Wire, Skid Control Sensor			\$78.80	2
	Sensor, Speed, Front RH			\$446.50	
	Sensor, Speed, Front LH			\$446.50	
	Switch, Push Start			\$412.00	7
	Computer, Engine Control			\$2,636.10	17
	Sensor Assy, Side Air Bag, RH			\$709.30	aut /
	Sensor, Air Bag, Rear RH			\$567.80	ang
	Sensor, Battery Voltage			\$256.80	7
	Transmitter Sub-Assy, Electrical Key			\$447.10	7
	Cover, Rain Sensor			\$500.70	des
	Engine Front Mounting Bracket, LH			\$172.91	7 -
	Cover, Engine Undercover Centre			\$448.30	alt !
	Cover, Engine Under, No. 2			\$76.90	de-?
	Cover, Engine Under, No. 2			\$76.90	der
- 1	Cover, Engine Under, Rear RH			\$84.90	7
- 1	Cover, Engine Under, Rear LH			\$84.90	7
1	Engine Main Wire			\$6,138.00	?
- 1	Wiring Front			\$8,450.50	?
- 1	Wiring Engine			\$2,133.90	0
1	Wiring Floor			\$3,380.60	?
1	Wire, Engine, No. 2			\$195.00	7
1	Wire, Instrument Panel, No. 3			\$4,208.10	0
- 1	Wire, Front Door, RH			\$445.70	1
	Wire, Front Door, LH			\$445.70	7
	Mary William (MCC)			\$6,138.00	7
1	Engine Room Wire			0.000.000.000.000.000	2
1	Body Assy, Throttle			\$1,965.40	7
	Manifold Assy			\$875.60	2
ŀ	ntake Air Flow (Air Flow Sensor)			\$344.60	
	njector Assy, Fuel			\$476.10	5
	Actuator			\$881.60	
	/alve Assy, EGR			\$685.00	7
ļ.	Gasket, EGR Valve			\$11.50	?
r	Motor Assy, Hybrid Vehicle			\$4,833.00	
H	Hybrid Inverter Spare Tank			\$371.30	
ŀ	Hybrid Inverter Bypass Hose (Inlet)			\$42.60	. !
H	Hybrid Inverter Bypass Hose (Outlet)			\$29.30	1
		- 1	I	\$432.20	

ART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	SUB TOTAL			189618.3
	LESS 25%			47404.57
	DISCOUNTED TOTAL			142213.73
	Labour Charge			
	Panel Beating			\$2,800.00
	Spray Painting Charge			\$1,200.00
	Wiring Charge			\$500.00
	Tuff Kote			\$120.00
	Towing Charge			\$60.00
	Front Chassis Alignment Charge			\$400.00
	Repiar Gear Box			\$150.00
	Remove/Refix Undercarriage (Frt)			\$200.00
	Rear Wheel Alignment			\$120.00
	Remove/Refix Radiator			\$280.00
	Remove/Refix Aircon & Refill Gas			\$150.00
	Remove/Refix Engine		1	\$500.00
	Remove/Refix Dashboard			\$450.00
	Remove/Refix Fuse Box			\$180.00
	Remove/Refix Front Windscreen Glass			\$120.00
	Remove/Refix Cushion & Upholstery Front		1	\$150.00
	Remove/Refix Steering Rack/Wheel/Dr Shaft		1	\$500.00
	Remove/Refix Power Steering Pump			\$450.00
	Remove/Refix Brake Master & Booster Pump			\$180.00
	Repair Front Cushion Seat			\$200.00
	Remove/Refix Air Bag/Steering Wheel/Dashboard/Seat			\$550.00
	Diagnosis & Resetting To Erase Fault Code			\$480.00
	TOTAL LABOUR			\$9,740.00
	ESTIMATE TOTAL			\$151,953.73

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

e based on a visual inspection of the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanking 17917999 Worthold Parts 70527.22.

Which top; book value SN 487.10

To duch repair limit Labour 5780

Fauffling Character was \$59,162.51

Book Value - \$49203.02

Rebate - \$24326 Reporte - 424326

reparlint \$24,800 PB6019

Not Economical to repoir.

	-	B8
	w	~
	1	0
		3
Ŕ		0,
ij.		0
		le N
ř		85
		8
		25.00
		IBV for Fleet Safe
	GOLDE	1
	E SELEC	
		-
		8
		-
		CA
		0
		3
		7
		0
		3
		2
		isio
		0
		10.0

		Comfort Transports	TI nota					
		Vehicle HBV for E	eet Safety Sivi	100			170	SUARRESON VILLOR
		AS RT \$1.12.2028					3 5	ANGE : I
Per.Kth.Dep								
•	par. Dep. value	Bal.Dep.Value Asset Desciption 1	Coat	Op.Acc.Dep	Cur. Year Dep	Accum. Dec Ne	522 8532	Scrap value/Estimated
451.11	par.pep.varue	Asset Desciption 1	Coat	Op.Acc.Dep	Cur.Year Dep	Accum. Dep Net Book Value	BBB 1027 8832	value/Estimated FARF Refund \$
64.46	22,104.39	Asset Description 1 SEALTSEA TEN 23.08.2017 EASTC COST W ATRICUM	Cost C	Op.Acc.Dep	Cur.Year Dep	Accum. Dep Ne	1 1000 1000 1000	value/Estimated FARF Refund \$
22.22	22,104.39 3,155.54	Asset Description 1 SELITEDA TER 23.08.2017 EASTC COST W AIRCON SELITEDA TER 23.08.2017 INDEXT DUTY 2000MV22607	Cost 40,600,48	Op.Acc.Dep 4 13,082.05	Cur.Year Dep C 5,413.26-	Accum. Dep Ne	FE SEE 1888 1888 1888	value/Estimated FARF Refund \$
	22,104.39 3,155.54 1,088.78	Asset Desciption 1 SELITSA IPH 23.05.2017 EASTC COST W ATRON SELITSA IPH 23.05.2017 IMPGRI DUTY 2040N/125007 SELITSA IPH 23.05.2017 AMF XXXVV255007	40,600.45 5,801.35 5,000.00	Op.Acc.Dep 4 13,082.05 1,569.34 644.45	Cur.Year Dep C 5,413.26- 773.52- 266.67-	Accum. Dep Ne 18,455.31- 2,642.56- 911.12-	COLOR DE SERVICIO DE 1888 DE 1	value/Estimated PARF Refund \$ 1.00 0.00
403.56	22,104.35 3,155.54 1,055.76 19,774.44	Asset Description 1 SEALISSA IES 23.05.2017 EASTC COST W AIRCON SEALISSA IES 23.05.2017 INSERT BUIL 2040EM/225007 SEALISSA IES 23.05.2017 EAST MONVESSOT SEALISSA IES 23.05.2017 EAST MONVESSOT	Cost 6,800.48 5,801.39 5,000.00 36,320.00	Op.Acc.Dep 4 13,082.05 1,082.05 1,082.34 1,082.35 1,083.37 1,083.12	Cur.Year Dep c 5,413.26- 773.52- 266.66-	Accus. Dep Ne 18,495.31- 2,642.96- 911.12- 16,545.78-	SAR STORY OF THE REST SEED OF THE REST OF	PARF Refunds 1.00 0.00 3,000.00
0.00	22,104.35 3,155.54 1,085.76 19,774.44	Asset Desciption 1 SBA1796A TFM 23.08.2017 BASIC COST W ARRCOM SBA1796A TEM 23.08.2017 IMPORT DUTY 2000MY225007 SBA1796A TEM 23.08.2017 CME TOWN 0F SBA1796A TEM 23.08.2017 CME TOW UF	Coat 40,600.48 5,801.39 5,000.00 36,320.00 0.00	Op.Acc.Dep 4 13,082.05- 1,683.34- 644.45- 111,703.12- 0.00	Cur.Year Dep c 5,413.26- 773.52- 266.67- 4,942.66- 0.00	Accum. Dep Ne 18,435.31 2,642.96 911.12 16,545.78	200 KU 201 m 2 m 4 m 1 m 200 200 200 1 m 1	PART Refund 5 1.00 0.00 3.000.00 0.00 0.00
0.00 0.00	22,104.39 3,155.54 1,085.79 19,774.44	ASSET Description 1 SEALISSA IPS 23.05.2017 EASTC COST W AIRCON SEALISSA IPS 23.05.2017 INFORT DUTY 2040M9/225007 SEALISSA ITS 23.05.2017 CE 804 SEALISSA ITS 23.05.2017 CE 805 SEALISSA ITS 23.05.2017 CE 805 SEALISSA ITS 23.05.2017 CE 805	Coat 40,600.48 5,601.39 5,000.00 36,320.00 0.00 0.00 0.00 0.00	Op.Acc.Dep 4 13,082.05- 11,669.34- 644.45- 11,703.12- 0.00	Cur.Year Dep 5,413.26- 773.52- 266.67- 4,941.66- 0.00	Accum. Dep Ne 18,495.31- 2,642.96- 911.12- 16,545.78- 0.00	100 100 Kill (20 m) 20 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	**************************************
0.00	22,104.39 3,155.54 1,056.76 19,774.40 0.00	Asset Description 1 SRA199A TEM 23.05.2017 EASTC COST W AIRCOM SRA199A TEM 23.05.2017 INDEX: DUTY 204.004/225007 SRA199A TEM 23.05.2017 COM TOM UP SRA199A TEM 23.05.2017 COM TOM UP SRA199A TEM 23.05.2017 COM TOM UP SRA199A TEM 23.05.2017 FAIRTER DIGITAL THERMSAL SRA199A TEM 23.05.2017 FAIRTER DIGITAL THERMSAL	Cost 40,600.48 5.801.39 5.000.00 36,320.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	Op.Acc.Dep 13,082.05- 1,569.34- 644.45- 11,703.12- 0.00 0.00	Cur Year Dep 5,413.26- 773.52- 266.67- 4,941.66- 0.00	Accum. Dep Ne 18,495.31- 2,642.96- 911.12- 16,545.78- 0.00 0.00	THE RESIDENCE OF THE PARTY OF T) value/Escimaced FARF Refund 1.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0
0.00 0.00 0.00	22,104.35 32,152.54 1,085.76 15,774.44 0.00 0.00 0.00	ASSET DESCRIPTION 1 SEALINGA ITE 23.05.2017 EASTC COST W AIRCON SEALINGA ITE 23.05.2017 INFORT DUTY 2040MV125007 SEALINGA ITE 23.05.2017 COE 804 SEALINGA ITE 23.05.2017 COE 804 SEALINGA ITE 23.05.2017 COE 106 SEALINGA ITE 23.05.2017 INFORT DIGITAL THENGAL SEALINGA ITE 23.05.2017 INFORTER DIGITAL INFORMAT	Cost 40,600.48 5,501.39 5,000.00 0.00 0.00 0.00 0.00 0.00 0.00	0p.Acc.Dep 2 13,082.05- 11,869.34- 11,703.11- 0.00 0.00 0.00	Cur.Year Dep 5,413.26- 773.53- 266.67- 4,941.66- 0.00	Accum. Dep Ne 4 18,495.31- 2,642.96- 911.12- 16,555.78- 0.00 0.00	TO SHOW HE WAS AND THE PARTY OF	######################################
0.00 0.00 0.00 0.00	22,104.35 3,152.54 1,085.54 19,774.44 0.00 0.00 0.00 0.00	Asset Descipcion 1 SEAL196A IPH 23.08.2017 EASIC COST W AIRCON SEAL196A IPH 23.08.2017 IMPORT DUTY 20400W/226007 SEAL196A IPH 23.08.2017 COE 804 SEAL196A IPH 23.08.2017 COE 804 SEAL196A IPH 23.08.2017 AIR CONDITIONER SEAL196A IPH 23.08.2017 AIR CONDITIONER SEAL196A IPH 23.08.2017 AIR DIGITAX IPH SEAL196A IPH 23.08.2017 AIR DIGITAX IPH SEAL196A IPH 23.08.2017 VIEN ROG FEE	Coat 40,600.48 5,000.00 5,000.00 0.00 0.00 0.00 0.00 0	Op.Acc.Dep 4 13,082.05- 1,269.34- 11,703.12- 11,703.12- 0.00 0.00 45.12-	Cur.Year Dep 5,413.26- 773.53- 266.47- 4,941.66- 0.00 0.00 0.00 0.00	Accum. Dep Ne 18,495.31- 2,642.96- 911.12- 16,545.78- 0.00 0.00 0.00 0.00 0.00 0.00	25 1 15 2 10 10 10 10 10 10 10 10 10 10 10 10 10	9810e/Estimated FARY Sefund 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00
403.56 0.00 0.00 0.00 1.56 942.91	22,104.39 3,155.54 1,055.79 19,774.44 10,000 0,0	ASSET DESCRIPTION 1 SEALITS A TEM 23.05.2017 EASTC COST W AIRCON SEALITS A TEM 23.05.2017 IMFORE DUTY 204089/226007 SEALITS A TEM 23.05.2017 AMF YM.OMY226007 SEALITS A TEM 23.05.2017 COE BOW SEALITS A TEM 23.05.2017 COE TOF UT SEALITS A TEM 23.05.2017 TAX CONDITIONER SEALITS A TEM 23.05.2017 TAX DISTIAN THERSAL SEALITS A TEM 23.05.2017 TAX DISTIAN TEM 25.05.2017	Cost: 40,600.45 5,500.10 5,500.10 0.00 0.00 0.00 0.00 0.00 0.00 0.0	77,341.08-	Cur.Year Dep 5,413.26- 773.53- 266.67- 4,941.66- 0.00 0.00 0.00 0.00 0.00 0.00	Accum. Dep Ne 18,495.31- 2,642.96- 911.12- 16,545.78- 0.00 9.00 9.00 9.00 9.78- 83.78-	FE 1 10 S 10 C C C C C C C C C C C C C C C C C C	White/Estimated FARF Sefund 0.00 3,000.00 0.00 0.00 0.00 0.00 0.00
403.56 0.00 0.00 0.00 0.00 1.56	22,104.39 3,155.54 1,086.76 15,774.8.70 0,00 0,00 0,00 0,00 0,00 0,00 0,00 0	ASSET DESCRIPTION 1 SEALITS A TEM 23.05.2017 EASTC COST W AIRCON SEALITS A TEM 23.05.2017 IMPORT DUTY 204089/226007 SEALITS A TEM 23.05.2017 COE 80% SEALITS A TEM 23.05.2017 COE 80% SEALITS A TEM 23.05.2017 COE 106 UP SEALITS A TEM 23.05.2017 TAX CONDITIONER SEALITS A TEM 23.05.2017 TAX CONDITIONER SEALITS A TEM 23.05.2017 TAX DESCRIPTION THE MESSAL SEALITS A TEM 23.05.2017 TAX DESCRIPTION TEM 25.05.2017 TAX DESCRIPTION TEM 25.05.	Cost: 40,600.48 5,501.39 5,500.00 0.00 0.00 0.00 0.00 0.00 0.00	Op.Acc.Dep 4 11,082.05 1,269.34 1,269.34 11,703.12 0.00 0.00 0.00 0.00 45.12 27,341.06	Cur.Year Dep 5,413.26- 773.53- 266.47- 4,942.66- 0.00 0.00 0.00 0.00 0.00 0.00	Accum. Dep Ne 18,495.31- 2,642.96- 911.12- 16,555.78- 0.00 0.00 0.00 9.00 9.00 9.78- 35,650.85-		White/Estimated FARF Sefund 0.00 0.00 0.00 0.00 0.00 0.00 0.00
403.56 0.00 0.00 0.00 0.00 1.56 403.56	22,104.35 3,185.54 1,000.00 15,774.44 46,202.55	Asset Description 1 SRAI198A THE 23.08.2017 EASTC COST W AIRCOR SRAI198A THE 23.08.2017 INDEED OUT 200.000/225007 SRAI198A THE 23.08.2017 COE TOR UP SRAI198A THE 23.08.2017 COE TOR UP SRAI198A THE 23.08.2017 COE TOR UP SRAI198A THE 23.08.2017 AIR COMDITIONER SRAI198A THE 23.08.2017 AIR STAITER DIGITAX THE SRAI198A THE 23.08.2017 TAINETER DIGITAX THE SRAI198A THE 23.08.2017 TAINETER DIGITAX FI SRAI198A THE 23.08.2017 THE REG FEE Vehicle : Without T/M a COE	Comp C Comp C C C C C C C C C C C C C C C C C C C	0p.Joc.Der 11,022.03- 1,263.34- 11,021.03- 11,021.03- 11,021.03- 10.00 0.00 0.00 0.00 0.00 0.00 15,041.05- 15,040.56-	Cur. Year Dep 5,413.26- 773.53- 266.67- 4,942.66- 9.00 9.00 9.00 9.00 10.00 11.314.77- 11,314.77-	Accum. Dep Ne 18,495.31- 2,642.96- 91112- 16,545.78- 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.	A STATE OF THE PROPERTY OF THE PARTY OF THE	Value/Estimated FARF Refund 1.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0
403.56 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0	22,104.39 3,155.54 1,155.54 1,005.79 19,774.44 46,202.59 19,774.44	Asset Desciption 1 SEALTSCA TEM 23.08.2017 BASIC COST W AIRCOM SEALTSCA TEM 23.08.2017 INFORT BUTY 200.009/225007 SEALTSCA TEM 23.08.2017 COE 804 SEALTSCA TEM 23.08.2017 COE 109 UP SEALTSCA TEM 23.08.2017 COE TOP UP SEALTSCA TEM 23.08.2017 TAINCHIER DIGITAX FILESALTSCA TEM 23.08.2017 VEMBOR TEM Vehicle : Without T/M, With COE Vehicle : Without T/M, With COE	Cort 5,500.00 5,500.0	0p.loc.Dep 4 13,022.05- 1,569.34- 11,702.10- 0.00 0.00 0.00 0.00 0.00 0.00 0.00	Cur.Year Dep 5,411.26- 771.52- 266.67- 4,941.66- 0.00 0.00 0.00 10.00 11.314.77- 11.314.77-	Accum. Dep Ne 18,485.31. 2,642.96 911.12- 16,545.78- 0.00 0.00 0.00 0.00 63.78- 39,656.85-		Walte/Estimated FARF Refind 4 1.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0
								Comfort Temagostaring El Venicle HBV for Elect Safety Division AS RT N.15.2020

ARF/COE Rebate for Registered Vehicle

ner Particulars	
	Company
e:	
ails.	821R
alis.	SHA1798A
Exported:	No
egistration Date:	10 Feb 2021
	TOYOTA
	PRIUS HYBRID 1.8 CVT
or:	Blue
ng Year:	2017
	2ZRS062014
	JTDKB3FU103563524
wer Output:	90.0 kW (120 bhp)
: Value:	\$29,007.00
stration Date:	23 Aug 2017
etion Date:	23 Aug 2017
nt:	0
aid:	\$5,000.00
ARF Rebate Details	
ity:	Yes
ity Expiry Date:	22 Aug 2025
Amount:	\$3,750.00
OE Rebate Details	
Date:	22 Aug 2025
ry:	A - Car up to 1600cc & 97kW (130bhp)
Years):	8
	\$36,320.00
Amount:	\$20,576.00
Amount:	\$24,326.00

that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if a earlier.



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

CHASSIS CODE JTDKB3FU103563524

Date/Time: 09.02.2021 17:11 Page: 1

COMPLETION DATE/TIME:

Team: ARC Repair TP(CLSO)1 JOB CARD Sales Order: JC NO.: 305452155 REGN NO.: SHA1798A TOMER MILEAGE COMFORT TRANSPORTATION PTE LTD MAKE: FUEL 7010045 TOYOTA 383 SIN MING DRIVE E.....1/2... PRIUS HYBRID(G4)27.01.2021 17:30 MODEL Singapore SINGAPORE 575717 65508755 YR OF MANU. 23.08.2017 (R) (O) TARGET DATE (P)

JOB DESCRIPTION Accident Date: 27.01.2021


NATURE: TP/3P.27.01.2021 -

S/NO

OUNT CARD NO.

LABOR CODE

DESCRIPTION



						REAR SE	
JKED & I	PASSED OUT BY:		P.				
	SERVICE ADVISO	R				CUSTOMER'S SIGN	IATURE
ledgeme	ent Slip			Exit Pass			
No.:	SHA1798A	JU		Vehicle No.:	98A		
						*	
f Service	Advisor		Signature/Date	Name of Service Advisor		Date	
turned to	Service Reception upon	collection		To be kept by Security Guard	Í		

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
2. This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident Exact Location of Accident Additional Location Information Country/State of Loss

28/01/2021 13:21 (SGT) 27/01/2021 17:30 (SGT) Bartley Rd, Singapore TOWARDS UPPER PAYA LEBAR

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SHA1798A

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

Company Reg No

Email Address

Mobile Phone No.

Alternative Phone No.

COMFORT TRANSPORTATION PTE LTD

1XXXXX821R

fleetsafety@cdgtaxi.com.sg (Phone) +65-92731695

(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle?

Vehicle Category

Toyota

Prius

Private hire

No - Claiming third party

Taxi

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage

Fleet Policy

Policy Number

Cover Note Number

Axa

ThirdPartyFireTheft

Yes

VFX/P2419138

DRIVER

Name of Driver

NRIC No

Date Of Birth

Occupation

LIM KHOON LEK SXXXX065G

16/11/1957

Outdoor



Accident report SJ04211S0003

Page 1 of 9

Date Of Driving Pass 30/09/1976 Driving experience 44 YEARS AND 4 MONTHS Gender Mobile Number (Phone) +65-92731695 Alt. Phone Number Email Address fleetsafety@cdgtaxi.com.sg Address BLK 871 TAMPINES ST 84 #02-47 Address complement Postcode 520871 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head on collision Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? Yes Was any other material or property damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1 Name UNKNOWN Gender Female DETAILS OF POLICE ACTION

CIRCUMSTANCES OF ACCIDENT

If yes, against whom?

Was the accident reported to the police? Was notice of intended Prosecution given?

ON 27/1/2021 AT ABOUT 1730HRS I WAS DRIVING MY VEH SHA1798A ALONG BARTLEY ROAD. WHILE DRIVING ON THIRD LANE, SUDDENLY I NOTICED A VEH SLG6983U FROM OPPOSITE DIRECTION HEADING TO TOWARDS MY VEH. I APPLIED JAM BRAKE. ABOUT 2-3 SECONDS VEH B - SLG6983U WAS VERY FAST, COLLIDED ONTO THE FRONT OF MY VEH. I WAS NOT ABLE TO STEP OUT OF MY VEH. THEN I'M CONVEYED BY AMBULANCE TO TTSH DUE TO MY CHEST PAIN AND LEG INJURY. MY PASSENGER WAS ALSO INJURED DUE TO THE IMPACT.

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Was there any audio recorded?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model

Vehicle Variant

Vehicle Colour

Vehicle Colour

SLG6983U

Toyota

Vios

Vios



INJURED PERSONS DETAILS

INJURED 1

Name of injured person

Address

Address Complement

Post Code

Approximate Age Years Old

Injuries Sustained

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

LIM KHOON LEK

CHEST PAIN, LEG

SHA1798A

Yes

Name of injured person

Address
Address Complement
Post Code
Approximate Age Years Old
Injuries Sustained
Injured person in which vehicle?
Was this injured conveyed to hospital by ambulance?

UNKNOWN PASSENGER

UNKNOWN PASSENGER
SHA1798A
UNKN

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2 This Formmust be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Formby insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation
- The report will be forwarded by the insurers of the GW Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)
- Lunderstand, acknowledge, agree and consent that
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of .
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
- (ii) investigating the accident and/or my claims.
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or.
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signati Time	re / Date & Oriver's & Time		er is not the policyhok	ter) / Date Witne	ssed by Reporting Centr
Sketch Plan	545	99111	7071	1011	Wiende
	March of her	1111	11		
	How I un Dr		7		
		X			
110000	<u> </u>			, -	
			1	A-3	HA 179+4.
					0.00.00
		[P]	1	12 - 71	969330
		10			

Describe Circumstances of the Accident
on 37/1/2021, at about 1730hm, I was
driving my vehicle AHA 1790A along Buttey Al.
while diving on third lane at about juddenly
I noticed on vehicle which ship 69834 from appoints
About 2 to 3 counts as a second to a second the second and a second as a secon
About 210 3 seconds reliable B-SLG 69+3 mer very feet collided buto my front of my reliable. I
could not able to stop and from may vehicle . & then
I conveyed to subulance to TTAH due to my chief
pair and leg injury. My partitioner also injury
due to the impact.

Declaration

We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD CO. REG. NO. 199303821R





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865

1 of 3 Report No. T/20210203/2063

Tel No: 65470000

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/02/2021 12:56			Vide Report No.: Station Diary F/20210127/0131			
Informa	nt's Partic	ulars				
Name of Informant: LIM KHOON LEK			Address: 871 TAMPINES STREET 84 #02-47 TAMPINES VISTA SINGAPORE 520871			
ID Type / ID No.: NRIC NO / S1236065G Nationality: SINGAPORE CITIZEN			Contact No.: Home/Office: Mobile: 92731695 Email:			
Sex: Male	Age: 63	Date of Birth: 16/11/1957	Type of Informant: Driver			
Race: Chinese			Language: English	Institution / School Name:		
Occupation: Taxi driver			Driving Licence Information:	Date of Expiny		

nation of the Accident			
Injury Conveyed By Ambuland	Drink Drive:	Date/Time of Accident: 27/01/2021 17:30	Type of Location: Straight Road
AD			
			29
Ro	ad Surface:		Road Speed Limit:
	Injury Conveyed By Ambuland	Injury Drink Conveyed By Ambulance Drive: No	Injury Conveyed By Ambulance Drive: No Accident: 27/01/2021 17:30

vveatilei.	Road Surface:	Road Speed Limit:
Clear	Dry	
Traffic Flow:	Traffic Control:	Traffic Volume:
Two Way	Not Controlled	Moderate
Type of Collision:	Anyone conveyed by	
Between Moving Vehicles - Head To Rear		ambulance:
		Yes

Details of Vehicle Involved						
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
SHA1798A	TAXI	ТОУОТА	PRIUS HYBRID 1.8 CVT	Blue		0
SLG6983U	Car	TOYOTA	VIOS E AUTO	White		0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

2 of 3 Report No. T/20210203/2063

CONTINUATION OF REPORT

NI						
Name	LIM KHOON LEK			ID No).	S1236065G
Related Vehicle	SHA1798A (TAXI)			Conta	act No.	92731695
Hospital/Clinic	TTSH			Class Drivin Licen	g	Class: NIL Date of Expiry: NIL
Date Treatment	27/01/2021		Date Disch			/2021
No. of Days granted Medical Leave 14			ree of Injury NIL		12021	

Brief Details.

ON THE STATED DATE, TIME AND LOCATION,

I WAS TRAVELLING ALONG BARTLY ROAD EAST TOWARDS UPPER PAYAR LEBAR ROAD ON THE LEFT OF TWO LANES, AND SUDDENLY THE SAID CAR TRAVELLED AGAINST FLOW ON THE RIGHT LANE AND CHANGED INTO LEFT LANE, CAUSING AN HEAD ON COLLISION. IO ESMOND THEN TOLD TO MAKE MY WAY TO TPHQ TO LODGE A REPORT ACCORDINGLY. THAT'S ALL.





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 3 of 3 Report No. T/20210203/2063

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Informant:

Signature Of Officer Recording The Report:
TP /
SC MUHAMMAD SYAFIQ BIN ABDULLAH

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Sgt 3 MUHAMMAD SYARIFUDDIN
MUHAMMAD AJMAIN
Contact No.: 65476367

Authentication Stamp
NP168

_	All		
1			
Date/Time	:		
03/02/202	1 12:56		
Classificati	ion Of Case		
Classificati	M N		
	OF BEEN TO	SINGAPORE	
		POLICE FORCE	
	APL STA	1	

