

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/11/21002125/4653

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

have G.A

MTA 31743

26/2/24 1/5 @ 5500 confirmed with E.Olin

Veh No:

SLT 6837R

Yr Regn:

7/11/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

mit space star

c.c

1193

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

47734

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

AMCXTA03AJH001640

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

other

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/55 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS, SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Ulu: Jaser

not Authorised

Ulu
15/2/21

4/5 \$5500/
5 days

Car Number: SLT6837R

Model : Mitsubishi Space Star

Damaged Area: (Front, RH & LH Damaged)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

Parts / Material :

1	Front Bumper	DIS 751	\$ 825.40	✓
2	Front Bumper Bracket @ SGD 68.90	11	\$ 137.80	X
3	Front Bumper Side Retainer @ SGD 75.80	NLS CR 35	\$ 151.60	1PC
4	Front Bumper Centre Garnish	11	\$ 295.80	X
5	Front Bumper Side Garnish @ SGD 175.60	NLS TWI 115	\$ 351.20	1PC
6	Front Bumper Centre Chrome Garnish	11	\$ 245.80	X
7	Front Bumper Side Chrome Garnish @ SGD 195.70	NLS CR 125	\$ 391.40	1PC
8	Front Bumper Fog Lamp @ SGD 328.40	NLS CR 311.00	\$ 656.80	1PC
9	Front Bumper Number Plate Based Garnish	NZ	\$ 105.60	X
10	Front Bumper Clips (Set)	11 50	\$ 60.00	1
11	Radiator Grille Chrome Garnish	11	\$ 195.80	X
12	Radiator Grille Based Garnish	11	\$ 325.80	X
13	Radiator Grille Clips (Set)	11	\$ 60.00	X
14	Front Headlamp Assy NLS	CR 1842	\$ 2,213.60	✓
15	Front Headlamp Bracket @ SGD 98.50	NLS	\$ 197.00	X
16	Front Fender @ SGD 779.60	NLS DIS 435	\$ 1,559.20	1PC
17	Front Fender Quarter Garnish @ SGD 72.40	11	\$ 144.80	X
18	Front Fender Emblem @ SGD 89.20	NLS REC 62	\$ 178.40	1PC
19	Front Fender Bracket @ SGD 95.40	11	\$ 190.80	X
20	Front Fender Inner Shield @ SGD 214.50	NLS DIS 103	\$ 429.00	1PC
21	Front Fender Inner Shield Clips (Set)	11 50	\$ 60.00	1
22	Wing Mirror Assy LH	11	\$ 479.10	X
23	Front Door LH	11	\$ 984.20	X
24	Front Door Inner Trimboard Clips	11	\$ 60.00	X
25	Front Door Outer Glass Moulding LH	11	\$ 175.80	X
26	Front Door Weather Strip LH	11	\$ 198.40	X
27	Front Door Top Hinge LH	11	\$ 78.10	X
28	Front Door Bottom Hinge LH	11	\$ 67.20	X
29	Front Door Checker LH	11	\$ 59.40	✓
30	Front Rim LH (Ori)	20 / Bent	\$ 1,011.20	580 S/N
31	Front Knuckle Arm LH	Bent 367.00	\$ 420.00	1
32	Front Knuckle Hub, Wheel Bearing LH	11 245	\$ 320.00	1
33	Front Lower Arm LH	BUC 280	\$ 392.00	1
34	Front steering rackend	Bent 165	\$ 245.00	1
35	Front Shock Absorber LH	Bent 320	\$ 395.00	1

Parts : \$ 13,661.20

Less Parts 10% : \$ 1,366.12

Total Parts : \$ 12,295.08

Special Net Items :

Front Number Plate W/Garnish

Front Tyre RH 15" Inch

\$ 65.00 40

\$ 380.00 X

Total S/N Parts : \$ 445.00

Labour :

To Remove, Repair & Renew Affected Accident Areas	\$ 1,200.00	600
To Putty, Spray Paint on Front Affected Accident Areas	\$ 1,600.00	600
To Check & Re-Connect all electrical wiring	\$ 50.00	20
To Remove & Install Front Left Undercarriage Components	\$ 250.00	150
To Conduct All Wheel Alignment	\$ 250.00	100
To transfer, Replace & Balance Front Rim & Tyre	\$ 1100.00	X
To Remove & Install Front Door LH Components	\$ 1180.00	X
To Diagnostic & Reset to specification	\$ 450.00	50
To Rust Proof Affected Areas	\$ 200.00	30
Total Labour :	\$ 4,280.00	

TOTAL PARTS : \$ 12,295.08
TOTAL SPECIAL NET ITEM : \$ 445.00
TOTAL LABOUR : \$ 4,280.00
TOTAL REPAIR COST : \$ 17,020.08

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

FINALISED AMOUNT :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-5258
107
P-4730-40
S.N-620
L-1550
6900-40
292
5520



Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Classic Promo! Best Deal! Fast Selling! Hurry Down Now!



Flexible Loan, Trade In Are
 Welcome. 100% Deposit Refund
 For Unapproved Loan,
 Classic Credit StarAd



Browse by Category

Sort by Date Posted 20 results/page

1 vehicles

mitsubishi space

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	mitsubishi space	Any	Any	2017	Any	Any	Any	Available



Mitsubishi Space Star 1.2A Sport

\$50,988

\$7,190 /yr

15-Nov-2017

1,193 cc

49,000 km

Hatchback

Available

1 Owner Only! Full Agent Maintained Since Day 1! 10 Years Warranty By C&C. Flexible Loan Packages Available. Please Call For Viewing Appointment.

Cycle & Carriage. Fulco Motor Dealer

Posted: 02-Feb-2021 Tags: 2017 Mitsubishi Space, Mitsubishi Space, Mitsubishi, Space

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Rental Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used mitsubishi space, mitsubishi space Singapore, used mitsubishi space Singapore, used mitsubishi space, used vehicles Singapore or even buy used mitsubishi space Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2021 sgCarMart, Singapore. All rights reserved.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	335J
Vehicle Details	
Vehicle No.:	SLT6837R
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Feb 2021
Vehicle Make:	MITSUBISHI
Vehicle Model:	SPACE STAR 1.2 CVT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	3A92UGJ9340
Chassis No.:	MMCXTA03AJH001640
Maximum Power Output:	59.0 kW (79 bhp)
Open Market Value:	\$14,490.00
Original Registration Date:	07 Nov 2017
First Registration Date:	07 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Nov 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	06 Nov 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$41,617.00
COE Rebate Amount:	\$27,993.00
Total Rebate Amount:	\$31,743.00

The information contained herein is correct as at 15 Feb 2021

OK

TECHNEAT PTE LTD
8 Kaki Bukit Avenue 4
(Enter by Gate 2)
#03-38/39/40
Premier@Kaki Bukit
Singapore 415875

Tel : (65) 6384 1996
Fax : (65) 6384 1996
Hotline : (65) 9691 0887

Email: techneatcarcare@yahoo.com.sg
Business Hour : 9am to 7pm(Mon to Sat)

Service - Repair - Rim - Tyres - Battery - Balancing & Alignment

Work Order: slt 6837r

Date 16.2.21 9:01

Mitsubishi : Space Star : 2013- (A0)

Front : Left

Actual	Before	Specified Range
-4°11'		-0°50' 0°40'
5°50'		3°20' 4°50'
0°15'		-0°09' 0°09'
16°23'		10°20' 13°20'
12°13'		9°30' 14°00'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°08'		-0°50' 0°40'
5°52'		3°20' 4°50'
0°28'		-0°09' 0°09'
12°13'		10°20' 13°20'
12°04'		9°30' 14°00'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-4°03'		-0°30' 0°30'
-0°02'		-0°30' 0°30'
4°11'		
0°43'		-0°18' 0°18'

Rear : Left

Actual	Before	Specified Range
-1°05'		-1°45' -0°15'
0°22'		0°00' 0°18'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°46'		-1°45' -0°15'
-0°14'		0°00' 0°18'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°41'		-0°30' 0°30'
0°08'		0°00' 0°36'
0°18'		

TECHNEAT PTE LTD
8 Kaki Bukit Avenue 4
(Enter by Gate 2)
#03-38/39/40
Premier@Kaki Bukit
Singapore 415875

Tel : (65) 6384 1996
Fax : (65) 6384 1996
Hotline : (65) 9691 0887
Email: techneatcarcare@yahoo.com.sg
Business Hour : 9am to 7pm(Mon to Sat)

Service - Repair - Rim - Tyres - Battery - Balancing & Alignment

Work Order: SLT 6837 R
Date 19.2.21 12:30

Mitsubishi : Space Star : 2013- (A0)

Front : Left

Actual	Before	Specified Range
-1°33'	-1°48'	-0°50' 0°40'
3°09'	3°09'	3°20' 4°50'
0°07'	-1°26'	-0°09' 0°09'
31°01'	31°17'	10°20' 13°20'
29°29'	29°29'	9°30' 14°00'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°51'	-0°34'	-0°50' 0°40'
2°43'	2°43'	3°20' 4°50'
0°03'	-1°24'	-0°09' 0°09'
15°53'	15°37'	10°20' 13°20'
15°03'	15°03'	9°30' 14°00'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°42'	-1°14'	-0°30' 0°30'
0°26'	0°26'	-0°30' 0°30'
15°08'	15°40'	
0°10'	-2°50'	-0°18' 0°18'

Rear : Left

Actual	Before	Specified Range
-1°12'	-1°19'	-1°45' -0°15'
-0°08'	-0°10'	0°00' 0°18'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-0°58'	-0°55'	-1°45' -0°15'
0°15'	0°18'	0°00' 0°18'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°14'	-0°23'	-0°30' 0°30'
0°07'	0°08'	0°00' 0°36'
-0°11'	-0°14'	