



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/III20014199/Dtf3q2-1	
			Date: 17/02/2021	
			Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 6233A	Veh. Inspected	SMS 1044M	
Policy No.	MCOM0015	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	CARINE KEK PHEI SER	Assign Date	15/02/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FREED 1.5G	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	GB71114737	Colour	GREY	
Odometer	14970 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	185/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	185/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	185/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/12/2020	Inspection Date	22/12/2020	
Survey held at	YAP MOTOR REPAIR SERVICE BLK 7 SIN MING IND EST SEC C #01-80 & 82 SINGAPORE 575642			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	