

ASS. REC. BY: *Morales*

REF: CCY/1421002130/4p93

ASSIGNMENT

ENVY 12-2-21 L74 856450
Nett 53810

The U/C / Chassis frame / Body Structure affected due to collision.

Lump Sum / I.B.I: (\$

TOTAL



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

Not Authorized
Alan
Edu phlo before 24 mty
16/2/21
P/P *ShyS.*

ESTIMATE

Account Details		Account No.	Customer Details				
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1	Mr Kuo Chung-Liang				
		Document No. 0	528 East Coast Road #04-04 Singapore 458969				
		Document Date 15/02/2021	Mobile: 81230929				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ASU60R	ANTGT L1	14/09/2018	SME0375M	0	20721	67/TP/SME0375M
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTEKB3GH10J002653		8ARZ130620	60	Sam San Joi	15/02/2021 8.35		--/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY-MS SUNDRIES TP-CLAIM PTP-SMN5515X ACC DATE:10/02/2021 TOW IN:10/02/2021 DATE-IN:10/02/2021 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:					30.00
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON FRT ACCIDENT AREAS					366.36
3	S	BP-SUBLET FRT NUMBER PLATE					68.00
4	B	BP-LAB2 DRILL HOLE & INSTALL FRT SENSOR					180.00
5	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM					122.40
6	B	BP-LAB2 REMOVE & INSTALL AIRCON CONDENSER ASSY A ND CHARGE UP GAS					360.00
7	Z	BP-SLANT SUPPLY SEALANT (NETT)- BONNET, FRT SUPPO RT PANEL					120.00
8	S	BP-SUBLET TO CONDUCT ADJUSTMENT ON FRT WAVE RADAR SENSOR					180.00
9	S	BP-SUBLET TO RESET ECU AND REPROGRAMME					180.00
10	B	BP-LAB2 REPLACE FRT ACCIDENT DAMAGED PART STRAIGHTEN & ALIGN FRT ACCIDENT AFFECTED AREAS 720 x 4					3600.00
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		Less		
			Labour				
			Sublet				
			Lubrication/Fluid				
			Others		Amount Due		

Customer Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details				
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1	Mr Kuo Chung-Liang				
		Document No. 0	528 East Coast Road #04-04 Singapore 458969				
		Document Date 15/02/2021	Mobile: 81230929				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ASU60R	ANTGT L1	14/09/2018	SME0375M	0	20721	67/TP/SME0375M
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTEKB3GH10J002653		8ARZ130620	60	Sam San Joi	15/02/2021 8.35		--/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
11	B	BP-RES2 RESPRAY JOB ON FRT ACCIDENT AFFECTED ARE 150 x 51			29.50	3540.00	
12	1	T52119-4D946 COVER, FR BUMPER	1.00	811.30		811.30	
13	2	T52536-48030 RETAINER, FR BUMPER	1.00	115.20		115.20	
14	3	T52535-48040 RETAINER, FR BUMPER	1.00	115.20		115.20	
15	4	S52161-0K040 CLIPS	10.00	4.10		41.00	
16	5	T52614-48050 ABSORBER, FR BUMPER	1.00	112.20		112.20	
17	6	T52021-48090 REINFORCEMENT	1.00	521.70		521.70	
18	7	T52612-48050 ABSORBER, FR BUMPER	1.00	49.80		49.80	
19	8	T52611-48210 ABSORBER, FR BUMPER	1.00	49.80		49.80	
20	9	T52029-48010 REINFORCEMENT	1.00	301.10		301.10	
21	0	T52538-48040 RETAINER, FR BUMPER	1.00	117.40		117.40	
22	1	T52537-48040 RETAINER, FR BUMPER	1.00	117.40		117.40	
23	2	T75392-42030 RETAINER, OUTSIDE	2.00	11.20		22.40	
24	3	L47749-50090 CLIP	4.00	1.80		7.20	
25	4	L53879-30050 RETAINER, FR FENDER	4.00	16.80		67.20	
26	5	T53102-48081 GRILLE SUB-ASSY	1.00	417.70		417.70	
27	6	T53286-48090 COVER, FR BUMPER ARM	1.00	38.80		38.80	
28	7	T53285-48080 COVER, FR BUMPER ARM	1.00	38.80		38.80	
29	8	T52126-48100 BRACKET, FOG LAMP	1.00	98.20		98.20	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		Less		
			Labour				
		Sublet					
		Lubrication/Fluid					
		Others		Amount Due			

Customer Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / ICIII1	Mr Kuo Chung-Liang 528 East Coast Road #04-04 Singapore 458969 Mobile: 81230929
	Document No. 0	
	Document Date 15/02/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ASU60R	ANTGT L1	14/09/2018	SME0375M	0	20721	67/TP/SME0375M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEKB3GH10J002653	8ARZ130620	60	Sam San Joi	15/02/2021 8.35	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
30	9	T52125-48100 <i>o/s</i> BRACKET, FOG LAMP	1.00	98.20	?	98.20
31	0	T52701-48010 MOULDING SUB-ASSY, <i>che</i>	1.00	465.60	✓	465.60
32	1	T52411-48050 GUARD, FR BUMPER <i>D/S</i>	1.00	340.20	✓	340.20
33	2	L75392-35220 RETAINER OUTSIDE <i>D/S</i>	2.00	3.90	✓	7.80
34	3	T90467-07220 CLIP <i>ner</i>	10.00	2.50	✓	25.00
35	4	T48691-48040 DAMPER, SUSPENSION	1.00	1343.10	?	1343.10
36	5	T48696-48020 <i>o/s</i> BRACKET, TOWER BAR, <i>D/S</i>	1.00	312.90	✓	312.90
37	6	T48695-48020 <i>o/s</i> BRACKET, TOWER BAR, <i>D/S</i>	1.00	263.50	✓	263.50
38	7	T52618-48030 <i>o/s</i> ABSORBER, FR BUMPER, <i>D/S</i>	1.00	172.00	✓	172.00
39	8	T51410-78010 COVER ASSY, ENGINE <i>D/S</i>	1.00	303.30	✓	303.30
40	9	T90467-07215 CLIP <i>ner</i>	10.00	2.50	✓	25.00
41	0	T53101-48920 GRILLE SUB-ASSY, <i>che</i>	1.00	1351.40	✓	1351.40
42	1	T53141-48130 GARNISH, RADIATOR <i>che</i>	1.00	1673.50	✓	1673.50
43	2	T53301-48170 HOOD SUB-ASSY <i>R</i>	1.00	1983.90	X	1983.90
44	3	T53812-48190 PANEL, FR FENDER, LH <i>R</i>	1.00	1446.30	X	1446.30
45	4	T53811-48210 PANEL, FR FENDER, RH <i>R</i>	1.00	1446.30	X	1446.30
46	5	T53876-48120 LINER, FR FENDER, LH <i>70mm</i>	1.00	522.50	?	522.50
47	6	T53875-48120 LINER, FR FENDER, RH	1.00	522.50	✓	522.50
48	7	T90467-07201 CLIPS <i>ner</i>	10.00	3.50	✓	35.00
49	8	T90189-06013 GROMMET <i>ner</i>	10.00	2.20	✓	22.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII1		Mr Kuo Chung-Liang 528 East Coast Road #04-04 Singapore 458969 Mobile: 81230929		
			Document No.				
			0				
			Document Date				
			15/02/2021				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ASU60R	ANTGT L1	14/09/2018	SME0375M	0	20721	67/TP/SME0375M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEKB3GH10J002653	8ARZ130620	60	Sam San Joi	15/02/2021 8.35	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
50	9	T53896-48150 <i>9/5</i> SHIELD, FR FENDER <i>see</i>	1.00	53.00	?	53.00
51	0	T53895-48150 <i>9/5</i> SHIELD, FR FENDER <i>see</i>	1.00	53.00	?	53.00
52	1	T53420-48140 HINGE ASSY, HOOD, LH <i>17</i>	1.00	87.10	X	87.10
53	2	T53410-48140 HINGE ASSY, HOOD, RH <i>17</i>	1.00	87.10	X	87.10
54	3	T53510-48260 LOCK ASSY, HOOD <i>17</i>	1.00	164.60	X	164.60
55	4	T53208-48091 SUPPORT SUB-ASSY, <i>17</i>	1.00	407.30	X	407.30
56	5	T53205-48030 <i>ctr</i> SUPPORT SUB-ASSY, <i>17</i>	1.00	1111.90	X	1111.90
57	6	T53203-48130 SUPPORT SUB-ASSY, <i>17</i>	1.00	176.20	X	176.20
58	7	T53202-48090 SUPPORT SUB-ASSY, <i>17</i>	1.00	216.80	X	216.80
59	8	T16683-36100 PLATE, RADIATOR LWR	1.00	121.90	?	121.90
60	9	T53159-48010 SEAL, RADIATOR	1.00	56.50	?	56.50
61	0	T16697-36070 PLATE, RADIATOR SIDE	1.00	90.90	?	90.90
62	1	T16695-36140 PLATE, RADIATOR SIDE	1.00	53.70	?	53.70
63	2	T16693-36070 PLATE, RADIATOR SIDE	1.00	73.40	?	73.40
64	3	T16691-36140 PLATE, RADIATOR SIDE	1.00	55.10	?	55.10
65	4	T53867-48090 SEAL, FR FENDER TO <i>see</i>	1.00	50.00	---	50.00
66	5	T53866-48080 SEAL, FR FENDER TO <i>holder cre</i>	1.00	51.10	---	51.10
67	6	T81185-48E40 UNIT, HEADLAMP <i>LH</i>	1.00	6714.50	✓	6714.50
68	7	T81145-48E40 UNIT, HEADLAMP <i>RH</i>	1.00	6714.50	?	6714.50
69	8	T52134-48070 <i>15</i> REINFORCEMENT, FR <i>surf</i>	1.00	69.80	---	69.80

For & on behalf of		Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd				
Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others	Less	
			Amount Due	

Customer Copy



Borneo Motors



TOYOTA

Inchcape
Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
India International Insurance P L		S1000006 / ICIII1	Mr Kuo Chung-Liang	
64 Cecil Street		Document No.	528 East Coast Road	
#06-02 IOB Building		0	#04-04	
Singapore 049711		Document Date	Singapore 458969	
Attn: Motor Claims Dept		15/02/2021	Mobile: 81230929	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ASU60R	ANTGT L1	14/09/2018	SME0375M	0	20721	67/TP/SME0375M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEKB3GH10J002653	8ARZ130620	60	Sam San Joi	15/02/2021 8.35	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
70	9	T52133-48060 <i>ols</i> REINFORCEMENT, FR <i>sel</i>	1.00	69.80		69.80
71	0	T81156-48E30 BRACKET, HEADLAMP, A <i>sel</i>	1.00	31.60		31.60
72	1	T81116-48E30 BRACKET, HEADLAMP, A <i>sel</i>	1.00	31.60		31.60
73	2	T81056-48E30 COMPUTER SUB-ASSY,	1.00	1129.10		1129.10
74	3	T81016-48E30 COMPUTER SUB-ASSY,	1.00	1129.10		1129.10
75	4	T81108-47560 COMPUTER SUB-ASSY,	1.00	1173.40		1173.40
76	5	T81107-47560 COMPUTER SUB-ASSY,	1.00	1173.40		1173.40
77	6	L81220-48051 LAMP ASSY, FOG, LH <i>ols</i>	1.00	516.00		516.00
78	7	T81210-48051 LAMP ASSY, FOG	1.00	516.00		516.00
79	8	T81440-48010 <i>ols</i> LAMP ASSY, DAYTIME	1.00	907.60		907.60
80	9	T81430-48010 <i>ols</i> LAMP ASSY, DAYTIME	1.00	907.60		907.60
81	0	L89341-48040 C3 SENSOR, ULTRASONIC, <i>shaf</i>	2.00	481.90		963.80
82	1	T89341-58060 C1 SENSOR, ULTRASONIC, <i>shaf</i>	2.00	481.90		963.80
83	2	T89348-58150 C1 RETAINER, ULTRASONIC <i>rer</i>	2.00	21.30		42.60
84	3	T89348-58140 C1 RETAINER, ULTRASONIC <i>rer</i>	2.00	21.30		42.60
85	4	T89348-58120 RETAINER, ULTRASONIC <i>rer</i>	2.00	16.00		32.00
86	5	T89348-58130 CLIP, ULTRASONIC <i>rer</i>	2.00	12.30		24.60
87	6	T82219-78010 WIRE, SENSOR	1.00	253.30		253.30
88	7	T82113-48080 WIRE, ENGINE ROOM,	1.00	149.10		149.10
89	8	T85315-42360 JAR, WASHER, A	1.00	152.80		152.80

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	
			Amount Due

Customer Copy



Borneo Motors



TOYOTA

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no. : 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details				
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1	Mr Kuo Chung-Liang				
		Document No. 0	528 East Coast Road #04-04 Singapore 458969				
		Document Date 15/02/2021	Mobile: 81230929				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ASU60R	ANTGT L1	14/09/2018	SME0375M	0	20721	67/TP/SME0375M
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTEKB3GH10J002653		8ARZ130620	60	Sam San Joi	15/02/2021 8.35		--/--/---- 0.00
L	Cd	Job/Parts Description		Qty	Unit Price	Disc %	Amount
90	9	T85316-48230	CAP, WASHER, A	1.00	78.10	?	78.10
91	0	T88460-48160	CONDENSER ASSY	1.00	2044.10	X	2044.10
92	1	L16400-36100	RADIATOR ASSY	1.00	2634.40	X	2634.40
93	2	T16712-36050	SHROUD, FAN, NO.2	1.00	117.40	X	117.40
94	3	T16550-36060	RADIATOR ASSY,	1.00	603.70	X	603.70
95	4	T17751-36090	INLET, AIR CLEANER	1.00	220.00	X	220.00
96	5	S08889-80102	COOLANT, SLCC&&&	1.00	79.50	X	79.50
97	6	T75770-48060	MOULDING ASSY, HOOD,	1.00	567.50	C	567.50
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____							
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total 57,112.06	
		Please acknowledge receipt of vehicle		Parts	48,365.30	GST 7.00%	3,997.84
				Labour	7,952.40	Less	0.00
				Sublet	794.36		
				Lubrication/Fluid	0.00		
				Others	0.00	Amount Due	61,109.90

Customer Copy

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 584A

Vehicle Details

Vehicle No.: SME375M
Vehicle to be Exported: No
Intended Deregistration Date: 15 Feb 2021
Vehicle Make: TOYOTA
Vehicle Model: HARRIER G GRADE
Primary Colour: Black
Manufacturing Year: 2018
Engine No.: 8ARZ130620
Chassis No.: JTEKB3GH10J002653
Maximum Power Output: 170.0 kW (227 bhp)
Open Market Value: \$35,783.00
Original Registration Date: 14 Sep 2018
First Registration Date: 14 Sep 2018
Transfer Count: 0
Actual ARF Paid: \$42,097.00 21048
Intended PARF Rebate Details
PARF Eligibility: Yes
PARF Eligibility Expiry Date: 13 Sep 2028
PARF Rebate Amount: \$31,572.00
Intended COE Rebate Details
COE Expiry Date: 13 Sep 2028
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$32,429.00
COE Rebate Amount: \$24,578.00
Total Rebate Amount: \$56,150.00

The information contained herein is correct as at 15 Feb 2021

OK

sgCARMART.COM

Login Sign up

New Cars Used Cars Rental Cars Sell My Car Directory Products Insurance Articles Forum Resources



Get Inspired.
Drive the Best from Select

Select
By Toyota's Premium Dealer

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Not Your Average Scirocco. Solid Power And Handling.



Forged Engine. Reliable. Good
FC. Excellent Power And
Handling.
Direct Owner StarAd

PRIME MOTOR & LEASING

JOHNSON YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

Sort by Date Posted 20 results/page

17 vehicles

Toyota Harrier

Advanced Search Submit

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Harrier	Any	Any	2018	Any	Any	Any	Available
	Toyota Harrier 2.0A Elegance	\$102,800	\$11,930 /yr	11-May-2018	1,986 cc	30,000 km	SUV	Available
Lowest Depreciation! Sincere Seller With Full Servicing From Reputable Jack Cars Workshop, It Was Serviced And Maintenance By Them...								PREMIUM AD
Posted: 10 Feb 2021 Tags: 2018 Toyota Harrier, Toyota Harrier, Toyota, Harrier								
	Toyota Harrier 2.0A M-Grade Turbo	\$112,800	\$13,220 /yr	30-Apr-2018	1,998 cc	59,000 km	SUV	Available
Borneo Motors Unit. One Owner. White Pearl Exterior And Black Ultrasuede Interior Seats. The Last Few Batches Of Turbo Unit. Most Po... Inchape Pre-Owned								PREMIUM AD
Posted: 10 Feb 2021 Tags: 2018 Toyota Harrier, Toyota Harrier, Toyota, Harrier								
	Toyota Harrier 2.0A M-Grade Turbo	\$107,988	\$12,550 /yr	30-Apr-2018	1,998 cc	-	SUV	Available
Fully Maintained By Borneo Motors With Full Servicing Record, Still Under Warranty. Low Interest Rate/Flexible Bank/In House Loan Avail... Carz World Pte Ltd								PREMIUM AD
Posted: 10 Feb 2021 Tags: 2018 Toyota Harrier, Toyota Harrier, Toyota, Harrier								
	Toyota Harrier 2.0A G-Grade	\$119,800	\$12,900 /yr	30-Nov-2018	1,998 cc	51,000 km	SUV	Available
Free Servicing And Warranty Till Nov 2023. Agent Unit. Immediate Transfer Ownership. Attractive Interest For Loan. 1 Owner Only. Rea...								
Posted: 10 Feb 2021 Tags: 2018 Toyota Harrier, Toyota Harrier, Toyota, Harrier								
	Otocar Jet Auto Service Pte Ltd - Repair & Servicing At Otocar Jet Auto, they are committed to care for your cars and service, customers satisfaction is our top priority. More info about this shop							
	Toyota Harrier 2.0A M-Grade Turbo	\$113,800	\$13,540 /yr	26-Mar-2018	1,998 cc	38,000 km	SUV	Available
1 Owner, Very Low Mileage Done, Latest Arrival! Drive Home With Safe Peace Of Mind With Valid Agent Warranty Till Mar 2023, Carefully...								
Posted: 09 Feb 2021 Tags: 2018 Toyota Harrier, Toyota Harrier, Toyota, Harrier								
	Toyota Harrier 2.0A M-Grade Turbo	\$112,800	\$13,460 /yr	13-Mar-2018	1,998 cc	43,179 km	SUV	Available
1 Owner. Under 5 Years Warranty With Agent Borneo Motors. Beautiful Original Pearl White Paintwork. Neat And Tidy Interior. New " S...								
Posted: 09 Feb 2021 Tags: 2018 Toyota Harrier, Toyota Harrier, Toyota, Harrier								
	Toyota Harrier 2.0A M-Grade Turbo	\$112,800	\$13,110 /yr	22-May-2018	1,998 cc	68,000 km	SUV	Available
1 Owner Only. Under Agent Warranty. In-House Loan And Bank Loan Available. Low Depreciation. High Approval Rate. Immediate Deliv...								
Posted: 08 Feb 2021 Tags: 2018 Toyota Harrier, Toyota Harrier, Toyota, Harrier								
Compare	Toyota Harrier 2.0A Premium Panoramic	\$104,800	\$11,940 /yr	05-Apr-2018	1,986 cc	32,000 km	SUV	Available