



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

*not authorized
Alan
Edo p/hlo sebua p/nding
16/2/21
A/P. 36828-16 Phys.*

ESTIMATE

Account Details	Account No.	Customer Details
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / ICIII1	Mr Kuo Chung-Liang 528 East Coast Road #04-04 Singapore 458969 Mobile: 81230929
	Document No. 0	
	Document Date 15/02/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ASU60R	ANTGT L1	14/09/2018	SME0375M	0	20721	67/TP/SME0375M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEKB3GH10J002653	8ARZ130620	60	Sam San Joi	15/02/2021 8.35	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-MS SUNDRIES TP-CLAIM PTP-SMN5515X ACC DATE:10/02/2021 TOW IN:10/02/2021 DATE-IN:10/02/2021 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				30.00
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON FRT ACCIDENT AREAS				366.36
3	S	BP-SUBLET FRT NUMBER PLATE				68.00
4	B	BP-LAB2 DRILL HOLE & INSTALL FRT SENSOR ✓				180.00
5	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM ✓				122.40
6	B	BP-LAB2 REMOVE & INSTALL AIRCON CONDENSER ASSY A ND CHARGE UP GAS				360.00
7	Z	BP-SLANT SUPPLY SEALANT (NETT)- BONNET, FRT SUPPO RT PANEL				120.00
8	S	BP-SUBLET TO CONDUCT ADJUSTMENT ON FRT WAVE RADAR ✓ SENSOR				180.00
9	S	BP-SUBLET TO RESET ECU AND REPROGRAMME ✓				180.00
10	B	BP-LAB2 REPLACE FRT ACCIDENT DAMAGED PART STRAIGHTEN & ALIGN FRT ACCIDENT AFFECTED AREAS 720x4				3600.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details	
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1	Mr Kuo Chung-Liang	
		Document No. 0	528 East Coast Road #04-04 Singapore 458969	
		Document Date 15/02/2021	Mobile: 81230929	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ASU60R	ANTGT L1	14/09/2018	SME0375M	0	20721	67/TP/SME0375M
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTEKB3GH10J002653		8ARZ130620	60	Sam San Joi	15/02/2021 8.35		--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	B	BP-RES2 RESPRAY JOB ON FRT ACCIDENT AFFECTED ARE 590x55 AS			2950	3540.00
12	1	T52119-4D946 COVER, FR BUMPER <i>DIS</i>	1.00	811.30	///	811.30
13	2	T52536-48030 <i>nls</i> RETAINER, FR BUMPER <i>301</i>	1.00	115.20	///	115.20
14	3	T52535-48040 <i>ols</i> RETAINER, FR BUMPER <i>301</i>	1.00	115.20	///	115.20
15	4	S52161-0K040 CLIPS <i>nee</i>	10.00	4.10	///	41.00
16	5	T52614-48050 <i>ctr</i> ABSORBER, FR BUMPER <i>Torn</i>	1.00	112.20	///	112.20
17	6	T52021-48090 REINFORCEMENT <i>bar</i> <i>301</i>	1.00	521.70	///	521.70
18	7	T52612-48050 <i>nls</i> ABSORBER, FR BUMPER <i>Torn</i>	1.00	49.80	///	49.80
19	8	T52611-48210 <i>ols</i> ABSORBER, FR BUMPER <i>Torn</i>	1.00	49.80	///	49.80
20	9	T52029-48010 REINFORCEMENT <i>retink</i> <i>301</i>	1.00	301.10	///	301.10
21	0	T52538-48040 <i>nls</i> RETAINER, FR BUMPER <i>301</i>	1.00	117.40	///	117.40
22	1	T52537-48040 <i>ols</i> RETAINER, FR BUMPER <i>301</i>	1.00	117.40	///	117.40
23	2	T75392-42030 RETAINER, OUTSIDE <i>301</i>	2.00	11.20	///	22.40
24	3	L47749-50090 CLIP <i>301</i>	4.00	1.80	///	7.20
25	4	L53879-30050 <i>s.20</i> RETAINER, FR FENDER <i>301</i>	4.00	16.80	///	67.20
26	5	T53102-48081 GRILLE SUB-ASSY, <i>bumper</i> <i>301</i>	1.00	417.70	///	417.70
27	6	T53286-48090 <i>nls</i> COVER, FR BUMPER ARM <i>DIS</i>	1.00	38.80	///	38.80
28	7	T53285-48080 <i>ols</i> COVER, FR BUMPER ARM <i>DIS</i>	1.00	38.80	///	38.80
29	8	T52126-48100 <i>nls</i> BRACKET, FOG LAMP <i>301</i>	1.00	98.20	///	98.20

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Table with Account Details, Account No. (S1000006 / ICIII1), Document No. (0), Document Date (15/02/2021), and Customer Details (Mr Kuo Chung-Liang, 528 East Coast Road, Singapore 458969, Mobile: 81230929).

Table with vehicle specifications: Year (2018), Model (ASU60R), Variant (ANTGT L1), Reg. Date (14/09/2018), Reg. No. (SME0375M), Kilometers (0), Wip No. (20721), Order No. / Remarks (67/TP/SME0375M). Includes Chassis No., Engine No., Terms, SA / Counter, Vehicle In, and Collected On.

Main parts list table with columns: L, Cd, Job/Parts Description, Qty, Unit Price, Disc %, Amount. Includes handwritten notes and checkmarks for various parts like BRACKET, FOG LAMP, MOULDING SUB-ASSY, etc.

Summary table with columns: For & on behalf of (Borneo Motors (Singapore) Pte Ltd), Customer's Signature, Charge Summary (Parts, Labour, Sublet, Lubrication/Fluid, Others), Total, Less, Amount Due.

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / ICIII1	Mr Kuo Chung-Liang 528 East Coast Road #04-04 Singapore 458969 Mobile: 81230929
	Document No. 0	
	Document Date 15/02/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ASU60R	ANTGT L1	14/09/2018	SME0375M	0	20721	67/TP/SME0375M
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTEKB3GH10J002653	8ARZ130620	60	Sam San Joi	15/02/2021	8.35	--/------	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
50	9	T53896-48150 <i>ols</i> SHIELD, FR FENDER <i>17</i>	1.00	53.00	X	53.00 X
51	0	T53895-48150 <i>ols</i> SHIELD, FR FENDER <i>17</i>	1.00	53.00	X	53.00 X
52	1	T53420-48140 HINGE ASSY, HOOD, LH <i>17</i>	1.00	87.10	X	87.10 X
53	2	T53410-48140 HINGE ASSY, HOOD, RH <i>17</i>	1.00	87.10	X	87.10 X
54	3	T53510-48260 LOCK ASSY, HOOD <i>17</i>	1.00	164.60	X	164.60 X
55	4	T53208-48091 SUPPORT SUB-ASSY, <i>17</i>	1.00	407.30	X	407.30 X
56	5	T53205-48030 <i>ctr</i> SUPPORT SUB-ASSY, <i>R</i>	1.00	1111.90	X	1111.90 X
57	6	T53203-48130 SUPPORT SUB-ASSY, <i>R</i>	1.00	176.20	X	176.20 X
58	7	T53202-48090 SUPPORT SUB-ASSY, <i>R</i>	1.00	216.80	X	216.80 X
59	8	T16683-36100 PLATE, RADIATOR LWR <i>D/S</i>	1.00	121.90	X	121.90 X
60	9	T53159-48010 SEAL, RADIATOR <i>17</i>	1.00	56.50	X	56.50 X
61	0	T16697-36070 PLATE, RADIATOR SIDE <i>17</i>	1.00	90.90	X	90.90 X
62	1	T16695-36140 PLATE, RADIATOR SIDE <i>ols D/S</i>	1.00	53.70	X	53.70 X
63	2	T16693-36070 PLATE, RADIATOR SIDE <i>17</i>	1.00	73.40	X	73.40 X
64	3	T16691-36140 PLATE, RADIATOR SIDE <i>ols D/S</i>	1.00	55.10	X	55.10 X
65	4	T53867-48090 SEAL, FR FENDER TO <i>17</i>	1.00	50.00	X	50.00 X
66	5	T53866-48080 SEAL, FR FENDER TO <i>17</i>	1.00	51.10	X	51.10 X
67	6	T81185-48E40 UNIT, HEADLAMP <i>LH holder one</i>	1.00	6714.50	X	6714.50 X
68	7	T81145-48E40 UNIT, HEADLAMP <i>RH holder one</i>	1.00	6714.50	X	6714.50 X
69	8	T52134-48070 <i>ols</i> REINFORCEMENT, FR <i>17</i>	1.00	69.80	X	69.80 X

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	Account No.	Customer Details Mr Kuo Chung-Liang 528 East Coast Road #04-04 Singapore 458969 Mobile: 81230929
	S1000006 / ICIII1	
	Document No.	
	0	
	Document Date	
	15/02/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ASU60R	ANTGT L1	14/09/2018	SME0375M	0	20721	67/TP/SME0375M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEKB3GH10J002653	8ARZ130620	60	Sam San Joi	15/02/2021 8.35	--/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
70	9	T52133-48060 <i>ols</i> REINFORCEMENT, FR <i>sent</i>	1.00	69.80		69.80
71	0	T81156-48E30 BRACKET, HEADLAMP, A <i>sent</i>	1.00	31.60		31.60
72	1	T81116-48E30 BRACKET, HEADLAMP, A <i>sent</i>	1.00	31.60		31.60
73	2	T81056-48E30 COMPUTER SUB-ASSY, <i>^^</i>	1.00	1129.10		1129.10
74	3	T81016-48E30 COMPUTER SUB-ASSY, <i>^^</i>	1.00	1129.10		1129.10
75	4	T81108-47560 COMPUTER SUB-ASSY, <i>^^</i>	1.00	1173.40		1173.40
76	5	T81107-47560 COMPUTER SUB-ASSY, <i>^^</i>	1.00	1173.40		1173.40
77	6	L81220-48051 LAMP ASSY, FOG, LH <i>mis</i>	1.00	516.00		516.00
78	7	T81210-48051 LAMP ASSY, FOG <i>^^</i>	1.00	516.00		516.00
79	8	T81440-48010 <i>ols</i> LAMP ASSY, DAYTIME <i>^^</i>	1.00	907.60		907.60
80	9	T81430-48010 <i>ols</i> LAMP ASSY, DAYTIME <i>^^</i>	1.00	907.60		907.60
81	0	L89341-48040 C3 SENSOR, ULTRASONIC, <i>shub</i>	2.00	481.90		963.80
82	1	T89341-58060 C1 SENSOR, ULTRASONIC, <i>shub</i>	2.00	481.90		963.80
83	2	T89348-58150 C1 RETAINER, ULTRASONIC <i>ner</i>	2.00	21.30		42.60
84	3	T89348-58140 C1 RETAINER, ULTRASONIC <i>ner</i>	2.00	21.30		42.60
85	4	T89348-58120 RETAINER, ULTRASONIC <i>ner</i>	2.00	16.00		32.00
86	5	T89348-58130 CLIP, ULTRASONIC <i>ner</i>	2.00	12.30		24.60
87	6	T82219-78010 WIRE, SENSOR <i>^^</i>	1.00	253.30		253.30
88	7	T82113-48080 WIRE, ENGINE ROOM, <i>^^</i>	1.00	149.10		149.10
89	8	T85315-42360 JAR, WASHER, A <i>^^</i>	1.00	152.80		152.80

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary Parts Labour Sublet Lubrication/Fluid Others	Total
	Please acknowledge receipt of vehicle _____		Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details	
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1	Mr Kuo Chung-Liang 528 East Coast Road #04-04 Singapore 458969 Mobile: 81230929	
		Document No. 0		
		Document Date 15/02/2021		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ASU60R	ANTGT L1	14/09/2018	SME0375M	0	20721	67/TP/SME0375M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEKB3GH10J002653	8ARZ130620	60	Sam San Joi	15/02/2021 8.35	--/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
90	9	T85316-48230 CAP, WASHER, A <i>AA</i>	1.00	78.10	X	78.10
91	0	T88460-48160 CONDENSER ASSY <i>AA</i>	1.00	2044.10	X	2044.10
92	1	L16400-36100 RADIATOR ASSY <i>AA</i>	1.00	2634.40	X	2634.40
93	2	T16712-36050 SHROUD, FAN, NO.2 <i>AA</i>	1.00	117.40	X	117.40
94	3	T16550-36060 RADIATOR ASSY, <i>AA</i>	1.00	603.70	X	603.70
95	4	T17751-36090 INLET, AIR CLEANER <i>AA</i>	1.00	220.00	X	220.00
96	5	S08889-80102 COOLANT,SLLC&&& <i>AA</i>	1.00	79.50	X	79.50
97	6	T75770-48060 MOULDING ASSY, HOOD, <i>Cre</i>	1.00	567.50	X	567.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	57,112.06
	Please acknowledge receipt of vehicle	Parts 48,365.30 Labour 7,952.40 Sublet 794.36 Lubrication/Fluid 0.00 Others 0.00	GST 7.00% 3,997.84 Less 0.00 Amount Due 61,109.90	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details	
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1	Mr Kuo Chung-Liang 528 East Coast Road #04-04 Singapore 458969 Mobile: 81230929	
		Document No. 0		
		Document Date 06/04/2021		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ASU60R	ANTGT L1	14/09/2018	SME0375M	21062	20721	67/TP/SME0375M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEKB3GH10J002653	8ARZ130620	60	Sam San Joi	15/02/2021 8.35	--/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	1	T86520-48170 HORN ASSY, LOW	1.00	146.90	/	146.90
2	2	T88790-22131 THERMISTOR, COOLER	1.00	131.40	/	131.40
3	3	T90467-07217 CLIP	10.00	2.50	/	25.00

Handwritten notes: } ADD, cre, m.s, nu

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	303.30
	Please acknowledge receipt of vehicle	Parts 303.30 Labour 0.00 Sublet 0.00 Lubrication/Fluid 0.00 Others 0.00	GST 7.00%	21.23
			Less	0.00
			Amount Due	324.53

Customer Copy