

ORTDELGRO ENGINEERING PTE LTD

R ESTIMATE*

LE NO SHD3766M

DATE 12/02/21 12:00 AM

E HYUNDAI

MVA CHIANG/AIG

DEL I-40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR DOOR PANEL RH			\$2,201.10
1	ROCKER PANEL GARNISH RH			\$732.80
1	REAR RH FENDER PANEL			\$2,171.40
1	REAR TYRE RIM RH			\$650.60
1	FRONT/REAR WHEEL CAP RH			\$217.20
	SUB TOTAL		3151.10	\$5,973.10
	20.00%	256	2820.88	\$1,194.62
	DISCOUNTED TOTAL			\$4,778.48
1	REAR TYRE RIM RH			\$216.00
1	REAR DOOR ADVERTISEMENT			\$100.00
1	REAR DOOR COMFORT APP STICKER			\$80.00
1	REAR FENDER ADVERTISEMENT		280	\$100.00
	Labour Charge			\$496.00
	Panel Beating			\$750.00
	Spray Painting Charge			\$800.00
	Remove/refix door parts			\$180.00
	Tuff coat			\$120.00
	TOTAL LABOUR		1400	\$1,850.00
	ESTIMATE TOTAL		4200.88	\$7,124.48
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Tanphm 97495249
'WP' 5/2/21 12:00pm

3-4 days

in state

L/S Resurvey after repair
Tanphm c/hhantaw

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No legal modification is allowed
 - Supplemental claims must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: