

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883
Email: admin@cnmotorspl.com
Tel: 6509 5545 Fax: 6509 5567
UEN: 202026492W

02/01/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP A16.

Jasper

10/02/21.

Accident date: 31/12/2020

Estimated repair cost for vehicle no: SLQ2381E SUBARU FORESTER 2.0I-L CVT '17

CHASSIS: JF1SJ5KC5HG092435

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid		\$1,192.30
2	2	Rear Boot Lid Hinge	\$55.00	\$110.00
3	2	Rear Boot Lid Shock Absorber	\$154.00	\$308.00
4	1	Rear Boot Lid Emblem Logo		\$65.00
5	1	Rear Boot Lid Subaru Logo		\$68.00
6	1	Rear Boot Lid Forester Logo		\$68.00
7	1	Rear Boot Lid AWD Logo		\$65.00
8	1	Rear Boot Lid Number Plate	HP	\$50.00
9	1	Rear Boot Lid Inner Lock	NBC	\$560.30
10	1	Rear Boot Lid Weatherstrip		\$160.30
11	1	Rear Boot Lid Inner Trim Board		\$220.30
12	10	Rear Boot Lid Inner Trim Board Clip	\$6.50	\$65.00
13	1	Rear Boot Lid Windscreen Seal		\$85.00
14	2	Rear Boot Lid Windscreen Side Seal	\$75.00	\$150.00
15	1	Rear Boot Lid Reverse Camera		\$850.00
16	2	Rear Tail Lamp	\$437.30	\$874.60
17	2	Rear Tail Lamp Clip	\$8.00	\$16.00
18	1	Rear L/H Tail Lamp Panel		\$105.80
19	1	Rear L/H Tail Lamp Lower Bracket		\$38.00
20	1	Rear Bumper		\$980.30
21	10	Rear Bumper Clip	\$6.50	\$65.00
22	1	Rear L/H Bumper Side Retainer		\$38.00
23	1	Rear L/H Bumper Side Reflector		\$42.00
24	1	Rear Bumper Towing Cover		\$22.00
25	1	Rear L/H Bumper Exhaust Cover		\$76.80
26	1	Rear Bumper Reinforcement		\$320.80
27	2	Rear Bumper Reinforcement Bracket	\$28.60	\$57.20
28	1	Rear Bumper Reverse Sensor (Special Nett)		\$380.00
29	1	Rear L/H Fender		\$1,060.40
30	2	Rear Fender Inner Trim Board	\$486.30	\$972.60

X

600.30

30.

X.

✓

✓

✓

✓

+

+

+

+

31	8	Rear Fender Inner Trim Board Clip <i>new</i>	\$6.50	\$52.00	+
32	1	Rear End Panel <i>Dented</i>		\$332.00	✓
33	1	Rear End Panel Top Garnish <i>det d</i>		\$90.00	✓
34	1	Rear Spare Tyre Panel <i>Reps</i>		\$632.40	+
35	1	Rear Spare Tyre Panel Top Cover <i>det d</i>		\$336.00	✓
36	1	Rear Spare Tyre Panel & End Panel Sealant <i>new</i>		\$450.00	+
37	2	Rear Spare Tyre Panel Side Foam Tool Box <i>HH cnd</i>	\$85.50	\$171.00	85.50
38	1	Rear Spare Tyre Panel Foam Tool Box <i>cnd</i>		\$161.20	✓
39	1	Rear Centre Exhaust <i>new</i>		\$1,048.40	+

2092.60

Subtotal :- \$12,339.70

1674.08

S.N: 200

Labour charges

To remove & refit cushion & trim board	\$280.00 60
To remove & refit reverse sensor	\$100.00 50
To remove & refit reverse camera	\$180.00 +
To remove & refit rear windscreen	\$150.00 +
To remove & refit rear exhaust	\$200.00 +
Gum	\$60.00 +
To check wiring	\$100.00 30
Tuff kote	\$150.00 60
Panel beating	\$2,400.00 800
Spray painting	\$2,000.00 700

Subtotal :- \$5,620.00

Total:- \$17,959.70

Total: 3574.08

L/s: 2.8K

05 Days

2.8K

05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: