

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883  
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
 GST:201300201N

**M/S :** AUTO & GENERAL INSURANCE (S) PTE LTD  
 190 CLEMENCEAU AVE #03-01  
 SINGAPORE SHOPPING CENTRE  
 SINGAPORE 239924

**Estimate No:** EST2100047  
**Date:** 15 Feb 2021

TEL: 6221 2199 FAX: 6725 0853  
 ATTN: Motor Claim Department \ Motor Claim

**Veh Reg No:** SMC2377E  
**Make/Model:** TOYOTA VIOS E AUTO  
**Chasis No:** MR2B23F3901121246  
**Reg. Date:** 28/06/2018  
**Your Ref No:** SLE482Z

**Claim Type:** Third Party  
**Accident Date:** 11/02/2021  
**TP Veh Reg No:** SLE482Z

## Estimate Repair Cost to Vehicle No :SMC2377E

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	<b>List Price</b>		
1	1 PC BOOT LID	855.50	
2	1 PC BOOT LID LOGO	52.20	
3	1 PC BOOT LID "VIOS" EMBLEM	43.60	
4	1 PC BOOT LID "E" EMBLEM	38.60	
5	1 PC BOOT LID LAMP LH	279.80	
6	1 PC BOOT LID LAMP RH	279.80	
7	1 PC BOOT LID LOCK	320.40	
8	1 PC BOOT LID LOCK CHECKER	28.90	
9	1 PC BOOT LID RUBBER	166.40	
10	1 PC BOOT LID TRIM	208.90	
11	1 PC REAR PANEL	628.70	
12	1 PC REAR PANEL TRIM	262.30	
13	1 PC TAIL LAMP LH	397.10	
14	1 PC TAIL LAMP - RH	397.10	
15	1 PC REAR BUMPER	482.20	
16	1 PC REAR BUMPER REINFORCEMENT	316.10	
17	2 PCS REAR BUMPER SIDE RETAINER	333.00	
18	2 PCS REAR BUMPER RETAINER - SMALL	145.40	
19	1 PC REAR BUMPER REFLECTOR - LH	102.80	
20	1 PC REAR RH MUDFLAP	76.90	
		<u>5,415.70</u>	
	Less 25%	<u>1,353.93</u>	4,061.82
	<b>Special Net</b>		
21	1 PC BOOT LID NUMBER '611' STICKER	35.00	
22	1 SET BOOTLID TRIM CLIPS	40.00	
23	1 SET REAR PANEL TRIM CLIPS	30.00	
24	1 SET REAR FENDER TRIM CLIPS RH	40.00	
25	1 SET REAR FENDER TRIM CLIPS LH	40.00	
26	2 PCS "L" PLATE BRACKET	70.00	

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883  
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD  
190 CLEMENCEAU AVE #03-01  
SINGAPORE SHOPPING CENTRE  
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853  
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party  
Accident Date: 11/02/2021  
TP Veh Reg No: SLE482Z

Estimate No: EST2100047  
Date: 15 Feb 2021

Veh Reg No: SMC2377E  
Make/Model: TOYOTA VIOS E AUTO  
Chasis No: MR2B23F3901121246  
Reg. Date: 28/06/2018  
Your Ref No: SLE482Z

## Estimate Repair Cost to Vehicle No :SMC2377E

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
27	1 SET REAR BUMPER STICKER	280.00	
28	1 SET REAR BUMPER CLIPS	40.00	
29	1 SET REAR RH MUDFLAP CLIPS	20.00	
		595.00	595.00
	<b>Labour</b>		
30	1 TO CHECK WIRING	50.00	
31	1 TO REPLACE STICKERS	80.00	
32	1 TO SPRAY UNDERSEAL	100.00	
33	1 (REAR) TO SPRAY PAINTING	1,000.00	
34	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00	
		2,230.00	2,230.00
		Total	S\$ 6,886.82
		Add GST @ 7%	482.08
		Total Amount Payable	<u>S\$ 7,368.90</u>

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND THREE HUNDRED SIXTY EIGHT AND CENTS NINETY ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE