

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
 190 CLEMENCEAU AVE #03-01
 SINGAPORE SHOPPING CENTRE
 SINGAPORE 239924

Estimate No: EST2100047
 Date: 15 Feb 2021

TEL: 6221 2199 FAX: 6725 0853
 ATTN: Motor Claim Department \ Motor Claim

Veh Reg No: SMC2377E
 Make/Model: TOYOTA VIOS E AUTO
 Chasis No: MR2B23F3901121246
 Reg. Date: 28/06/2018
 Your Ref No: SLE482Z

Claim Type: Third Party *Xiao Chen.*
 Accident Date: 11/02/2021
 TP Veh Reg No: SLE482Z

Estimate Repair Cost to Vehicle No :SMC2377E

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BOOT LID <i>Dented</i>	855.50 ✓	
2	1 PC BOOT LID LOGO	52.20 ✓	
3	1 PC BOOT LID "VIOS" EMBLEM <i>new</i>	43.60 ✓	
4	1 PC BOOT LID "E" EMBLEM	38.60 ✓	
5	1 PC BOOT LID LAMP LH <i>new</i>	279.80 +	
6	1 PC BOOT LID LAMP RH	279.80 +	
7	1 PC BOOT LID LOCK <i>Dented</i>	320.40 ✓	
8	1 PC BOOT LID LOCK CHECKER <i>new</i>	28.90 t.	
9	1 PC BOOT LID RUBBER <i>ut</i>	166.40 ✓	
10	1 PC BOOT LID TRIM <i>new</i>	208.90 +	
11	1 PC REAR PANEL <i>Dented</i>	628.70 ✓	3976.60
12	1 PC REAR PANEL TRIM <i>Dented</i>	262.30 ✓	
13	1 PC TAIL LAMP LH <i>new</i>	397.10 ✓	2982.45
14	1 PC TAIL LAMP - RH <i>new</i>	397.10 +	
15	1 PC REAR BUMPER <i>Dented</i>	482.20 ✓	
16	1 PC REAR BUMPER REINFORCEMENT <i>Dented</i>	316.10 ✓	
17	2 PCS REAR BUMPER SIDE RETAINER <i>new</i>	333.00 ✓	145
18	2 PCS REAR BUMPER RETAINER - SMALL <i>new</i>	145.40 t.	
19	1 PC REAR BUMPER REFLECTOR - LH <i>new</i>	102.80 ✓	
20	1 PC REAR RH MUDFLAP <i>new</i>	76.90 +.	
	<i>Res End Panel Antenna sensor</i> 165.70 ✓	5.415.70	
	<i>new</i>	Less 25%	4.061.82
	Special Net		
21	1 PC BOOT LID NUMBER '611' STICKER <i>new</i>	35.00 ✓	
22	1 SET BOOTLID TRIM CLIPS <i>new</i>	40.00 +.	
23	1 SET REAR PANEL TRIM CLIPS <i>new</i>	30.00 ✓	10
24	1 SET REAR FENDER TRIM CLIPS RH <i>new</i>	40.00 +	
25	1 SET REAR FENDER TRIM CLIPS LH <i>new</i>	40.00 +	
26	2 PCS "L" PLATE BRACKET <i>new</i>	70.00 ✓	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
 190 CLEMENCEAU AVE #03-01
 SINGAPORE SHOPPING CENTRE
 SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853
 ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
 Accident Date: 11/02/2021
 TP Veh Reg No: SLE482Z

Estimate No: EST2100047

Date: 15 Feb 2021

Veh Reg No: SMC2377E

Make/Model: TOYOTA VIOS E AUTO

Chasis No: MR2B23F3901121246

Reg. Date: 28/06/2018

Your Ref No: SLE482Z

Estimate Repair Cost to Vehicle No :SMC2377E

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
27	1 SET REAR BUMPER STICKER <i>new</i>	280.00 ✓	
28	1 SET REAR BUMPER CLIPS <i>new</i>	40.00 30	
29	1 SET REAR RH MUDFLAP CLIPS <i>new</i>	20.00 *	
	Beck End Panel Antenna Sensor <i>165.20</i>	595.00	595.00
	Labour <i>'k' Plate 70</i>		
30	1 TO CHECK WIRING <i>Self</i>	50.00 30	
31	1 TO REPLACE STICKERS	80.00 * 50	
32	1 TO SPRAY UNDERSEAL	100.00 60	
33	1 (REAR) TO SPRAY PAINTING	1,000.00 800	
34	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00 800	
	<i>To remove upholstery.</i>	120 80	2,230.00
	<i>To transfer bootlid fittings.</i>	120 80	2,230.00
		Total	SS 6,886.82
		Add GST @ 7%	482.08
		Total Amount Payable	<u>SS 7,368.90</u>

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND THREE HUNDRED SIXTY EIGHT AND CENTS NINETY ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

total: 5337.45
A/S: 43K.
43K
Adrian
1/5 16/02/21
06 yrs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: