



KGC WORKSHOP PTE LTD

Sincere • Secure • Satisfaction

Since 1967

Not Withheld

8
Pruning After Paint

2 days

8 1407.44

Lai Siu Kei
14 Ang Mo Kio St 63
Block B
Singapore 569116

TP210202
Date 15/2/2021
No of Page : 1/1

Registration No : SMF 9625C

Accident Date : 9-Feb-21

Our Ref : TP 210202

Model : Hyundai Elantra AD GLS AT

Chassis No: KMHD841CMHU143719

Engine Capacity 1.6cc

S/No	Qty	Items	Unit Price	Amount
1	1	Rear Bumper 459.40	\$ 845.70	\$ 845.70 ✓
2	1	Rear Lower Bumper 280.10	\$ 412.00	\$ 412.00 ✓
3	2	Rear Bumper Retainer	\$ 32.50	\$ 65.00 ✓
4	1	Rear Bumper reflector RHS	\$ 85.00	\$ 85.00 ✓
5	1	Rear Bumper reflector LHS	\$ 85.00	\$ 85.00 ✓
6	1	Rear Bumper reinforcement 294.80	\$ 480.00	\$ 480.00 ✓
7	1	Rear end Panel	\$ 525.00	\$ 525.00 ✓

Special Nett

1	1 set	Rear Bumper Clips
2	1 set	Reverse Sensor

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

	\$	2,497.70
-20%	\$	499.54
Total for spare parts	\$	1,998.16
	\$	50.00
	\$	380.00
Total for SP	\$	430.00
Sub-Total for Parts :	\$	2,428.16

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts	600.00	2501
2		To putty and spray paint on all accident damage parts and other accident	600.00	229
3		To check wiring system to facilitate repair and refit the same	80.00	101
4		To remove and refit reverse sensor and conduct safe distance setting	80.00	501
5		Apply rust proofing on the adjacent panels	na	50.00 X

TOTAL AMOUNT : 1,410.00
OVERALL COST : 3,838.16