

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF578Z****AAD2102-045***Not Authored**Recovery Bypaint**810201*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**15 FEB 2021****SHF578Z**

JTDKB3FU603092731

TOYOTA

PRIUS GEN 4

08/02/2021

**AIG**

20/11/2020

PART		LIST	
1	COVER, REAR BUMPER	\$	485.60
1	GUARD, REAR BUMPER, CENTER	\$	374.50
1	REAR BUMPER TOWING COVER	\$	22.00
1	SEAL, REAR BUMPER SIDE, RH	\$	118.30
1	RETAINER, REAR BUMPER SIDE, RH	\$	132.60
1	PANEL SUB-ASSY, QUARTER, RH	\$	871.50
1	LINER, REAR WHEEL HOUSE, RH	\$	139.80
1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	594.80
1	PANEL SUB-ASSY, REAR DOOR, RH	\$	1,294.90
1	HINGE ASSY, REAR DOOR, LOWER RH	\$	87.10
1	HINGE ASSY, REAR DOOR, UPPER RH	\$	98.90
<b>TOTAL</b>		<b>\$</b>	<b>4,220.00</b>
<b>25%</b>		<b>\$</b>	<b>1,055.00</b>
		<b>\$</b>	<b>3,165.00</b>

**Special Nett**

1	REAR BUMPER SIDE CLIP	\$	60.00	X
1	REAR FENDER LINER CLIP	\$	65.00	X
1	RIM	\$	1,879.40	X
1SET	PARKING AID	\$	700.00	X
1SET	REAR BUMPER CLIP	\$	85.00	X
1	REAR BUMPER RETAINER CLIP	\$	75.00	X
1	BUMPER CENTRE GUARD CLIP	\$	80.00	X
1	REAR DOOR STICKER '6555-3333'	\$	80.00	60.00
1	REAR BUMPER PROTECTOR	\$	180.00	X
<b>TOTAL</b>		<b>\$</b>	<b>2,864.40</b>	

**Trans-cab Auto Services Pte Ltd**

AAD2102-045

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF578Z

**TOTAL PARTS \$ 6,029.40****LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ *nn* 240.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,600.00 *300*

To transfer of rear end panel fittings, attachment to facilitate bodywork repair.

\$ *nn* 380.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00 *660*

To reinstall rear bumper parking sensor.

\$ *nn* 170.00 X

To transfer of tire, rim and on wheel balancing.

\$ *4* 170.00 X

To Check Electrical Lighting Concerned.

\$ *4* 170.00 X

To check steering geometry and computer wheel alignment

\$ *4* 220.00 X

To remove and refit of rear fender fittings, attachment and perform water seepage test.

\$ *4* 170.00 X**TOTAL \$ 5,100.00****Over All Total \$ 11,129.40****(PART-BY-PART) Repair Days***10 Days**2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: