

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF665E**

**AAD2102-040**

*NOT Authorized  
Resurvey B4 point  
\$3755.70*

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :  
Date of Registration :

15 FEB 2021

**SHF665E**  
JTDKB3FU903091301  
TOYOTA  
PRIUS GEN 4  
08/02/2021  
**AIG**  
14/08/2020

PART	LIST	
1 FENDER SUB-ASSY, FRONT LH	\$ R	977.80 X
1 EMBLEM, SIDE PANEL	\$ Na	54.60 ✓
1 PANEL SUB-ASSY, FRONT DOOR, LH	\$ B4 point	1,300.70 ✓
1 WEATHERSTRIP, FRONT DOOR, LH	\$ Sn	231.30 X
1 HINGE ASSY, FRONT DOOR, LOWER LH	\$ R	110.60 X
1 HINGE ASSY, FRONT DOOR, UPPER LH	\$ R	97.50 X
1 TAPE, BLACK OUT, NO.1 FRT LH	\$ Na	13.30 —
1 TAPE, BLACK OUT, NO.2 FRT LH	\$ Na	43.50 —
1 TAPE, BLACK OUT, NO.3 FRT LH	\$ Na	26.30 —
1 MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH	\$ Sn	926.00 X
1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	\$ Sn	238.30 X
1 PANEL SUB-ASSY, REAR DOOR, LH	\$ R	1,294.90 X
1 WEATHERSTRIP, REAR DOOR OPENING TRIM, LH	\$ Sn	293.00 X
1 HINGE ASSY, REAR DOOR, LOWER LH	\$ R	87.10 X
1 HINGE ASSY, REAR DOOR, UPPER LH	\$ R	98.90 X
1 TAPE, BLACK OUT, NO.1 REAR LH	\$ Na	21.90 X
1 TAPE, BLACK OUT, NO.2 REAR LH	\$ Na	34.90 X
1 TAPE, BLACK OUT, NO.3 REAR LH	\$ Na	15.40 X
1 MOTOR ASSY, POWER WINDOW REGULATOR, LH	\$ Sn	926.00 X
1 REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH	\$ Sn	206.70 X
1 PANEL SUB-ASSY, QUARTER, LH	\$ R	871.50 X
1 LINER, REAR WHEEL HOUSE, LH	\$ Sn	139.80 X
1 MOULDING ASSY, BODY ROCKER PANEL, LH	\$ Na	594.80 ✓
<b>TOTAL</b>	<b>\$</b>	<b>8,604.80</b>
<b>25%</b>	<b>\$</b>	<b>2,151.20</b>
	<b>\$</b>	<b>6,453.60</b>

*0030-80  
1258-80  
0033-80*

**Trans-cab Auto Services Pte Ltd**

**AAD2102-040**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF665E**

**Special Nett**

2 FENDER CLIP	\$	<i>Nn</i> 130.00 X
1 FENDER LINER CLIP	\$	<i>Nn</i> 65.00 X
1 FRT BUMPER CLIP	\$	<i>Nn</i> 65.00 X
2SET DOOR WEATHERSTRIP CLIP	\$	<i>Nn</i> 130.00 X
1 FRT DOOR STICKER TRANSCAB	\$	<i>Nn</i> 100.00 <i>601n</i>
1 TYRE	\$	<i>Sm</i> 350.00 X
1 RIM	\$	<i>Sm</i> 1,879.40 X
1 HUB CAP <i>175.80</i>	\$	<i>Nn</i> 211.50 ✓
1SET CLIP, ROCKER PANEL MOULDING	\$	<i>Nn</i> 65.00 ✓
<b>TOTAL</b>	<b>\$</b>	<b>2,995.90</b>

**TOTAL PARTS \$ 9,449.50**

**LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 *601*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,400.00 *5001*

Putty And Spray Painting Of The Affected Portion.

\$ 1,400.00 *13201*

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 240.00 *301*

To Check Electrical Lighting Concerned.

\$ 170.00 *201*

**TOTAL \$ 3,590.00**

**Over All Total \$ 13,039.50**

**(PART-BY-PART) Repair Days**

*20 days*

*5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: