

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI21002164/T1QD3E2

Date: 11/03/2021

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	ML000124
Claimant Vehicle No :	SHD4545C	Insured Vehicle No :	SLP4936Y
Date of Loss:	11/02/2021	Nature of Claim:	TP
		Claim No:	M2100789

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD4545C	Engine No:	G4LEKU410411
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVLU190360
Reg. Date:	19/12/2019 (Man. Year: 2019)	Odometer:	67589 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	769.44	21.28	748.16	97.23
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,000.00	850.00	150.00	15.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,780.44	882.28	898.16	50.45
+ GST 7.00/7.00% (S\$)	124.63	61.76	62.87	50.45
Nett Amount (S\$)	1,905.07	944.04	961.03	50.45

INSPECTION

Date of Assignment:	16/02/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	15/02/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang)
			59 Loyang Drive
			Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Mar 2021)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD4545C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRT FENDER RH	Repair	588.80 FL	-	*- FL
2	1		*FRT FENDER BLUE-DRIVE RH	Necessary	26.60 FL	-	*26.60 FL
3	1		*FRT WHEEL CAP RH (Cut)	Old Damaged	346.40 FL	-	*- FL
					Sub Total (\$\$)	961.80	26.60
					- List Item Discount on L Items 20.00/20.00% (\$\$)	192.36	5.32
					Total Parts (\$\$)	769.44	21.28

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING	New	600.00	500.00
Gross Labour Cost (\$\$)			1,000.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >