



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for Ong Joo Leong and vehicle SKS4896A.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Includes account CSM00041.

Main estimate table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various repair items like bumper, fender, and electrical system.

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info | |
|-----------------------------|---------------------------|----------------------------------|
| Ong Joo Leong | Cust No/Name | /Ong Joo Leong |
| Blk 604 Senja Road | Reg No/Reg Date | SKS4896A / 20/04/201 |
| #17-21 | Date In/Mileage | / 88252 |
| Singapore 670604 | Chassis No | JMYSRCY1AFU004153 |
| Contact No Mobile: 90938093 | Engine No | 4A92BT6268 |
| | Make/Model | MIT/LANCER EX 1.6 GLS 4A/T (F05) |
| | Colour/Trim | PO2 / BK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | Qty | Unit Price | Disc% | Amount |
|---------------------------------|----------------------------|-------------------|-----|-----------------|--------|------|-------------------|-------|--------|
| CSM00041 | Cash | 15/02/2021/ 11:24 | QUA | 265 / AndreChow | 62907 | | | | |
| Description of Goods / Services | | | | | | | | | |
| M | HINGE, TRUNK LID, LH | X NM | | | | 1.00 | 93.00 | 00.00 | 93.00 |
| M | WEATHERSTRIP, TRUNK LID | CRU | | | | 1.00 | 184.00 | 00.00 | 184.00 |
| M | STRIKER, TRUNK LID LATCH | X NM | | | | 1.00 | 24.00 | 00.00 | 24.00 |
| M | LATCH, TRUNK LID | X NM | | | | 1.00 | 74.00 | 00.00 | 74.00 |
| M | PANEL, TRUNK LID | OO | | | | 1.00 | 768.00 | 00.00 | 768.00 |
| M | MARK, THREE-DIA | RC | | | | 1.00 | 69.00 | 00.00 | 69.00 |
| M | MARK, EX | RC | | | | 1.00 | 41.00 | 00.00 | 41.00 |
| M | REFLECTOR | X NM | | | | 1.00 | 37.00 | 00.00 | 37.00 |
| M | LAMP ASSY, LICENSE PLATE | X NM | | | | 1.00 | 35.00 | 00.00 | 35.00 |
| M | LAMP AS, HIGH MOUNTED STOP | X NM | | | | 1.00 | 373.00 | 00.00 | 373.00 |

Estimate

SURVEYOR NAME : Steve (LKK)
 SURVEYOR SIGNATURE : OO-NM AL
 DATE : EXPIRE - ?
 REMARKS : PIP
My PL say
6 & days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To notify damaged parts before resurvey

Confirm & accepted by _____ subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Authorized signatory and company stamp

| | | |
|----------------------|---------|-----------------|
| | Nett | 8,461.00 |
| 7% GST on | 8461.00 | 592.27 |
| Total Payable | | 9,053.27 |

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.