



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/III20010618/Qqf3e2-1	
			Date: 09/03/2021	
			Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 6974H	Veh. Inspected	SMC 6662E
	Policy No.	MCOM0015	Coverage (\$)	0.00
	Claim No.	MCT20090238	Excess (\$)	0.00
	Assign From	CARINE KEK PHEI SER	Assign Date	16/02/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA LEXUS RX350	c.c	3456
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	JTJBK11AX02423153	Colour	GREY
	Odometer	194597 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/60 R18	MICHELIN	6 mm
	L/H Front Tyre	235/60 R18	MICHELIN	6 mm
	R/H Rear Tyre	235/60 R18	MICHELIN	6 mm
	L/H Rear Tyre	235/60 R18	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	16/09/2020	Inspection Date	05/10/2020
	Survey held at	SHENG KHOON MOTOR SERVICE 393 WOODLANDS ROAD BLK D4 YEE TEE INDUSTRIAL ESTATE SINGAPORE 677972		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	