

QUOTATION

NO. : 37746

LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWER
SINGAPORE 189702

ATTN: LONPAC INSURANCE BHD

VEHICLE NO. : FBL7432D
MAKE/MODEL : SYM / MAXSYM 400I CVT

DATE : 14/01/2021
CLAIM NO. : 11685
POLICY NO. : 5113921882-01
FROM : HASRIANAH

(Page 1 of 11)

S/N	Description	Action	Qty	Unit Price	Amount
1	ABS DETECTIVE DISK - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	17.00
2	ALIGNMENT BODY P/N: 29561 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$392.00	392.00
3	AXLE HANGER ENG P/N: 55080 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	16.00
4	BALANCER HANDLE P/N: 29008 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$37.00	37.00
5	BALL BEARING 6003 P/N: 61999 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$16.00	32.00
6	BALL RACE SET P/N: 57433 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$112.00	112.00
7	BALL STEERING UPPER P/N: 54481 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00	19.00
8	BAR HANDLE P/N: 56670 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$51.00	51.00
9	BEARING P/N: 55114 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$26.00	26.00

*37746 *

bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
10	BEARING P/N: 55059 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	31.00
11	BEARING 6203-2NS (NACHI) P/N: 36830 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	14.00
12	BEARING 6204-2NS (NACHI) P/N: 29215 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$14.00	28.00
13	BEARING 6205-2NS (NACHI) P/N: 48795 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	14.00
14	BOX FR-INNER P/N: 55078 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$66.00	66.00
15	BOX REAR (GIVI) V56N MAXIA 4 P/N: 54026 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$665.00	665.00
16	BRACKET BOX REAR (GIVI) P/N: 54025 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$210.00	210.00
17	BREATHER JOINT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	5.00
18	CAM CHAIN GUIDE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
19	CAM CHAIN TENSIONER P/N: 56059 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
20	CHAIN TIMING P/N: 55456 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$82.00	82.00
21	COIN BOX LH.LID BK-001U P/N: 57438 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$20.00	20.00
22	COLLAR P/N: 64648 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$3.00	12.00
23	COLLAR MAINSTAND 1 P/N: 65220 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$7.00	14.00
24	CON-ROD BRG.(37*44*20) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	17.00
25	CON-ROD BRG.(37*44*20) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	17.00

*37746 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
26	COOLANT (MOBIL) ANTIFREEZE P/N: 60213 - (REPORTED BY MECHANIC)	REPLACE	3.00	\$17.00	11 51.00 X
27	COVER CARB.INSULATOR P/N: 55452 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	11 14.00 X
28	COVER FRONT STAY P/N: 55096 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$168.00	eng 168.00
29	COVER L-BODY ASSY P/N: 65680 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$198.00	eng 198.00
30	COVER L-CRANK CASE P/N: 55121 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$256.00	eng 256.00
31	COVER LIGHT BOX V56N P/N: 63376 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$79.00	eng 79.00
32	COVER OUTER ASSY .BK-001U P/N: 55354 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$119.00	eng 119.00
33	COVER R-BODY ASSY P/N: 55123 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$199.00	eng 199.00
34	COVER UNDER SPOILER FRONT P/N: 57449 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$262.00	eng 262.00
35	DAMPER BOX INNER LID P/N: 56666 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	eng 12.00
36	DAMPER COVER TAIL RH P/N: 56673 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	eng 10.00
37	ENG HANGER HNK ASSY P/N: 55069 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$294.00	eng 294.00 X
38	EXH.MUFFLER ASSY P/N: 55107 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$2,548.00	eng 2,548.00 X
39	FILTER COVER CAP CRANKCASE P/N: 55076 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	eng 8.00 X
40	FILTER OIL P/N: 49485 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$18.00	eng 18.00 X
41	FINAL SHAFT P/N: 55561 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$168.00	eng 168.00 X

*37746 *

bizSAFE₃CERT NO : 2002-1-0363
ISO 9001 : 2015

S/N	Description	Action	Qty	Unit Price	Amount
42	FLANGE BOLT 8X16 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	10.00
43	FORK FRONT RH ASSY P/N: 57441 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$432.00	432.00
44	FORK TOP BRIDGE P/N: 64952 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$195.00	195.00
45	FR FENDER GY-517S P/N: 57032 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$94.00	94.00
46	FR.WHEEL AXLE P/N: 64948 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$84.00	84.00
47	GASKET P/N: 55116 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	5.00
48	GASKET P/N: 55085 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$9.00	9.00
49	GASKET COVER CARB.INSULATOR P/N: 55106 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	5.00
50	GASKET COVER CRANKCASE P/N: 55100 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$30.00	30.00
51	GASKET CYLINDER BLOCK P/N: 55063 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	13.00
52	GASKET CYLINDER HEAD P/N: 55111 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$47.00	47.00
53	GASKET CYLINDER HEAD COVER (RUBBER TYPE) P/N: 55115 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	13.00
54	GASKET EXHAUST PIPE P/N: 55060 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6.00	6.00
55	GASKET MAGNET COVER P/N: 55073 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$24.00	24.00
56	GASKET PLUG OIL P/N: 31198 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	5.00
57	GASKET TENSIONER P/N: 41130 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00	7.00

*37746 *

bizSAFE₃CERT NO.: 2002-1-0383
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
58	GRIP LH-RR P/N: 55074 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$93.00	93.00 <i>700</i>
59	L FRONT BRAKE DISK BK-001C P/N: 57437 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$173.00	173.00 <i>cm</i>
60	L. PILLION STEP ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$129.00	129.00 <i>cm</i>
61	L.SIDE COVER ASSY WH-300P P/N: 61511 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$135.00	135.00 <i>cm</i>
62	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	<i>h</i> Supply/Install	40.00	\$63.00	2,520.00 <i>810</i>
63	L-CRANK CASE COMP P/N: 55064 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$546.00	546.00 <i>1.7</i>
64	LEVER LH P/N: 55102 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$83.00	83.00 <i>cm</i>
65	L-FR COVER GARNISH BK P/N: 55050 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	17.00 <i>cm</i>
66	LH.FR.CUSHION COMP BK-001C P/N: 57432 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$441.00	441.00 <i>cm</i>
67	LIGHT BOX REAR (GIVI) E160 P/N: 54027 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$147.00	147.00 <i>3.00</i>
68	LIGHT L-TAIL ASSY P/N: 55105 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$273.00	273.00 <i>cm</i>
69	LIGHT R-TAIL ASSY P/N: 55082 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$266.00	266.00 <i>3.00</i>
70	LOWER L HANDLE COVER ASSY P/N: 61801 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$9.00	9.00 <i>cm</i>
71	LOWER R HANDLE COVER ASSY BK-001U - (REPORTED BY MECHANIC)	REPLACE	1.00	\$9.00	9.00 <i>2.0</i>
72	MAIN BRG OP P/N: 55067 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	13.00 <i>AA</i>

*37746 *

5409

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
73	MAIN BRG OP P/N: 55067 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	13.00 X
74	MAINSTAND ASSY P/N: 55104 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$145.00	145.00
75	METER PANEL BK-001U P/N: 55090 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	31.00
76	METER VISOR BK-001U P/N: 64950 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	17.00
77	MIRROR LH P/N: 57022 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$140.00	140.00
78	MIRROR RH P/N: 57405 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$140.00	140.00
79	MISCELLANEOUS FEE (CRANKCASE INSPECTION) P/N: 39670		1.00	\$75.00	75.00 X
80	MISCELLANEOUS FEES (VITAS) P/N: 33771		1.00	\$84.00	84.00 X
81	MUDGUARD REAR ASSY3 P/N: 64191 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$51.00	51.00
82	NEEDLE BRG. NK18/20R - (REPORTED BY MECHANIC)	REPLACE	1.00	\$77.00	77.00 X
83	OIL BRAKE (KUTTEN KEULER) DOT 4 P/N: 39338 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00 X
84	OIL ENGINE (YAMAHA) 20W-40 (4ST) S.S P/N: 39050 - (REPORTED BY MECHANIC)	REPLACE	3.00	\$13.00	39.00 X
85	OIL SEAL - (REPORTED BY MECHANIC)	REPLACE	1.00	\$9.00	9.00 X
86	O-RING P/N: 60120 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00 X
87	O-RING P/N: 58206 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$2.00	2.00 X
88	O-RING P/N: 55122 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	5.00 X

*37746 *

5983

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
89	O-RING (COVER WATER PUMP) P/N: 56120 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	5.00 <i>11</i> <i>X</i>
90	O-RING COVER CRANKCASE P/N: 33950 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	10.00 <i>11</i> <i>X</i>
91	O-RING FILTER OIL P/N: 55083 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00	7.00 <i>11</i> <i>X</i>
92	O-RING HEAD R SIDE COVER P/N: 60119 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00	7.00 <i>11</i> <i>X</i>
93	O-RING PLUG OIL (FILL UP) P/N: 33879 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00	7.00 <i>11</i> <i>X</i>
94	PANEL LH-FLOOR ASSY P/N: 55055 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$41.00	41.00 <i>cm</i>
95	PANEL RH- FLOOR P/N: 55065 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$41.00	41.00 <i>cm</i>
96	PIN PISTON P/N: 60106 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	14.00 <i>11</i> <i>X</i>
97	PLAIN WASHER 10.2MM P/N: 60229 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$2.00	4.00 <i>rec</i>
98	PLASTIC NUT 6MM - (REPORTED BY MECHANIC)	REPLACE	4.00	\$3.00	12.00 <i>rec</i>
99	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 - (REPORTED BY MECHANIC)	REPLACE <i>2</i>	1.00	\$27.00	27.00 <i>self</i> <i>15 s/n</i>
100	PLUG OIL P/N: 31197 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00	7.00 <i>11</i> <i>X</i>
101	R FRONT BRAKE DISK BK-001C P/N: 57434 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$173.00	173.00 <i>set</i>
102	R. SIDE COVER ASSY WH-300P P/N: 64953 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$110.00	110.00 <i>cm</i>
103	RAD. BALL BRG. CSB305C - (REPORTED BY MECHANIC)	REPLACE	1.00	\$49.00	49.00 <i>Dayed</i>
104	RADIATOR COVERBK-001U - (REPORTED BY MECHANIC)	REPLACE	2.00	\$31.00	62.00 <i>Dayed</i>

*37746 *

6475

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
105	RH FLOOR MAT A BK-001U P/N: 64949 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
106	RH.FR.CALIPER ASSY GD-7403S - (REPORTED BY MECHANIC)	REPLACE	1.00	\$349.00	349.00
107	RIM SPORT FRONT P/N: 55465 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$556.00	556.00
108	RING PISTON SET P/N: 55454 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$49.00	49.00
109	RR BRAKE DISK P/N: 55091 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$229.00	229.00
110	RR. CALIPER ASSY(GD-7403S) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$357.00	357.00
111	RR. COVER ASSY WH-300P - (REPORTED BY MECHANIC)	REPLACE	1.00	\$83.00	83.00
112	RR-CAST WHEEL COMP P/N: 55056 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$534.00	534.00
113	RUBBER MOUNT P/N: 64647 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$3.00	12.00
114	RUBBER SHOCK ABSORBER REAR P/N: 55538 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00	7.00
115	RUBBER STOPPER BUSH P/N: 55068 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$11.00	22.00
116	SEAL COIN BOX B P/N: 61135 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	10.00
117	SEAL COIN BOX C P/N: 61136 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	10.00
118	SEAL OIL P/N: 55075 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$9.00	9.00
119	SEAL OIL (45X65X10) P/N: 55071 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00	7.00
120	SEAL VALVE P/N: 41678 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$6.00	24.00

*37746 *

8274

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
121	SENSOR OIL PRESSURE P/N: 56145 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00 X
122	SIDE STAND COMP P/N: 57435 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$41.00	41.00 X
123	SIDE STAND SW COMP - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	31.00 X
124	SOCKET BOLT 10*65 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$5.00	20.00 ✓
125	STEEL BALL UP ASSY P/N: 52815 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00 ✓
126	STEERING CONE UPPER P/N: 54480 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00	19.00 ✓
127	STICKER (ORANGEFORCE) BOX REAR NEW P/N: 54254 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00 S.N
128	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00	19.00 X
129	STICKER(ORANGEFORCE) COVER SIDE LH/RH NEW P/N: 61957 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$70.00	70.00 S.N
130	STICKER(ORANGEFORCE) WINDSHIELD NEW P/N: 54253 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00 S.N
131	STRG DUST SEAL P/N: 57894 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00	19.00
132	STRG HEAD TOP THREAD COMP P/N: 68503 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	13.00 ✓
133	STRG.STEM COMP P/N: 57436 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$170.00	170.00 ✓
134	SWING ARM ASSY P/N: 55061 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$325.00	325.00 ✓
135	SWITCH HANDLE RH ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$112.00	112.00 ✓

*37746

*

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
136	TAPPING SCREW 5*12 P/N: 57010 - (REPORTED BY MECHANIC)	REPLACE	6.00	\$2.00	12.00
137	TENSIONER LIFTER P/N: 64400 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$32.00	32.00
138	TRANSPORT CHARGES (SCOOTER) LARGE P/N: 45834 - DELIVER BIKE TO INSPECTION CENTER FOR VITAS INSPECTION AND RETURN BACK TO BHH		1.00	\$84.00	84.00
139	TYRE 160/60-14 (METZELER) FEEL FREE TL P/N: 46770 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$248.00	248.00
140	UNDER COVER BK-001U - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00
141	UPPER HANDLE COVER ASSY WH-300P - (REPORTED BY MECHANIC)	REPLACE	1.00	\$82.00	82.00
142	VALVE RIM P/N: 55062 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	10.00
143	VALVE RIM P/N: 55062 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	10.00
144	WASHER OIL BOLT P/N: 57423 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$2.00	4.00
145	WHOLE BIKE SPRAY PAINT	Spray	1.00	\$910.00	910.00
146	WINDSCREEN SET P/N: 56667 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$229.00	229.00

SUB TOTAL

\$18,479.00

GST @ 7 %

\$1,293.53

GRAND TOTAL (SGD)

\$19,772.53

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

*37746 *

Acknowledge & Accepted By

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

bizSAFE₃CERT NO: 2002-1-0363
ISO 9001:2015



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWER
SINGAPORE 189702

NO. : **38614**

Supplementary 1 To QTN: 37746

DATE : 23/06/2021
CLAIM NO. : 11685
POLICY NO. : 5113921882-01
FROM : RAYMOND

VEHICLE NO. : FBL7432D
MAKE/MODEL : SYM / MAXSYM 400I CVT

S/N	Description	Action	Qty	Unit Price	Amount
1	OIL GEAR (UNITED) GL-5 SAE 90 P/N: 38679	Replace	0.50	\$8.00	4.00
2	PROTECTOR EXHAUST P/N: 55471	Replace	1.00	\$117.00	117.00
3	PROTECTOR MUFFLER REAR P/N: 60513	Replace	1.00	\$62.00	62.00

SUB TOTAL	\$183.00
GST @ 7 %	\$12.81
GRAND TOTAL (SGD)	\$195.81

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*38614 *

bizSAFE₃

