



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/III20010028/Qvf3e2-1	
			Date: 17/03/2021	
			Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9623B	Veh. Inspected	FBP 2708X	
Policy No.	MCOM0015	Coverage (\$)	0.00	
Claim No.	MCT20080219/01/02	Excess (\$)	0.00	
Assign From	CARINE KEK PHEI SER	Assign Date	16/02/2021	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA SNIPER T150	c.c	150	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	MH3UG0740K0149650	Colour	GREEN	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	70/90-17	MAXXIS	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	70/90-17	MAXXIS	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/08/2020	Inspection Date	18/09/2020	
Survey held at	61 Woodlands Industrial Park E9			
Repairer	AM MOTORWERKZ PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	