

Veron Chen (LKKAUTO)

From: Simon Ho (LKKAUTO)
Sent: Friday, 12 March 2021 10:51 AM
To: Veron Chen (LKKAUTO)
Subject: RE: FBP 2708X

Dear Veron,

Audit check done for FBP2708X without problem.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Veron Chen (LKKAUTO)
Sent: Friday, 12 March, 2021 7:28 AM
To: Simon Ho (LKKAUTO)
Subject: FW: FBP 2708X

Dear Simon

File for audit check.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sun Pin (LKK Auto) <sunpin@lkkauto.com>
Sent: Thursday, 11 March 2021 1:13 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: FBP 2708X

Hi Veron,

Final amount \$2,550. Repair day 3 days. (L/S, before gst).

Please refer attachment.

Thank you.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)