



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
WONG MUI LAN BLK 154 SIMEI STREET 1 #07-69 SINGAPORE 520154 Contact No Mobile: 98800108	Cust No/Name /WONG MUI LAN Reg No/Reg Date SMG9591K*KC17/ 07/01/201 Date In/Mileage / 0 Chassis No KNAF1416MK5021372 Engine No G4FGJH711501 Make/Model KIA/CERATO 1.6 A L S116 Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	15/02/2021/ 10:50	BLC	442 / CocoLu	28911

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER,				400.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER				350.00
M SUNDRY APPLY RESEAL FRT NUMBER PLATE FROM LTA				80.00
M SUNDRY FRT NUMBER PLATE				50.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY Sundry				20.00
M COVER-FR BUMPER ✓ <i>OR</i>	1.00	633.00	00.00	633.00
M GRILLE-FRONT BUMPER ✓ <i>OR</i>	1.00	262.00	00.00	262.00
M GRILLE ASSY-RADIATOR ✓ <i>?</i>	1.00	223.00	00.00	223.00
M MOULDING-FRONT BUMPER, RH ✓ <i>CUT (long light)</i>	1.00	36.00	00.00	36.00
M LAMP ASSY-SIDE REPEATER, RH ✓ <i>CUT (long light)</i>	1.00	143.00	00.00	143.00
M AIR DUCT-FR BUMPER, RH ✓ <i>?</i>	1.00	14.00	00.00	14.00
M ABSORBER-FRONT BUMPER ENERGY ✓ <i>?</i>	1.00	84.00	00.00	84.00
M STIFFNER-FR BPR LWR ✓ <i>OR</i>	1.00	114.00	00.00	114.00
M BRACKET-FR BUMPER UPR SIDE MTG ✓ <i>?</i>	1.00	22.00	00.00	22.00
M LAMP ASSY-HEAD, RH ✓ <i>CUT</i>	1.00	1040.00	00.00	1040.00
M BEAM COMPLETE-FR BUMPER ✓ <i>?</i>	1.00	497.00	00.00	497.00
M CARRIER ASSY-FRONT END MODULE ✓ <i>OR</i>	1.00	675.00	00.00	675.00
M LAMP ASSY-DAY RUNNING LIGHT, RH ✓ <i>CUT (round light)</i>	1.00	203.00	00.00	203.00

Estimate

Steve (LKK) 15/2/21, 1:00pm
 DO - N/A AIL
 EXPR - ?

LKK Auto Consultants hence notify the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and confirmed by the customer.	Confirm & accepted by 3 days , PIP, RY BEL SRY 7% GST on	Nett 4,996.00 4996.00 Total Payable 5,345.72
---	--	--

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.