



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
WONG YEAN YEAN (HUANG YANYAN) BLK 486 PASIR RIS DRIVE 4 #10-495 SINGAPORE 510486 Contact No Mobile: 91886508	Cust No/Name /WONG YEAN YEAN (HUANG YANYAN) Reg No/Reg Date SMF529G*ECB / 26/10/201 Date In/Mileage / 0 Chassis No KNAF3416MK5019146 Engine No G4FGJH710287 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	01/02/2021/ 18:18	QUE	261 / Edwin Caina	28407			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW LHF FENDER, LHF DOOR & LH WINGMIRROR REPAIR LHF DOOR PILLAR, FRT BUMPER & LHR DOOR					400 X 2			800 2000.00
E PNT98000 RESPRAY LHF FENDER, LHF DOOR, LHR DOOR, LHF DOOR PILLAR, FRT BUMPER & LH WINGMIRROR					350 X 3			1050 1925.00
M SUNDRY SUPPLY LHF SPORT RIM-S8004								380.00
M SUNDRY RENEW LHF SPORT RIM / TRANSFER TYRE & WHEEL BALANCE								30.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment								120.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS								80.00
M SUNDRY SUPPLY BODY PNL SEALANT								40 60.00
M SUNDRY Sundries								20.00
M PANEL-FENDER,LH					1.00	430.00	00.00	430.00
M GUARD ASSY-FRONT WHEEL,LH					1.00	95.00	00.00	95.00
M MIRROR ASSY-OUTSIDE RR VIEW,LH					1.00	559.00	00.00	559.00
M PANEL ASSY-FRONT DOOR,LH					1.00	1277.00	00.00	1277.00
M HINGE ASSY-FRT DOOR UPP,LH					1.00	30.00	00.00	30.00
M HINGE ASSY-FRT DOOR LWR LH					1.00	27.00	00.00	27.00
M BLACK TAPE-FR DR RR,LH					1.00	13.00	00.00	13.00
M MOULDING ASSY-FRT DR FRAME,LH					1.00	37.00	00.00	37.00
M W/STRIP ASSY-FR DR BELT O/S LH					1.00	64.00	00.00	64.00
M PANEL ASSY-FRONT DR MODULE,LH					1.00	241.00	00.00	241.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
WONG YEAN YEAN (HUANG YANYAN) BLK 486 PASIR RIS DRIVE 4 #10-495 SINGAPORE 510486 Contact No Mobile: 91886508	Cust No/Name /WONG YEAN YEAN (HUANG YANYAN) Reg No/Reg Date SMF529G*ECB / 26/10/201 Date In/Mileage / 0 Chassis No KNAF3416MK5019146 Engine No G4FGJH710287 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	01/02/2021/ 18:18	QUE	261 / Edwin Caina	28407

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M LATCH ASSY-FRONT DOOR,LH ? X NN	1.00	400.00	00.00	400.00

Estimate

SURVEYOR NAME: Steve (LKK) 15/2/21, 2.00pm

SURVEYOR SIGNATURE: [Signature]

DATE: P/P

REMARKS: My B/L Sp
6 & days

LKK Auto Consultants hence notify

that the cost of the following:

Confirm & accepted by

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

7% GST on	Nett	7,938.00
	7938.00	555.66
Total Payable		8,493.66

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.