

ASS. REC. BY:

REF:

CT2/ 21002181/KV

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

4-5 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PK81030P

Yr Regn:

01.16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Aqua

c.c

1496

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

41579

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

N14P10

6436157

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

165/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

7

mm

R/Bal.

6

mm

L/Bal.

7

mm

L/Bal.

6

mm

D.O.A.

11/2/21

D.O.I.

17/2/2021

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - R.S. - SI

Fees

Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐


Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
LIM NAM HAI

Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP CHINA
Policy No:	DMPCSNW00149232001	Date of Loss:	11/02/2021
Vehicle Reg. No.:	SKZ1030P	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	ANTON WONG HUI TERN	Driver (Insured):	FRANCIS
Make/Model:	TOYOTA AQUA HYBRID, 1.5 E S CVT (A)	Vehicle Reg. Date:	08/01/2016
Vehicle Colour:	SILVER	Chassis No:	NHP106436157
Engine No:	1NZ7633347		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		

*Not withstanding
1/12/21
Resurvey After Paint
4-5 days*

Description of Accident/Loss: REFER REPORT ATTACH
Remarks: VEH TOWED IN ON 12/2/2021
Present Location: CHENG HOE MOTOR PTE LTD (ANG MO KIO)

COST OF CLAIMS

	Amount
Parts	1,881.50
Miscellaneous Items	315.00
Labour	1,720.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,916.50
+ GST 7.00% (S\$)	274.16
Nett Amount (S\$)	4,190.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Comp.

Acknowledged by Repairer
Signature:
Date:

This claim is handled by: JUNE PHUA LIAN HUA

Generated using Merlimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Feb 2021)
 Parts: 144 TOYOTA AQUA HYBRID 1.5 E S CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Cheng Hoe Motor Pte Ltd/SKZ1030P/17/02/2021 10:18
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the
 END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc rear bumper	Ry 0.00	0.00	*250.00 F ✓
2	1		*2 pcs rear bumper side retainers @ \$30/pc	CM 0.00	0.00	*60.00 F ✓
3	1		*1 pc rear bumper lower centre cover	Di 0.00	0.00	*60.00 F ✓
4	1		*5 pcs rear bumper clips @ \$1.50/pc	Na 0.00	0.00	*7.50 F ✓
5	1		*1 pc rear bumper RH inner shield	0.00	0.00	*60.00 F ?
6	1		*1 pc tailgate	Ry 0.00	0.00	*410.00 F ✓
7	1		*1 pc tailgate inner rubber	0.00	0.00	*115.00 F
8	1		*1 pc tailgate logo	Na ✓ 0.00	0.00	*32.00 F
9	1		*1 pc tailgate emblem AQUA	Na ✓ 0.00	0.00	*28.00 F
10	1		*1 pc tailgate emblem Hybrid Synergy Drive	Na ✓ 0.00	0.00	*30.00 F
11	1		*2 pcs taillamps @ \$210/pc	CL/CA ✓ 0.00	0.00	*420.00 F
12	1		*1 pc RH taillamp lower retainer	Di ✓ 0.00	0.00	*26.00 F
13	1		*1 pc rear end panel	? 0.00	0.00	*320.00 F
14	1		*1 pc rear end panel inner top garnish	Na ✓ 0.00	0.00	*60.00 F
15	1		*2 pcs rear end panel inner top garnish clips @ \$1.50/pc	Na 0.00	0.00	*3.00 F
Total Parts (\$\$)						1,881.50

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SKZ1030P/17/02/2021 10:18. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	1 pc rear no. plate	35.00 ✓
2	1	1 set reverse sensor	200.00 ✓
3	1	1 unit rear end panel sealant	40.00 ?
4	1	1 unit rear windscreen glass sealant	40.00 ✓
Sub Total (\$\$)			315.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Remove & refix rear windscreen glass	New	120.00 ✓
2	Remove & refix rear bumper & attachments,tailgate & attachments,tailamp;to cut,weld & renew rear end panel;knocking & repair rear RH fender & realign the same	New	700.00 ?

Cheng Hoe Motor Pte Ltd/SKZ1030P/17/02/2021 10:18. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Particulars

Lab.Type

Amount

Putty & respray rear bumper & parking sensors,tailgate,rear end panel,rear RH fender & all affected areas

New

600 750.00

Remove & refix reverse camera,reset & realign the same

New

50 60.00

Rustproofing

New

? 90.00

Gross Labour Cost (\$)

1,720.00

Cheng Hoe Motor Pte Ltd/SKZ1030P/17/02/2021 10:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Feb 2021)
Parts:	144	TOYOTA AQUA HYBRID 1.5 E S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Cheng Hoe Motor Pte Ltd/SKZ1030P/17/02/2021 10:27	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

There are no new parts selected.

Cheng Hoe Motor Pte Ltd/SKZ1030P/17/02/2021 10:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Towing (By King Dolly on 1st day of CNY) - bill attach	Bill Attch New	150.00
Gross Labour Cost (\$\$)			150.00

Cheng Hoe Motor Pte Ltd/SKZ1030P/17/02/2021 10:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 12/02/2021 18:31 (SGT)
Date of Accident 11/02/2021 16:31 (SGT)
Exact Location of Accident Singapore
Additional Location Information ALONG ANG MO KIO AVE 6 AND ANG MO KIO AVE 5
JUNCTION
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKZ1030P

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner XU GUIQIN, GERMAINE
NRIC No S7925870I
Email Address GERMAINEXU@GMAIL.COM
Mobile Phone No (Phone) +65-91123889
Alternative Phone No +65-91123889

VEHICLE PARTICULARS

Manufacturer Toyota
Model Aqua
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car


INSURANCE COMPANY

Name of Insurance Company NTUC
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 5076967304-05
Cover Note Number -

DRIVER

Name of Driver ANTON WONG HUI TERN
NRIC No S7970509H
Date Of Birth 23/01/1979

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stationary waiting for the traffic light to change. Subsequently Vehicle B collided against my vehicle rear

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 12/02/2021 / 12:34pm

Reporting Centre Personnel's Signature
Name: [Signature]
NRIC/FIN No.: 5042345