

PAIR DETAILS

Reference

Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Feb 2021)
 s: 144 TOYOTA AQUA HYBRID 1.5 E S CVT (A) (Catalogue:Merimen Singapore 1.0)
 our: Repairer's (Price-denominated Standard List)
 t Code: Cheng Hoe Motor Pte Ltd/SKZ1030P/17/02/2021 10:18
 dity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the
 END OF ESTIMATES marker on the last estimate page
 her Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

Qty	Part No.	Particulars	%Disc	%Depr	Amount
1		*1 pc rear bumper	R 0.00	0.00	*250.00 F ✓
1		*2 pcs rear bumper side retainers @ \$30/pc	CM 0.00	0.00	*60.00 F ✓
1		*1 pc rear bumper lower centre cover	Di 0.00	0.00	*60.00 F ✓
1		*5 pcs rear bumper clips @ \$1.50/pc	Na 0.00	0.00	*7.50 F ✓
1		*1 pc rear bumper RH inner shield	CM 0.00	0.00	*60.00 F ✓
1		*1 pc tailgate	R 0.00	0.00	*410.00 F ✓
1		*1 pc tailgate inner rubber	in 0.00	0.00	*115.00 F ✓
1		*1 pc tailgate logo	Na 0.00	0.00	*32.00 F ✓
1		*1 pc tailgate emblem AQUA	Na 0.00	0.00	*28.00 F ✓
1		*1 pc tailgate emblem Hybrid Synergy Drive	Na 0.00	0.00	*30.00 F ✓
1		*2 pcs taillamps @ \$210/pc	CL 0.00	0.00	*420.00 F ✓
1		*1 pc RH taillamp lower retainer	Di 0.00	0.00	*26.00 F ✓
1		*1 pc rear end panel	R 0.00	0.00	*320.00 F ✓
1		*1 pc rear end panel inner top garnish	Na 0.00	0.00	*60.00 F ✓
1		*2 pcs rear end panel inner top garnish clips @ \$1.50/pc	Na 0.00	0.00	*3.00 F ✓
Total Parts (\$\$)					1,881.50

franchise part.

Cheng Hoe Motor Pte Ltd/SKZ1030P/17/02/2021 10:18. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Qty	Particulars	Amount
<u>Miscellaneous Items</u>		
1	1 pc rear no. plate	35.00 ✓
1	1 set reverse sensor	200.00 ✓
1	1 unit rear end panel sealant	40.00 ✓
1	1 unit rear windscreen glass sealant	40.00 ✓
Sub Total (\$\$)		315.00

Estimates on Labour

Particulars	Lab.Type	Amount
<u>Labour Items</u>		
Remove & refix rear windscreen glass	New	120.00 ✓
Remove & refix rear bumper & attachments,tailgate & attachments,tailamp;to cut,weld & renew rear end panel;knocking & repair rear RH fender & realign the same	New	570.00 ✓

Cheng Hoe Motor Pte Ltd/SKZ1030P/17/02/2021 10:18. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

e:

Veh No:

8N 870301

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Particulars

Lab.Type

Amount

Putty & respray rear bumper & parking sensors,tailgate,rear end panel,rear RH fender & all affected areas New 600 750.00

Remove & refix reverse camera,reset & realign the same New 50 60.00

Rustproofing New 30 90.00

Gross Labour Cost (\$)

1,720.00

Cheng Hoe Motor Pte Ltd/SKZ1030P/17/02/2021 10:18. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

COST OF CLAIM

Part

Material

Labour

Per cent Labour

Total

REPAIR DETAILS

Reference

Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Feb 2021)
Is: 144 TOYOTA AQUA HYBRID 1.5 E S CVT (A) (Catalogue:Merimen Singapore 1.0)
Our: Repairer's (Price-denominated Standard List)
It Code: Cheng Hoe Motor Pte Ltd/SKZ1030P/17/02/2021 10:27
dity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
ther Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

There are no new parts selected.

Cheng Hoe Motor Pte Ltd/SKZ1030P/17/02/2021 10:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

Particulars	Lab.Type	Amount
Labour Items		
Towing (By King Dolly on 1st day of CNY) - bill attach	Bill Attach New	150.00
Gross Labour Cost (S\$)		150.00

Cheng Hoe Motor Pte Ltd/SKZ1030P/17/02/2021 10:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >