

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

15/02/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Budget Direct

Xiao Chan

Accident date: 11/02/2021

Estimated repair cost for vehicle no: SLZ736G HYUNDAI I30 PDE 1.4 18'

CHASSIS: TMAH3513VJJ065281

S/n	Qty	Items	U/price	Amount	
				\$1,724.00	1455
1	1	Front R/H Door <i>Dented</i>		\$70.00	✓
2	2	Front R/H Door Frame Sticker <i>new</i>	\$35.00	\$80.00	X
3	1	Front R/H Door Glass Outer Moulding <i>Not new</i>		\$235.80	✓
4	1	Front R/H Door Outer Handle Assy <i>lt</i>		\$162.00	✓
5	1	Front R/H Door Lock <i>Damaged</i>		\$185.00	X
6	1	Front R/H Door Weatherstrip <i>Not new</i>		\$538.90	✓
7	1	Front R/H Door Inner Trim Board <i>cracked</i>		\$489.90	✓
8	1	Front R/H Door Window Motor & Regulator Assy <i>Damaged</i>		\$135.00	✓
9	1	Front R/H Door Handle <i>lt</i>		\$1,820.10	1518
10	1	Rear R/H Door <i>Dented</i>		\$70.00	✓
11	2	Rear R/H Door Frame Sticker <i>new</i>	\$35.00	\$155.00	X
12	1	Rear R/H Door Glass Outer Moulding <i>Not new</i>		\$145.00	✓
13	1	Rear R/H Door Outer Handle Assy <i>lt</i>		\$235.00	X
14	2	Rear R/H Door Lock <i>Not new</i>		\$128.00	X
15	2	Rear R/H Door Weatherstrip <i>Not new</i>		\$627.80	✓
16	2	Rear R/H Door Inner Trim Board <i>cracked</i>		\$489.90	✓
17	4	Rear R/H Door Window Motor & Regulator Assy <i>Damaged</i>		\$145.00	✓
18	1	Rear R/H Door Handle <i>lt</i>		\$2,289.20	1830
19	1	Rear R/H Fender <i>Dented</i>		\$355.00	X
20	1	Rear R/H Fender Cowling <i>2 new</i>	\$6.50	\$52.00	X
21	8	Rear R/H Fender Cowling Clip <i>2 new</i>		\$450.00	X
22	1	Rear R/H Tyre <i>Not new</i>		\$1,920.00	Sub (sn)
23	1	Rear R/H Rim <i>lt</i>		\$585.00	✓
24	1	Rear R/H Lower Arm <i>Best</i>		\$837.00	✓
25	1	Rear R/H Knuckle Arm <i>Damaged</i>		\$315.25	✓
26	1	Rear R/H Knuckle Arm Bearing <i>Damaged</i>		\$497.00	✓
27	1	Rear R/H Shock Absorber <i>Damaged</i>		\$328.50	✓
28	1	Rear R/H Trailing Arm <i>Best</i>			

29	1	Rear Bumper	Repr		\$1,125.50	X
30	10	Rear Bumper Clip	MM	\$6.50	\$65.00	X
31	2	Rear R/H Bumper Side Retainer	MM	\$32.00	\$64.00	X
32	1	R/H Rocker Panel	Repr		\$1,180.50	X

10475.05

Subtotal :- \$17,500.35

8380.04

S.N: 800

Labour charges

To remove & refit front R/H door, lock, glass, weatherstrip, trim board, frame sticker, window motor & regulator assy

~~\$280.00~~ 80

To remove & refit rear R/H door, lock, glass, weatherstrip, trim board, frame sticker, window motor & regulator assy

~~\$280.00~~ 80

To remove & refit reverse sensor

~~\$100.00~~ X 50.

To remove & refit rear undercarriage

~~\$450.00~~ 250

To check wheel alignment

~~\$150.00~~ 80

To check wiring

~~\$100.00~~ 30

Tuff kote

~~\$150.00~~ 100.

Panel beating

3070 ~~\$2,500.00~~ 1200.

Spray painting

~~\$2,500.00~~ 1200.

Subtotal :- \$5,150.00

Total:- \$22,650.35

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 12250.04

h/s: 9.8K

08 Days

9.8K