

RICO60 AUTO SERVICES

Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -%25	
SN	
Labour	
Lump Sum	
ERV	17K

TO: CHINA TAIPING

Vehicle No : SJR 9162 T

Make & Model : TOYOTA ALTIS

DATE:1/2/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE	
1	BONNET / BT	1	\$ 1,036.20	\$ 1,036.20	739.1
2	BONNET INNER LOCK X / BT.	1	\$ 372.40	\$ 372.40	82.6
3	BONNET STOPPER X BT NN	2	\$ 30.00	\$ 60.00	
4	BONNET RUBBER X BT NN	1	\$ 106.10	\$ 106.10	31
5	BONNET INSULATOR X	1	\$ 217.30	\$ 217.30	
6	BONNET HINGE X	2	\$ 247.90	\$ 495.80	
7	HEAD LAMP LT RT - CAA.	2	\$ 738.50	\$ 1,477.00	1060.2
8	HEAD LAMP BOTTOM RETAINER X NN	4	\$ 50.00	\$ 200.00	
9	FRONT BUMPER / CA Re	1	\$ 681.70	\$ 681.70	459
10	FRONT BUMPER TOP RUBBER X NN	1	\$ 120.00	\$ 120.00	
11	FRONT BUMPER SIDE RETAINER LT RT NN, RH-RR	2	\$ 94.30	\$ 188.60	35
12	FRONT BUMPER BADGE / CC	1	\$ 96.00	\$ 96.00	38
13	FRONT BUMPER BADGE BASE X NN	1	\$ 124.00	\$ 124.00	
14	FRONT BUMPER REINFORCEMENT X BT	1	\$ 480.10	\$ 480.10	379
15	FRONT BUMPER REINFORCEMENT BRACKET X NN	2	\$ 82.00	\$ 164.00	
16	FRONT BUMPER LOWER GRILLE X / RR	1	\$ 235.00	\$ 235.00	102.3
17	FORNT BUMPER UNDER COVER X / RR	1	\$ 271.00	\$ 271.00	133
18	FRONT FOG LAMP X LT RT NN, RH / RR	2	\$ 350.00	\$ 700.00	266.98
19	FRONT FOG LAMP COVER X LT RT NN, RH / RR	2	\$ 97.20	\$ 194.40	62.5
20	FRONT FOG COVER CHROME MOULDING X NN	2	\$ 45.60	\$ 91.20	
21	FRONT GRILLE X / RR	1	\$ 438.00	\$ 438.00	266.2
22	FRONT GRILLE CHROME MOULDING(SHORT) X	2	\$ 96.00	\$ 192.00	
23	FRONT GRILLE CHROME MOULDING(LONG) X	1	\$ 136.00	\$ 136.00	
24	SUPPORT PANEL X / BT.	1	\$ 1,425.00	\$ 1,425.00	728.1
25	RADIATOR X	1	\$ 1,109.50	\$ 1,109.50	
26	RADIATOR TOP GARNISH X NN	1	\$ 317.00	\$ 317.00	

1	RADIATOR TOP BRACKET	X NW	2	\$	35.00	\$	70.00	
27	RADIATOR FAN COWLING	X PR	1	\$	297.50	\$	297.50	230
28	RADIATOR FAN MOTOR	X	1	\$	357.90	\$	357.90	
29	RADIATOR FAN BLADE	X	1	\$	87.90	\$	87.90	
30	AIR CON CONDENSER	X Cut	1	\$	890.10	\$	890.10	✓
34	AIR CON PIPE	X	1	\$	432.00	\$	432.00	
35	WASHER TANK	X } NW	1	\$	125.30	\$	125.30	
36	WASHER TANK MOTOR	X	1	\$	97.60	\$	97.60	
37	FRONT FENDER RH	X Repair	1	\$	799.80	\$	799.80	
38	FRONT FENDER EMBLEM (VVTI)	X / MC	1	\$	109.00	\$	109.00	65
39	FRONT FENDER INNER SHILED RH	X / RL	1	\$	265.30	\$	265.30	171.2
Subtotal :							\$ 14,460.70	5739.28
Less 25%							\$ 3,615.18	
Parts Total :							\$ 10,845.53	4304.46

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE	
1	BONNET INSULATOR CLIP	X	1	\$ 60.00	\$ 60.00
2	BONNET RUBBER CLIP SET	X	1	\$ 30.00	\$ 30.00
3	FRONT BUMPER CLIP SET	X	1	\$ 50.00	\$ 50.00
4	FORNT BUMPER UNDER COVER CLIP SET	X	1	\$ 40.00	\$ 40.00
5	FRONT FOG LAMP BULK	X	1	\$ 30.00	\$ 30.00
6	FRONT GRILLE CLIP SET	X	1	\$ 40.00	\$ 40.00
7	SUPPORT PANEL SEALANT	X	1	\$ 70.00	\$ 70.00
8	RADIATOR COOLANT	X	1	\$ 60.00	\$ 60.00
9	FRONT FENDER INNER SHILED CLIP SET	X	1	\$ 50.00	\$ 50.00
				\$	430.00

LABOUR			PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	600	400	\$ 1,800.00
TO SPRAY PAINT AFFECTED AREA	800	600	\$ 1,600.00
TO PERFORM LIGHTING & WIRING CHECK		30	\$ 100.00
TO APPLY ANTI-RUST & TUFF KOTE	60	NA	\$ 200.00
REMOVE AND INSTALL RADIATOR AND REFILL COOLANT AND HIGH PRESSURE TEST	100	NA	\$ 180.00
REMOVE AND INSTALL CARPET, SEAT, DASH BOARD AND ININTERIOR	X	NW	\$ 350.00
REMOVE AND INSTALL CONDENSER AND REFILL AIRCON GAS	X	NA	\$ 150.00
			1590

LABOUR TOTAL \$ 4,380.00

Total Parts Cost	\$ 11,275.53
Total Labour Cost	\$ 4,380.00
Total Repair Cost	\$ 15,655.53

5924.46

-20%: 4700

APPROVED DETAILS
NO. OF WORKING DAYS
PART BY PART OR LUMP SUM
DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

4 Days.

Lump sum repair

After repair photos.

Guo Qi Amp

82880282

19/2/2021.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: